

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-23662
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 992279
7. Lease Name or Unit Agreement Name Hobbs State
8. Well Number 5
9. OGRID Number 131652
10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other P & A

2. Name of Operator
HRC, Inc.

3. Address of Operator
P.O. Box 5102 Hobbs, NM 88241

4. Well Location

Unit Letter F : 2280 feet from the North line and 1980 feet from the West line

Section 29 Township 18S Range 38E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐


OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. See attached list of completed plugging operations.



Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Ray M Schubert TITLE President DATE 3/18/05

Type or print name Ray M Schubert E-mail address: _____

For State Use Only

APPROVED BY: Hayden W. Wink TITLE _____

Conditions of Approval (if any): _____

OC FIELD REPRESENTATIVE II/STAFF MANAGER Telephone No. _____
MAR 23 2005

**H.R.C., Inc.
P O Box 5102
Hobbs, NM 88241
(505)393-6662**

12/30/04

Rig up on location approximately 1:00 P.M..
Disassemble old dry hole marker.
Install B.O.P..
Hook up reverse unit and swivel.
Shut down for night.

12/31/04

Drill out surface plug; hole loaded with brine gel.
Run tubing in hole and tag old plug at 3500'.
Pull up to 2600' to spot cement plug.
Unable to get cement truck; shut down for weekend.
Set up cement job for 8:00 A.M. Monday 1/3/05.

1/3/05 7:00 A.M.

Rig up Schlumberger and Signal Wireline.
Fill reverse pit with 25# /BBL brine gel and circulate hole until loaded to surface.
Pump 200' cement plug at 2600'.
Pull out work string.
Run in hole with wireline and tag top of cement plug at 2405'.
Perforate casing at 1600'.
Run in hole with tubing and set cement plug at 1633' for plug inside and outside of casing (estimated T.O.C. at 1325').
Pull tubing out of hole and run wireline to tag top of cement plug at 1298'.
Perforate casing at 415'.
Run tubing in hole to approximately 1250' and circulate brine gel.
Pull tubing to 415' and pump cement and circulate cement to surface on backside of 7" casing.
Pull tubing out of hole.
Wash out tubing to reverse pit.
Release Signal Wireline and Schlumberger and shut down for night to wait on cement.

1/4/05

Run in hole and tag top of cement at 45'.
Break out B.O.P. and install dry hole marker.
Install bull plugs on casing openings and clean location.
Release reverse unit and well service rig.

