•	Submit 3 Copies To Appropriate District Office District I	State of New M Energy, Minerals and Na		Form C-103 May 27, 2004			
, j	1625 N. French Dr., Hobbs, NM 88240			WELL API NO.			
	District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		30-025-11889 5. Indicate Type of Lease STATE FEE			
	District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM	87505	6. State Oil & Gas Lease No.			
	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			<ol> <li>Lease Name or Unit Agreement Name Dabbs</li> </ol>			
		Gas Well 🗌 Other	8. Well Number 2				
	2. Name of Operator Doyle Hartman			9. OGRID Number 6473			
Ī	3. Address of Operator			10. Pool name or Wildcat			
	500 N. Main, Midland, Texas 79701			Jalmat/Langlie Mattix			
Ì	4. Well Location	• · · · · · · · · · · · · · · · · · · ·					
	Unit Letter E:	2310feet from theNo	orth line and	330feet from theWestline			
	Section 34	Township 25S	Range 37	E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3012' RKB							
	Pit or Below-grade Tank Application or Closure						
	Pit typeSteelDepth to Groundwater185'Distance from nearest fresh water well>1000'Distance from pearest surface water>1000						
	Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	nstruction Materia			
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
	NOTICE OF IN	SUB	SEQUENT REPORT OF:				
	PERFORM REMEDIAL WORK	K 🗋 🤇 🗍					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR				LLING OPNS. 🗌 👌 🕅 🦓 🖉 🖉 👘 🗌 👘			
	PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	ГЈОВ			
-	OTHER			ed csg integrity test and injectivity test			
	13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Pulled rods and tbg. Ran 7" RBP and 7" pkr. Set 7" RBP at 2702'. Located csg leak at 206' to 238'. Could not circulate fluid to surface up 10 3/4" x 7" csg annulus. Pressure tested 7" O.D. csg to 500 psi (238'-2702'). Pressure held okay. Pulled 7" RBP. Set 7" pkr at 2300'. Performed injectivity test at 1.5 BPM, at 550 psi.

Raised 7" pkr to 897'. Performed injectivity test at 1.5 BPM, at 500 psi.

We hereby propose to P&A well in accordance with procedures outlined on page 2 of 3 attached hereto, and made a part hereof.

## THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS.

I hereby certify that the information above is true grade tank has been/will be constructed or closed according			
SIGNATURE OF Mach	TITLE_	Engineer	DATE07-12-05
Type or print name Don Mashburn For State Use Only	E-mail address:	dhoo-ll@swbell.net	Telephone No. (432) 684-4011
91	) in R TITLE	TELD HELEN SAM	Overa DATE
Conditions of Approval (if any):			GINEER
APPROVED BY: Augustic Conditions of Approval (if any):	Jank TITLE		DATE GINEER VSTAFF MANAGER JUL JUL 2005 2

Page 2 of 3 NMOCD Form C-103 dated July 12, 2005 Doyle Hartman Dabbs No. 2 E-34-25S-37E API No. 30-025-11889

ź

## **Details of Proposed Plugging Operations**

- 1. Set 7" CICR at 900'.
- Squeeze below retainer with 175 sx of API Class "C" cement containing 3% CaCl<sub>2</sub>, 5 lb/sx Gilsonite, 0.5 lb/sx Flocele followed by 225 sx of HLC containing 2% CaCl<sub>2</sub>. Stage to a final pressure of 500 psi to 1000 psi.
- 3. Dump 10 sx on top of CICR.
- 4. Run 2 3/8" O.D. open-ended tbg to top of cement.
- 5. Cement down 2 3/8" O.D. tbg and back to surface with 50 sx of API Class "C" cement containing 3% CaCl<sub>2</sub>, 5 lb/sx Gilsonite, 0.5 lb/sx Flocele followed by 100 sx of HLC containing 2% CaCl<sub>2</sub>.
- 6. Leave casing full of cmt from 0' to 3250' (will not displace cmt).
- 7. Remove rig anchors. Install dry hole marker. Clean location.
- Note: In 2-52, two-stage tool was installed in 7" O.D. csg string at 1051'. Upper portion of csg was cemented with 200 sx.



л