_ `				
Submit 3 Copies To Appropriate District Office Coffice State of New Mexico Energy, Minerals and Natural Resources			Form C-103 May 27, 2004	
District I 1625 N. French Dr., Hobbs, NM 87240	WELL API		1111 y 27, 2004	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		0-025-34073		
District III1220 South St. Francis Dr.1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505	5. Indicate Type of Lease STATE FEE X			
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		& Gas Lease N		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		ume or Unit Ag	reement Name:	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Nur			
1. Type of Well: Oil Well X Gas Well Other	8. Well Nul	nder 1		
2. Name of Operator Energen Resources Corporation	9. OGRID Number 162928			
		10. Pool name or Wildcat		
<u>3300 North A St., Building 4, Suite 100 Midland, TX 79705</u> 4. Well Location	n A St., Building 4. Suite 100 Midland, TX 79705 Shoe Bar; Strawn, Northeast			
Unit Letter U : 990 feet from the South line and	874 f	eet from the	West line	
Section 6 Township 16-S Range 36-E	NMPM	Count	ty Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3956' GR, 3976' KB				
Pit or Below-grade Tank Application or Closure				
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	SEQUENT		OF: RING CASING 🗌	
PULL OR ALTER CASING IN MULTIPLE CASING TEST AND CEMENT JOB	C		IDONMENT	
OTHER:			Γ.	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 				
See attached AMENDED procedure.		24 25 26 22 3	Ved the the the the the the the the the the	
THE OIL CONSERVATION DIVISION MUST				
BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGONIC CORD TO THE		12		
BEGINNING OF PLUGGING OF THE I hereby certify that the information above is true and complete to the best of mixed belief. I further certify that any pit or below- grade tank has been will be constructed or closed according to NMOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan				
	<u>y Analyst</u>	eu) anernative OC DATE _	D-approved plan [
Type or print name Carolyn Larson	clarson@en	ergen.com	. 432/684-3693	
For State Use Only OC FIELD REPRESENTATIV APPROVED BY Approval, if any:	<u>E II/STAFE A</u>	-		
Conditions of Approval, if any:		MANAGE	2 5 2005	

••

ENERGEN RESOURCES CORPORATION

Snyder A Com #1

990' FSL and 874' FWL Sec 6, T-16-S, R-36-E Lea, Co. NM Shoe Bar Strawn Field **P&A Well**

- 1. MIRU Pulling Unit
- 2. Install BOPE.

م`

- 3. RIH w/packer and 2-7/8" tubing. Set packer at 8600'. Establish pump in rate. Establish reverse circulation. POOH.
- 4. RIH w/cement retainer and set at 8586'.
- 5. Pump 150 sx class H cement through casing leak.
- 6. Sting out of retainer. PUH w/2 stands and reverse tubing clean.
- 7. SWI to let cement set up.
- 8. Tag PBTD.
- 9. Load hole with 9 #/gal plugging mud to 5580. POOH.
- 10. Set cement plug from 5630 to 5530'.
- 11. Circulate hole with 9#/gal mud to 4662'.
- 12. Tag plug at 5530'.
- 13. Perforate casing at 4862' with 4 squeeze holes.
- 14. RIH w/retainer and set at 4662'
- 15. Squeeze cement through perfs at 4862 back up to 4662' Leave a 20' cap of cement on top of retainer.
- 16. Sting out of retainer and circulate 9# mud to 1900
- 17. Perforate casing at 1950' with 4 squeeze holes.
- 18. RIH w/retainer and set at 1850'
- 19. Squeeze cement through perfs at 1950 back up to 1850' Leave a 20' cap of cement on top of retainer.
- 20. Sting out of retainer and circulate 9# mud to 398'
- 21. Perforate casing at 448' with 4 squeeze holes.
- 22. RIH w/retainer and set at 348'

23. Squeeze cement through perfs at 448 back up to 348' Leave a 20' cap of cement on top of retainer.

a the second second

- 24. Sting out of retainer and circulate 9 #/gal mud to surface.
- 25. Perforate casing at 70' with 4 squeeze holes.
- 26. Circulate cement through perfs at 70' to surface..
- 27. Cut off wellhead 3' from surface and well on P&A marker.
- 28. RD pulling unit

~`

•

ENERGEN RESOURCES CORPORATION

Snyder A Com #1

990' FSL and 874' FWL Sec 6, T-16-S, R-36-E Lea, Co. NM Shoe Bar Strawn Field **P&A Well**

Date: July 19, 2005

· ^ ·

AFE No: Cost: \$ WI: 87.51% NRI: 66.22% TD: 11745' PBTD: 11465' (Cement) KB: 3976' GL: 3956' Surface Casing: 13-3/8" 48#/ft, H-40 at 398'. Cemented w/200 Class C sx. Cement circulated. Intermediate Casing: 8-5/8" 32#/ft, J-55 Surf-3914' 32#/ft, Mav-80 3914-4762' Cemented w/1100 sx Lone Class C Cement circulated. Production Casing: 5-1/2" 17#/ft, M-95 Surf to 654' N-80 654-10548' M-95 10548 to 11745' Cemented w/650 Class H TOC at 8830' Tubing: None Rods: None Pump: None Perforations: Strawn: 11452-58 13 holes at 2 SPF Squeezed 11461-63 5 holes at 2 SPF Squeezed 11470-77 15 holes at 2 SPF Squeezed Strawn: 11446-49 12 holes at 4 SPF 11454-64 40 holes at 4 SPF Collapsed Casing: 8786-8825'

Fish: 2-7/8" tubing 8855-11443'. TAC at 11362'

