Submit 3 Copies To Appropriate District	State of New Mexico				Form C	-103
Office District I	Energy, Minerals and Natural Resources			Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
District II	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			30-025-02253		
1301 W. Grand Ave., Artesia, NM 88210 District III				5. Indicate Type		
1000 Rio Brazos Rd., Aztec, NM 87410					🛛 FEE 🗌	
District IV	Santa Fe	, NM 87	/505		Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				857948		
	Y NOTICES AND REPORTS ON WELLS				or Unit Agreement Na	ame:
(DO NOT USE THIS FORM FOR PROPOSA		0				
DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)						
1. Type of Well:				Vacuum Grayburg San Andres Unit		
Oil Well 🛛 Gas Well 🗌 O						
2. Name of Operator				8. Well No.	28	
Chevron						
3. Address of Operator			9. Pool name or Wildcat			
15 Smith Road Midland, Texas 79705			Vacuum			
4. Well Location						
Unit Letter I :_231	10_feet from theSouth	n I	ine and	feet from theEas	st_line	
Section 1	Township 1	8-S	Range 34-E	NMPM	County Lea	
	10. Elevation (Show w				Self Letter A. Provide State	
	3993 DF		, , , , ,			
11. Check Ap	propriate Box to Ind	licate N	ature of Notice,	Report or Other	Data	and the supervision of
NOTICE OF INT	ENTION TO:			SEQUENT RE		
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON	\boxtimes	REMEDIAL WOR		ALTERING CASING	GП
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND	
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN		ABANDONMENT	
	COMPLETION	L]	CEMENT JOB			
OTHER:			OTHER:			

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See attached procedure

,t

THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRICE TO THE BEGINNING OF PLUGGING OPERATIONS.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE P. W. Muchen_TITLE_Operations SupervisorDATE_7/26/2005	
Type or print name P. W. Minchew	Telephone No.
(This space for State use)	JUL 2 8 2005
APPPROVED BY <u>Aau</u> <u>Au</u> <u>Auptione</u> <u>MelD REPRESENTATIVE II/STAFF MA</u> Conditions of approval, if any:	N/DATE

<u>VI-</u>	Procedure
1	<u>Pull RBP:</u> TIH w/ Retrieving tool to top of RBP. Wash sand off the RBP. Fish RBP. TOH and L/D tools.
2	<u>Set Bottom Plug</u> R/U wireline. TIH w/ CIBP. Set @ 4030'. R/D wireline. TIH w/ 2 7/8" open ended tbg. Spud 20 sacks cl "C" cmt (4.65 bbls) on top of CIBP. Estimated plug thickness of 200'. TOH to 2930'.
3	Base of Salt Cement Plug: Set open ended tubing @ 2930'. Spud 30 Sacks of cl "C" cmt (300', ~7 bbls). Pull tubing to 1800' feet. WOC. TIH to tag top of plug. Pull tbg out of hole.
4	Injection test: TIH w/ 5 ½" packer and 2 7/8" working string. Set packer @ ~1800' . Perform injection test. Make sure that you can squezze leaks. If can not get rate go to step 6.
5	Squeeze Casing Leak @ 2340'-2384': R/U wireline. Set CR @ 1800'. R/D wireline. TIH w/ stinger and 2 7/8" tubing. Sting into CR. Pump ~100 Sx cl "C" cmt (23 bbls slurry). Sting out. Pump 40 Sacks cl "C" cmt (9.3 bbls) @ 1800'. Pull to Surface. WOC. TIH w/ 2 7/8" open ended tbg. Tag plug (Estimated top @ 1400'). TOH to 400'.
6	<u>Surface Plug:</u> Set open ended tbg @ 400'. Pump ~40 sacks cl "C" cmt to surface. Pull tubing out.
-	

6 Cut casing and cap off well. Well P&A.

Use

Prepared by Mario A. Ballesteros

.\$

•

CURRENT WELLBORE DIAGRAM



7/27/2005