Submit 1 Copy To Appropriate District State of New Me.	
District I – (575) 393-6161 Energy, Minerals and Natur	Coctober 13, 2009
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-005-27945
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OBBS OCD IL CONSERVATION District III – (505) 334-6178 12:20 South St. Fran	DIVISION 7. Indicate Type of Lease
	cis Dr. $STATE \boxtimes \sim FEE \square$
$\frac{1000 \text{ Rio Brazos Rd., Aztec, NM 87410}}{\frac{\text{District IV}}{1220 \text{ S}} - (505) 476-3460}$ Santa Fe, NM 87	
1220 S. St. Francis Dr., Santa Fe, NOC	
87505	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROCESSIES TO DRILL OR TO DEEPEN OR PLU	JG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FC	R SUCH Hominy 36 State
PROPOSALS.)	8. Well Number 001
1. Type of Well: Oil Well Gas Well Other	9. OGRID Number
2. Name of Operator Penroc Oil Corporation	9. OOKID Nulliber
3. Address of Operator	10. Pool name or Wildcat
PO Box 2769 Hobbs, New Mexico 88241-2769	
4. Well Location	
	line and 2310 feet from the East line
Unit Letter O : 660 feet from the South line and 2310 feet from the East line Section 36 Township 15S Range 31E NMPM Chaves County	
11. Elevation (Show whether DR,	<u> </u>
11. Elevation (Snow whether DR,	KKD, KI, UK, EL.)
12. Check Appropriate Box to Indicate Na	ature of Notice Report or Other Data
12. Check Appropriate Dox to indicate in	ature of Notice, Report of Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🔲 CASING/CEMENT JOB	
OTHER: Convert to SWD	OTHER:
13. Describe proposed or completed operations. (Clearly state all p	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
Pending approval of C108(Application for Authorization to Inject)	
Penroc proposes to drill out and squeeze numerous perforations per the enclosed procedure	
Enclosures; Proposed procedure, before and after well bore diagrams, C144 CLEZ, C144 CLEZ design, operation, closure plan	
د	
SWDD293	
Canal Data	
Spud Date: Rig Release Date:	
÷	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
1. Clan	
SIGNATURE / Selly C. Truling TITLE Agent for Penroc Oil Corporation DATE 7/8/2011	
Type or print name Billy E. Prichard E-mail address:	billy@pwllc.net PHONE: 432-934-7680
For State Use Only	
APPROVED BY: JUL 19 2011	
APPROVED BY:	
Conditions of Approval (if any):	

•

.

HOMINY 36 STATE #001 API 30-005-27945 Unit Letter "O", Section 36, T15S, R31E Chaves County, New Mexico

AFE to drill out plugs, squeeze WC (9,412'-10,032')

- drillout plug above CISCO (10,142'-10,304')
- equip downhole and surface equipment prepare for disposal

Proposed Outline:

- RU pulling unit, Reverse Unit, BOP
- PU 4 3/4" bit, 4/6 DC, work string (2 7/8")
- Test csg above 9,400'
- Drill out 9,400' CIBP and pump into perfs 9,412'-10,032'
- TIH with retainer and squeeze WC perf.
- After WC drill out, squeeze, test squeeze to 800#
- Drill out CIBP @ 10,110' to 11,200'
- Squeeze perfs 10,142' -10,394' with 100 sxs
- After W.O.C. drill out above, squeeze and test to hold at least 500# 30 mins
- Continue drilling ahead and drill out CIBP at 11,200'/cement. Squeeze perfs 11,242'-11,260' with 125 sxs.
- After W.O.C. drill out, squeeze 11,242'-11,260'. Test same to at least 500#.
- Drill out CIBP at 11,560'. Squeeze perfs 11,590'-11,692' with 150 sxs. After W.O.C drill out test to at least 500#
- Drill out and squeeze similarly (as above) CIBP's 11,840', 12,090', 12,850' and 13,750'. Squeeze each set of perfs per diagram except the Devonian perfs 13,800' and down
- Test for injection 13,800' and down. TOH.
- TIH with pkr and work string
- Acid under pkr acid with 20% 10,000 gallons NEFE. Get injection rate and pressure. TOH
- TIH with NC pkr and 2 7/8" pc tbg
- Set pkr @ 13,700' + notify NMOCD for MIT need 30 min @ 500#
- Clean up. RD
- Build battery 750 GB plus 2 to 3 500 bbl tanks
- . Set up security system
- Start disposal

Proposed conversion to Devonian SWD



