Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
District I Energy	v, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 HOBBS OCD District II	CONSERVATION DIVISION	30-025-05204
District III	220 South St. Francis Dr.	5. Indicate Type of Lease
1000 KIO BIAZOS KU., AZIEC, NWI 87410 JUL -	Santa Fe, NM 87505	STATE FEE X 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Suma 1 0, 1 m 0 / 0 00	0. State Off & Gas Lease NO.
87505 DECEMED SUNDRY NOTICES AND R	EPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		W T Mann A
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other Injector		8. Well Number 2
2. Name of Operator Celero Energy II, LP		9. OGRID Number
		247128 10. Pool name or Wildcat
3. Address of Operator 400 W. Illinois, Ste. 160 Midland, TX 79701	01	Denton; Devonian
4. Well Location		
Unit Letter B : 660 feet from the North line and 2310 feet from the East line		
	Township 14S Range 37E	NMPM CountyLea
11. Elevati	on (Show whether DR, RKB, RT, GR, etc.,	
12. Check Appropriate	Box to Indicate Nature of Notice,	Report or Other Data
	ABANDON C REMEDIAL WOR	
PULL OR ALTER CASING MULTIPLE	COMPL CASING/CEMEN	ТЈОВ 🗌
OTHER:		ta iniaatan 🕅
	OTHER: Convert	to injector
13. Describe proposed or completed operation	ons. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
 Describe proposed or completed operation of starting any proposed work). SEE RU 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con	d give pertinent dates, including estimated date
 Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con a @ 12,629'. RIH CIL from 12,400' to 12, smt w/ a total of 900 sx (c Starbond +.2%	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con a @ 12,629'. RIH CIL from 12,400' to 12, emt w/ a total of 900 sx (c Starbond +.2% start on shoe @ 12,627'. Drill 12,642' to	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displacement. 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con a @ 12,629'. RIH CIL from 12,400' to 12, emt w/ a total of 900 sx (c Starbond +.2% start on shoe @ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. a lacement pressure = 1000 PSI, bumped pl	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con a @ 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2% start on shoe @ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. (lacement pressure = 1000 PSI, bumped pl at @ 12,098'. Drill out cmt from 12,098' t	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con a @ 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2% start on shoe @ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. (lacement pressure = 1000 PSI, bumped pl at @ 12,098'. Drill out cmt from 12,098' t	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con (@) 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2% start on shoe $@)$ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. (lacement pressure = 1000 PSI, bumped pl at $@)$ 12,098'. Drill out cmt from 12,098' to tottoms up. Pumped 9 sweeps. Drill out to	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correlated starting and starting s	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con (@) 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2% start on shoe $@)$ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. (lacement pressure = 1000 PSI, bumped pl at $@)$ 12,098'. Drill out cmt from 12,098' to tottoms up. Pumped 9 sweeps. Drill out to attent to CNL dated 4/1/11. Perf 12,760'-12,9	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con (@) 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2% start on shoe $@)$ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. (lacement pressure = 1000 PSI, bumped pl at $@)$ 12,098'. Drill out cmt from 12,098' to tottoms up. Pumped 9 sweeps. Drill out to atte to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Ru pressure to 1000# psi for 1.5 hrs, 10 bbls g	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con (@) 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2% start on shoe $@)$ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. (lacement pressure = 1000 PSI, bumped pl at $@)$ 12,098'. Drill out cmt from 12,098' to tottoms up. Pumped 9 sweeps. Drill out to atte to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Ru pressure to 1000# psi for 1.5 hrs, 10 bbls g	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ * Continued on attached sheet 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con (@) 12,629'. RIH CIL from 12,400' to 12, ent w/ a total of 900 sx (c Starbond +.2% start on shoe $@)$ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. (lacement pressure = 1000 PSI, bumped pl at $@)$ 12,098'. Drill out cmt from 12,098' t ttoms up. Pumped 9 sweeps. Drill out to ate to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Ri pressure to 1000# psi for 1.5 hrs, 10 bbls g /2 frac, pull 22 jts.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con (@) 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2% start on shoe $@)$ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. (lacement pressure = 1000 PSI, bumped pl at $@)$ 12,098'. Drill out cmt from 12,098' to tottoms up. Pumped 9 sweeps. Drill out to atte to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Ru pressure to 1000# psi for 1.5 hrs, 10 bbls g	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ * Continued on attached sheet 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Con (@) 12,629'. RIH CIL from 12,400' to 12, ent w/ a total of 900 sx (c Starbond +.2% start on shoe $@)$ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. (lacement pressure = 1000 PSI, bumped pl at $@)$ 12,098'. Drill out cmt from 12,098' t ttoms up. Pumped 9 sweeps. Drill out to ate to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Ri pressure to 1000# psi for 1.5 hrs, 10 bbls g /2 frac, pull 22 jts.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ * Continued on attached sheet 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Control a @ 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2%) start on shoe @ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. 0 lacement pressure = 1000 PSI, bumped pl at @ 12,098'. Drill out cmt from 12,098't oftoms up. Pumped 9 sweeps. Drill out to ate to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Riverssure to 1000# psi for 1.5 hrs, 10 bbls g a frac, pull 22 jts. Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ * Continued on attached sheet Spud Date: 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Control a @ 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2%) start on shoe @ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. 0 lacement pressure = 1000 PSI, bumped pl at @ 12,098'. Drill out cmt from 12,098't oftoms up. Pumped 9 sweeps. Drill out to ate to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Riverssure to 1000# psi for 1.5 hrs, 10 bbls g a frac, pull 22 jts. Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ * Continued on attached sheet 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Control a @ 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2%) start on shoe @ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. 0 lacement pressure = 1000 PSI, bumped pl at @ 12,098'. Drill out cmt from 12,098't oftoms up. Pumped 9 sweeps. Drill out to ate to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Riverssure to 1000# psi for 1.5 hrs, 10 bbls g a frac, pull 22 jts. Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ * Continued on attached sheet Spud Date: 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Construction a @ 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2%) start on shoe @ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. 0 lacement pressure = 1000 PSI, bumped pl at to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Rig ressure to 1000# psi for 1.5 hrs, 10 bbls g ½ frac, pull 22 jts. Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ * Continued on attached sheet Spud Date: 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Construction a (@ 12,629'. RIH CIL from 12,400' to 12, 500 mm w/ a total of 900 sx (c Starbond +.2%) start on shoe (@ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. 0 lacement pressure = 1000 PSI, bumped pl nt (@ 12,098'. Drill out cmt from 12,098'. tottoms up. Pumped 9 sweeps. Drill out to ate to CNL dated 4/1/11. Perf 12,760'-12,972 BFW. POH w/ 22 jts tbg to 12,213'. Rig grade frac, pull 22 jts. Rig Release Date: mig Release Date: TITLE Regulatory Analyst E-mail address: Ihunt@celeroene	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of 000'. PU retainer & setting tool. Run into 12, FL -10 + .5% c - 11 + .2% c - 20 + .1% c - 51 12,980'. Circ hole. Run 2 jts 4 ½" csg float Cmt w/ 125 sx Class "H",.5% FL-10, .3% C- ug w/ 1500 PSI. Note: 4 ½" liner top @ 12, o 12,300', tag liner hanger top. Circ clean. 12,915'. Pumped bottoms up, pumped sweep, 000', 810 holes in 4 runs. Break circ w/ 40 U on csg to 500# psi, bled 120# psi in 5 min. gone. Perfs not breaking. RIH w/ 22 jts tbg to e and belief.
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ * Continued on attached sheet Spud Date: 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Construction a @ 12,629'. RIH CIL from 12,400' to 12, cmt w/ a total of 900 sx (c Starbond +.2%) start on shoe @ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. 0 lacement pressure = 1000 PSI, bumped pl at to CNL dated 4/1/11. Perf 12,760'-12,9 72 BFW. POH w/ 22 jts tbg to 12,213'. Rig pressure to 1000# psi for 1.5 hrs, 10 bbls g ½ frac, pull 22 jts. Rig Release Date: TITLE Regulatory Analyst E-mail address: Ihunt@celeroene	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of 000'. PU retainer & setting tool. Run into 12, FL -10 + .5% c - 11 + .2% c - 20 + .1% c - 51 12,980'. Circ hole. Run 2 jts 4 ½" csg float Cmt w/ 125 sx Class "H",.5% FL-10, .3% C- ug w/ 1500 PSI. Note: 4 ½" liner top @ 12, o 12,300', tag liner hanger top. Circ clean. 12,915'. Pumped bottoms up, pumped sweep, 900', 810 holes in 4 runs. Break circ w/ 40 U on csg to 500# psi, bled 120# psi in 5 min. gone. Perfs not breaking. RIH w/ 22 jts tbg to e and belief.
 13. Describe proposed or completed operatic of starting any proposed work). SEE RU proposed completion or recompletion. 2/28 - 3/12/11 - D/O cmt, plug & chase to btm 050', correlated log & set cmt retainer. Sqze c + .25% R-38 + 2% salt). Drill retainer, cmt & collar & 13 jts 4 ½" liner, x-over, liner hanger 11, .3% C-35, .25% R-38, 3% Salt. Final displ 300'. Bottom of liner shoe @ 12,971. Tag cm Drill cmt, 4 1/2" liner, @ 12,845', pumping bo displaced hole w/ FW. 4/5 - 4/9/11 - RIH w/ 3 1/8" slick guns, correla BFW, pump 250 gal 15% HCL acid, flush w/ Pressure to 800# psi for 1 hr, 3 bbls gone, re-p 12,920'. Rev tbg clean, rev 6 bbls hot acid to ½ * Continued on attached sheet Spud Date: 	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Construction a (@ 12,629'. RIH CIL from 12,400' to 12, 500 mm w/ a total of 900 sx (c Starbond +.2%) start on shoe (@ 12,627'. Drill 12,642' to & setting sleeve. Circulate bottoms up. 0 lacement pressure = 1000 PSI, bumped pl nt (@ 12,098'. Drill out cmt from 12,098'. tottoms up. Pumped 9 sweeps. Drill out to ate to CNL dated 4/1/11. Perf 12,760'-12,972 BFW. POH w/ 22 jts tbg to 12,213'. Rig grade frac, pull 22 jts. Rig Release Date: mig Release Date: TITLE Regulatory Analyst E-mail address: Ihunt@celeroene	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of 000'. PU retainer & setting tool. Run into 12, FL -10 + .5% c - 11 + .2% c - 20 + .1% c - 51 12,980'. Circ hole. Run 2 jts 4 ½" csg float Cmt w/ 125 sx Class "H",.5% FL-10, .3% C- ug w/ 1500 PSI. Note: 4 ½" liner top @ 12, o 12,300', tag liner hanger top. Circ clean. 12,915'. Pumped bottoms up, pumped sweep, 000', 810 holes in 4 runs. Break circ w/ 40 U on csg to 500# psi, bled 120# psi in 5 min. gone. Perfs not breaking. RIH w/ 22 jts tbg to e and belief.

AUG 0 8 2011

1

WT Mann A #2 - C103 continued

<u>4/11/11</u> - POH w/ 2 7/8" tbg. RIH w/ 1 jt 2 7/8" tailpipe, 4 ¹/₂" cline pkr, 2 3/8" SN, x-over, 400 jts 2 7/8" tbg. Tailpipe @ 12,901'. Break circ w/ 22 bbls, pump 1000 gals 15% HCL, flush w/ 63.5 BFW. Tailpipe @ 12,514', pkr @ 12,482'. Rev w/ 24 bbls, set pkr @ 12,482', csg to 500# psi, start pumping into perfs as soon as started pumping. Flush w/ 55 BFW. ISIP: 2100#, 5 min: 1911#, 10 min: 1825#, 15 min: 1736#. Max rate 5.8, avg rate 4.8, Max psi 3106, avg psi 2800.

6/22/11 - RIH w/ 4 1/2" CIBP & set @ 12,725'. Dump bail cmt in 2 runs.

6/23/11 - RIH w/ dump bailer. Tag @ 12,703'. Dump 35' cmt. RIH w/ 3 1/8" slick guns, w/ 120 degree phasing, locate top of tie back extension @ 12,258', correlate to GR/CCL/CNL dated 4/1/11. Perf 12,654'-12,644'-22 holes, 12,620'-12,599'-42 holes, 12,578'-42 holes, 12,488'-12,474'-28 holes, 12,474'-12,434' – 80 holes. Lost perf gun in hole. Locate top of tie back. Tag perf gun @ 12,627'. Top of fish @ 12,627' (Tally), btm of fish @ 12,673' (Tally).

6/27/11 - RU w/3 1/8" slick guns, w/ 120 degree phasing, fluid level @ 2500'. Locate top of tie back extension @ 12,258'. Correlate to GR/CCL/CNL dated 4/1/11. Perf 12,434' - 12,414'; 40 holes, 12,414' - 12,394'; 40 holes, 12,380' - 12,370'; 22 holes. Tag fish @ 12,614' (WL). Final fluid level @ 3400'.

6/28/11 - RIH w/ tie back seal assembly, 7" Model FA pkr, B2 setting tool, lubricated BS, 383 jts of tbg. Sting into tie back extension @ 12,302' (Tally). Load csg w/ 30 bbls, test to 500# psi, drop ball down tbg, psi up on ball to 1500# psi, pull 25 pts over on pkr, rotate out of FA pkr.

6/30/11 - Ran 2806', 13.5#, L-80, LT&C; 6997' L-80, LT&C; & 2479' 13.5# L-80, LT&C.

 $\frac{7/1/11}{1}$ - Tbg & csg was on a vacuum. Mix 3 drums of pkr fluid w/ 300 BFW in tank. Pump 2 BPM, broke circ w/ 53 bbls to half frac pumped 230 bbls down csg, stung into pkr, pulled 10 over to make sure it was latched up. NDBOP, install slips, landed well w/ 40K on pkr. Pressured up on csg to 560#. Recorded chart for 32 min, no psi loss or gain w/ tbg valve open. Install 4 $\frac{1}{2}$ gate valve on tbg.

<u>7/5/11</u> - Gelled acid in tank, install pressure relief valve on backside. Backside was loaded, pressured up to 500#. Test lines to 4000# psi, started pumping acid, pumped 20 bbls ahead then dropped 1 ball every 2 bbls, tbg loaded w/ 72 bbls. Avg psi 3143#, Max psi 3500#, Min psi 2785#, ISIP 1295#, Max rate 20.3 BPM, Avg rate 9.5 BPM. Total load to recover 798.5 bbls,

7/12/11 - RIH w/ Electro BHP tool to 12,507'- 2423 psi @ 181.96 F. POH making gradient stops 12,307' - 2335 psi, 12,000' - 2205 psi, 10,000' - 1354 psi, 8000' - 501 psi, 6000' - 38 psi, 4000' - 35 psi, 2000' - 31 psi, 0' - 29 psi. ND Master valve, NU 7 1/16" flange x 4 ½" ID w/ o'rings. NU Master valve. Ran MIT. Pressure to 590# psi. Lost 10# psi in 31 mins to 580# psi. Test is good. Maxey Brown w/ NMOCD witnessed & approved the test. Original chart is attached. Well in now an injection well as per Order No. R-13387.



--- ------

W. T. Mann "A" # 2 660' FNL & 2310' FEL of Sec. 36, T14S, R37E, Unit Letter "B"



1

.. .

1