Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
	Energy, Minerals and Natural Resources	October 13, 2009 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION DIVISION	30-025-40033
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 8000 0 5	2011	STATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICE	FAND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	S TO DRILL OR TO DEEPEN OR PLUG BACK TO A ON FOR PERMIT" (FORM C-101) FOR SUCH	T D Pope 35
	s Well Other	8. Well Number 34
Name of Operator Celero Energy II		9. OGRID Number 247128
3. Address of Operator 400 W. Illinois Midland, TX	s, Ste. 1601 79701	10. Pool name or Wildcat Denton; Devonian
4. Well Location		·
Unit Letter A : 715	feet from the N line and	1065 feet from the E line
Section 35	Township 14S Range 37E	NMPM CountyLea
The transfer of the second of	1. Elevation (Show whether DR, RKB, RT, GR, 6 3807'	etc.)
12. Check App	ropriate Box to Indicate Nature of Notice	ce, Report or Other Data
NOTICE OF INTE	INTION TO:	IDECOLENT DEDODT OF:
NOTICE OF INTE PERFORM REMEDIAL WORK ☐ PI	LUG AND ABANDON REMEDIAL W	JBSEQUENT REPORT OF: ORK
	— ,	DRILLING OPNS. P AND A
	IULTIPLE COMPL	
DOWNHOLE COMMINGLE		
OTHER:	☐ OTHER: Well	
OTHER: 13. Describe proposed or completed	d operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple pletion.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple pletion. woth bit, BS, 6-4 3/4" DC's. Start in hole w/ 2 7/8"	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple pletion. ooth bit, BS, 6-4 ¾" DC's. Start in hole w/ 2 7/8' circ, drill w/ 1 pt for 2 min, bit bouncing. PU of	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings,
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to ② 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak of 32 jts new 2 3/8" 4.7# L-80 8rd tbg (d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple pletion. Seth bit, BS, 6-4 ¾" DC's. Start in hole w/ 2 7/8" circ, drill w/ 1 pt for 2 min, bit bouncing. PU of fin 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to ② 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak of 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple pletion. soft bit, BS, 6-4 ¾" DC's. Start in hole w/ 2 7/8" circ, drill w/ 1 pt for 2 min, bit bouncing. PU of fir 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH (972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. W/ 485 BFW. POH w/ all tbg, LD 6-3 ½" DC's	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790',
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak o 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'.	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soth bit, BS, 6-4 ¾" DC's. Start in hole w/ 2 7/8" circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH (972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. w/ 485 BFW. POH w/ all tbg, LD 6-3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CE	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500#
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak o 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applocate collar @ 12,110'. Shoot 4 hole	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8" circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 1972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. W/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH es 90 degree phasing @ 12,115'. RIH w/* 4 ½" C	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ³/4" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x-
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak o 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applocate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'.	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soft bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8" circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 1972.25"), x-over, 332 jts 2 7/8" tbg to 11,801". W/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH es 90 degree phasing @ 12,115'. RIH w/* 4 ½" C. TIH witho369 jts 2 7/8", set pkr @ 12,157'. To	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x- est pkr to 1000# psi, raise pkr to 366 jts in. Set
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak o 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applocate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soft bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8" circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 1972.25"), x-over, 332 jts 2 7/8" tbg to 11,801". W/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH es 90 degree phasing @ 12,115'. RIH w/* 4 ½" C. TIH witho369 jts 2 7/8", set pkr @ 12,157'. To	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x- est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak o 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applocate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8' circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. w/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH es 90 degree phasing @ 12,115'. RIH w/* 4 ½" Composition of the composition of t	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x- est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak o 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applocate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B 4 ½" semi composite retainer, setting	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8' circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. w/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH es 90 degree phasing @ 12,115'. RIH w/* 4 ½" Composition of the composition of t	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x- est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak o 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applocate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B 4 ½" semi composite retainer, setting * Continued on attached sheet	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. ooth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8" circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. W/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH 98 90 degree phasing @ 12,115'. RIH w/* 4 ½" Compared to the series of the ser	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x-est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/ y, 355 jts 2 7/8" tbg to 11,710'.
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak o 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applocate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B 4 ½" semi composite retainer, setting	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8' circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. w/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH es 90 degree phasing @ 12,115'. RIH w/* 4 ½" Composition of the composition of t	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x-est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/ y, 355 jts 2 7/8" tbg to 11,710'.
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak of 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applicate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B 4 ½" semi composite retainer, setting * Continued on attached sheet Spud Date: O5/11/2011	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8' circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH (972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. w/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH es 90 degree phasing @ 12,115'. RIH w/* 4 ½" Co. TIH witho369 jts 2 7/8", set pkr @ 12,157'. To GPM @ 300# psi, pump 20 bbls, close 7", psi up g tool, 2 3/8" SN, 10 jts 2 3/8" tbg (332'), x-over	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ½" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x-est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/ y, 355 jts 2 7/8" tbg to 11,710'.
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak of 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applicate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B 4 ½" semi composite retainer, setting * Continued on attached sheet Spud Date: O5/11/2011	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. ooth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8" circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. W/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH 98 90 degree phasing @ 12,115'. RIH w/* 4 ½" Compared to the series of the ser	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ½" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x-est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/ y, 355 jts 2 7/8" tbg to 11,710'.
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak of 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applicate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B 4 ½" semi composite retainer, setting * Continued on attached sheet Spud Date: 05/11/2011	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8' circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH (972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. W/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CEProximately 7290'. POH w/ GR/CCL/CBL. RIH (98 90) degree phasing @ 12,115'. RIH w/* 4 ½" Co. TIH witho369 jts 2 7/8", set pkr @ 12,157'. To GPM @ 300# psi, pump 20 bbls, close 7", psi up g tool, 2 3/8" SN, 10 jts 2 3/8" tbg (332'), x-over cover is true and complete to the best of my knowledge.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ½" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x-est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/ y, 355 jts 2 7/8" tbg to 11,710'.
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak of 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applicate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B 4 ½" semi composite retainer, setting * Continued on attached sheet Spud Date: O5/11/2011	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8' circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH (972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. w/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CE proximately 7290'. POH w/ GR/CCL/CBL. RIH es 90 degree phasing @ 12,115'. RIH w/* 4 ½" Co. TIH witho369 jts 2 7/8", set pkr @ 12,157'. To GPM @ 300# psi, pump 20 bbls, close 7", psi up g tool, 2 3/8" SN, 10 jts 2 3/8" tbg (332'), x-over	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ½" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x-est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/ y, 355 jts 2 7/8" tbg to 11,710'.
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak of 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applicate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B 4 ½" semi composite retainer, setting * Continued on attached sheet Spud Date: O5/11/2011 I hereby certify that the information above the setting that the infor	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple obletion. soth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8' circ, drill w/ 1 pt for 2 min, bit bouncing. PU of off in 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH (972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. W/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's. Log from 12,877'- 9900'. POH w/ GR/CCL/CEProximately 7290'. POH w/ GR/CCL/CBL. RIH (98 90) degree phasing @ 12,115'. RIH w/* 4 ½" Co. TIH witho369 jts 2 7/8", set pkr @ 12,157'. To GPM @ 300# psi, pump 20 bbls, close 7", psi up g tool, 2 3/8" SN, 10 jts 2 3/8" tbg (332'), x-over cover is true and complete to the best of my knowledge.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ¾" workover bit, BS, 6- 3 1/8" DC's, x-over, Fag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x- est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/ y, 355 jts 2 7/8" tbg to 11,710'. DATE09/13/2011
OTHER: 13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 8/1 - 8/5/11 - NUBOP. PU 6" mill to @ 11,821' w/ 362 jts + 5'. Break rev psi well bore to 1000# psi, no leak of 32 jts new 2 3/8" 4.7# L-80 8rd tbg (12,871', rev btms up. Rev hole clean continue in hole. Tag TD @ 12,877'. psi, log from 12,210'-4795'. TOC applicate collar @ 12,110'. Shoot 4 hole over, 360 jts of 2 7/8" tbg to 11,611'. pkr @ 12,058', break circ out 7", 2 B 4 ½" semi composite retainer, setting * Continued on attached sheet Spud Date: O5/11/2011	d operations. (Clearly state all pertinent details, SEE RULE 19.15.7.14 NMAC. For Multiple poletion. soth bit, BS, 6- 4 ¾" DC's. Start in hole w/ 2 7/8" circ, drill w/ 1 pt for 2 min, bit bouncing. PU of fir 15 min, POH w/ tbg, LD 4 ¾" DC's. RIH 972.25'), x-over, 332 jts 2 7/8" tbg to 11,801'. W/ 485 BFW. POH w/ all tbg, LD 6- 3 ½" DC's Log from 12,877'- 9900'. POH w/ GR/CCL/CBproximately 7290'. POH w/ GR/CCL/CBL. RIH w/s 4 ½" Compression of the second of the	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of "tbg, ran 305 JTS bit @ 9,918'. TIH w/ bit. Tag ff liner, rev hole clean. Recovered metal shavings, w/ 3 ½" workover bit, BS, 6- 3 1/8" DC's, x-over, Tag w/ 362 jts + 25' @ 12,816'. Drill good cmt to s. RIH w/ GR/CCL/CBL. Top of fluid @ 790', BL. RIH w/ GR/CCL/CBL, load csg, psi to 1500# w/ 3 1/8" Slick guns, locate TOL @ 11,823', CST pkr, 2 3/8" SN, 11 jts of 2 3/8" tbg (334'), x- est pkr to 1000# psi, raise pkr to 366 jts in. Set to 1500# psi w/ no leak off. POH w/ pkr. RIH w/ y, 355 jts 2 7/8" tbg to 11,710'. DATE _09/13/2011 energy.com PHONE: _(432)686-1883

- 8/8/11 RIH w/ 11 jts of 2 7/8" tbg to 12,050'. Pump 80 bbls through retainer, set retainer @ 12,050'. Pump 410 BFW @ 1.5 BPM through retainer out holes @ 12,115' for cool down. Establish injection rate of 2 BPM @ 450# psi. Mix 50 sx of Class "H" cmt containing .5% FL-10, .3% C-15, .3% C-35, .2% C-20, .25% R-38, .3% salt @ 2:23 Cst, 15.6 ppg, 1.20 yield, 5.24 gallons p/sx. Displace w/ 68 BFW. Reverse out w/ 80 bbls, reversed 2 bbls colored cmt wtr, roll pumps in increments to 1500# psi w/ no bleed off. POH w/ 66 stands tbg. Load WB, psi to 1500# psi.
- 8/9/11 POH w/ tbg & setting tool. RIH w/ 3 $\frac{3}{4}$ " workover bit, BS, 6- 3 $\frac{1}{8}$ " DC's, x-over, 34 jts of 2 $\frac{3}{8}$ " tbg, x-over, 336 jts + 26' 2 $\frac{7}{8}$ ". Tag @ 12,018'. Wash drill to 12,047' in 15 min. Returns were soft cmt & soft cmt balls. Rev hole clean.
- <u>8/10/11</u> Drlg good cmt, Fell out of cmt @ 12,116'. Rev btms up, test to 1500# psi for 15 min w/ no leak off. RIH & tag @ 12,810'. RIH & tag @ 12,871'. Rev btms up w/ 100 bbls.
- 8/11/11 RIH w/ GR/CCL/CBL, log from 12,200'-11,700'. TOC @ 11,890', log correlated to Schlumberger density/neutron log dated 7/15/11. POH w/ GR/CCL/CBL. RIH w/ GR/CCL/CNL. Log from 12,880'-11,828' & 10,000'-9050'. Tools failed @ 9050'. POH w/ GR/CCL/CNL. Found cable shorted 4' above cable head. RIH w/ 3 1/8" slick guns, locate liner top @ 11,828', tag TD @ 12,880', tie into collars, perf 12,830'-12,848'-19 shots-0 degree phasing POH. RIH w/ 4 ½" CST pkr, 2 3/8" SN, 34 jts 2 3/8" tbg, x-over, 304 jts 2 7/8" tbg to 10,801'.
- 8/12/11 Set pkr @ 12,747'. RU swab, IFL surface, made 13 runs, recovered 57 bbls, FFL @ 9200'. Tag @ 10,674'.
- <u>8/15/11</u> Load tbg w/ 52 bbls, release pkr, pump 1000 gal of 15% HCL, flush w/ 79 bbls @ 1 BPM to pickle tbg, reverse acid out of tbg w/ 104 bbls. RIH w/ 3 jts of 2 7/8" tbg, pump 500 gal of 15% HCL, flush w/ 67.8 BFW to spot acid across perfs @ 12,830'-12,848'. Pull 3 jts to 12,747', reverse acid w/ 20 bbls, set pkr, psi csg to 500# psi. RU on tbg & acidize w/ 500 gal of 15% NEFE acid, flush w/ 40 BFW. Max psi = 3700, Avg psi = 3000. Max rate = 4.6, avg rate = 3.5, ISIP = 1720, 5 min = 923, 10 min = 462, 15 min = 182. RD Crain. RU swab, IFL surface, made 13 runs, recovered 82 bbls, FFL @ 7432'. Final pull from 8600'.
- <u>8/17/11</u> RIH w/ electro BHP tool to 12,700'- 4449.44 psi-184.02 F. POH making gradient stops: 12600' 4405.23 Psi, 12500' 4360.90 Psi, 12000' 4140.44 Psi, 11500' 3918.98 Psi, 11000' 3697.51 Psi, 10500' 3475.50 Psi, 10000' 3253.56 Psi, 9000' 2808.92 Psi, 8000' 2363.31 Psi, 6000' 1471.44 Psi, 4000' 578.29 Psi, 2000' 21.53 Psi, 0' 29.50 Psi. POH w/ tbg & pkr. RIH w/ 3.90 OD gauge ring & junk basket, tag TOL w/o correction @ 11,834', work gauge ring 5 times, fell inside liner & became stuck @ 11,852'. Work back up to 11,843', collar locator @ 11,835', pull 2000# over losing several pounds per/min. Leave w/ 2000# pulled.
- 8/18/11 Lost 450# psi overnight, work up to 4350 for 10 min, no upward movement. Pull up to 4800 & pulled out of rope socket. RIH w/ 3 7/8" overshot w/ 3 1/8" grapple, top sub, x-over, BS, x-over, 34 jts 2 3/8" tbg, x-over, 337 jts 2 7/8" tbg. Tag at 11,832', worked down to 11,842', set 6 pts, pull 10 pts over, pulled loose, set back down, pulled free w/ 6 pts pulled.
- <u>8/19/11</u> RIH with 3 3/4" O.D., short catch overshot with 1 11/16" grapple, BS, jars, x-over, 4) 3 1/8" DC's, x-over, 2 3/8" S.N., 10 jts 2 3/8" tbg, x-over, 354 jts 2 7/8" tbg to 11,816'. RIH with swab, IFL 1061', made 8 swab runs, recovered 72 bbls fluid, last 3 runs FL at 2500'. Tag top of extension at 11,828', had to rotate to work inside liner, tag fish at 11,841', set 6 pts wt, pulled 15 pts, fish came free, set 6 pts wt, fish moving down. RIH 45', pull up dragging through x-over, pull above liner extension, set gauge ring on top of extension. POH with tbg, LD 2 3/8" tbg and collars, recovered all of fish.
- <u>8/20/11</u> RIH with 3.60 gauge ring and junk basket, tag TOL to 12,860' POH with gauge ring. RIH with 4 1/2" CIBP, correlate to GR/CCL/CNL log dated 8-11-11, set CIBP at 12,820'. RIH with 3 1/8" slick guns, 0 degree phasing, 1 SPF, IFL at 3000', perf from 12,710' to 12,790', 80 holes in 4 runs, FFL at 2940'. RIH with 3" dump bailer w/ cone bottom, dump bail 1.5 sx cmt on CIBP at 12.820'.
- 8/22/11 RIH w/ 4 ½" CST pkr, 2 3/8" SN, x-over, 33 jts of 2 3/8" tbg, x-over, 362 jts of 2 7/8" tbg. Set pkr @ 12,642', load csg w/ 58 bbls, test pkr to 600# psi. RIH w/ swab, IFL 2500'. Made 10 swab runs, recovered 41 bbls, FFL 10,532', last pull from x-over @ 11,615'. Tag fluid @ 10,532'.

- <u>8/23/11</u> Psi csg to 500 psi, load tbg with 46.5 bbls, broke at 2860 psi, increase rate to 5 BPM at 2890 psi, acidize with 8000 gals 15% HCL with 2 stages of 1500# rock salt, completely blocked off both times, flush with 176 BFW, ISIP 3180, 5 min 2775, 10 min 2577 psi, 15 min 2410 psi, max psi 6000, avg psi 4285, avg rate 4.8 BPM, 482 bbls load to recover.
- <u>8/29/11</u> RIH with Electro BHP tool to 12750' 4162.69 psi 181.81 F, POH making gradient stops, 12600' 4095.92 psi, 12500' 4050.95 psi, 12400' 4006.19 psi, 12000' 3826.71 psi, 11000' 3377.26 psi, 10000' 2926.51 psi, 9000' 2472.81 psi, 8000' 2018.86 psi, 6000' 1108.53 psi, 4000' 205.48 psi, 2000' 115.95 psi, 0' 108.45 psi. Tag fluid at 4067'. POH with tbg and pkr. RIH with 4 1/2" Kline BP and CST pkr, 2 3/8" S.N., 33 Jts 2 3/8" tbg 1001', x-over, 322 jts 2 7/8" tbg to 12477'.
- 8/30/11 TIH to 363 jts 2 7/8" tbg in, set Kline RBP @ 12,660', set pkr @ 12,644'. Load tbg w/ 38 bbls, test tools to 3100 psi, release pkr. POH w/ tbg, pkr & overshot.
- <u>8/31/11</u> RIH with 3 1/8" slick guns, 180 degree phasing, 2 SPF, correlate to GR/CCL/CNL log dated 8-11-11. Tie into TOL each run, perforate 12600 12612, 12514 12562, 12367 12429, 12338 12348, total of 264 holes in 7 runs. RIH with 4 jts 2 3/8" tbg, x-over, 7" HD pkr, x-over, 2 3/8" S.N., x-over, 20 stands 2 7/8" tbg.
- <u>9/1/11</u> TIH with 7" HD pkr to 366 jts 2 7/8" tbg in, set pkr at 11,774.33', tailpipe at 11,895.19'. Load csg with 16 bbls, test pkr to 500 psi. RU on tbg, load tbg with 3 bbls, broke at 3600 psi, increase rate to 2 BPM at 4200 psi, 5 bbls gone, 1.6 BPM at 4900 psi, 10 bbls gone, 1.3 BPM at 5000 psi. SD pumps, ISIP 4900, 5 minute 3300 psi, bleed psi.
- <u>9/2/11</u> Acidize perfs 12600 12612, 12514 12562', 12367 12429, 12338 12348', 2 SPF, pump 16000 gallons 15% NEFE HCL, with 5000# of 50/50 100 Mesh/Graded Rock Salt in 5 stages, 6 stages of inhibitor, flush with 178 BFW, ISIP 2920, 5 min vacuum, max psi 6120, avg psi 4200, max rate 9.3, avg rate 8.0, total load 1038 bbls. POH with tbg & pkr.
- <u>9/6/11</u> RIH with overshot, 30 jts 2 3/8" tbg, x-over, 369 jts 2 7/8" tbg to 12,600'. Wash down to RBP at 12,660', release RBP. LD 89 jts 2 7/8" tbg, stand back 282 jts 2 7/8" tbg (9036.42'), LD 2 3/8" tbg and Kline RBP.
- <u>9/7/11</u> RIH with electro BHP tool to 12,695' 2511 psi 183 F. POH making gradient stops, 12595' 2467 psi, 12500' 2424 psi, 12000' 2208 psi, 11500' 1995 psi, 11000' 1783 psi, 10500' 1995 psi, 10000' 1359 psi, 9000' 939 psi, 8000' 631 psi 6000' 100 psi, 4000' 94 psi, 2000' 87 psi, 0' 82 psi. RIH with 82 jts "New" 2 7/8" 7.9# L-80 PH-6 tbg (2562.19').
- <u>9/8/11</u> NDBOP, NU Seaboard WH, NUBOP. PU GE sub pump as follows: 1) Smartguard, 1) 540 TR5 200 HP motor, 2140-V, 54-A, 1) TR5 Std seal, 1) TR5 DBG seal, 1) Mag gas separator, 5) TD1750 pumps 616 stages, 2 3/8" S.N., x-over, 220 jts 2 7/8" 6.5# L-80 8rd tbg. SWI. SDFN.
- <u>9/9/11</u> TIH with 62 jts 2 7/8" 8rd tbg, total of 282 jts 2 7/8" 6.5# L-80 8rd tbg (9036.40'), x-over, 82 jts new 2 7/8" 7.9# L-80 PH-6 tbg (2562.19'). Splice in new lower pigtail onto new #2 flat lead cable, WIR 110,000. Land donut into seaboard WH, intake at 11,735.63', btm of seaboard WH at 11,780.68', NDBOP, NU Master Valve and flowlines, check rotation start pumps at 3:50 CST at 57 Hz straight current. Leave well pumping to battery.