Submit 1 Copy To Appropriate District	To Appropriate District State of New Mexico		Form C-103	
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources		ral Resources	Revised August 1, 2011 WELL API NO.	
District III – (575) 748-1283 811 S. First St., Artesia, NM 8884,0885 OCD OIL CONSERVATION DIVISION District III – (505) 334-6178 1220 South St. Francis Dr.			30-025-00285	
			5. Indicate Type of Lease STATE X FEE	
1000 Rio Brazos Rd., Aziec, NM 87410 \mathbf{A} 2011 Santa Fe NM 87505		/505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, WART - 87505			303735	
SUNDRY NOT SUNDRY NOT SUND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name ROCK QUEEN UNIT	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injector			8. Well Number 108	
2. Name of Operator Celero Energy II, LP			9. OGRID Number 247128	
3. Address of Operator 400 W. Illinois, Ste. 1601			10. Pool name or Wildcat	
Midland, IX 79701			Caprock; Queen	
4. Well Location				
Unit Letter P: Section 19	<u>660'</u> feet from the <u>S</u> Township 13S Ra	line and <u>990'</u>	feet from th NMPM Co	
Section 19 Township 13S Range 32E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4380' KB				
12 Chaok	Annuanziata Day ta Indiasta N	oturo of Notico D	anout on Other De	ła
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB				
				•
OTHER:		OTHER: Unsuccess	ful return to injection	<u> </u>
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
10/13/11 - MIRU. Pump 22 BFW down tbg w/ no psi or flow. Pump down 4" x 5 ½" annulus @ ¼ BPM @ 300#. No psi or flow on 5 ½" x 8 5/8". NDWH & NUBOP. Unseat arrowset pkr & TOH. Pulled 7 jts + 15', pipe stuck. Tried to work pkr loose, but unsuccessful. Pump 10 bbls down backside. Pumped past pkr, had fluid return through tbg.				
10/14/11 - Managed to break top joint 2 3/8" 4.7# IPC w/ TOC & LD same. Tried again to get off pkr, but was unsuccessful. Run freepoint. Pipe 100% free @ 2720'. Top of pkr @ 2760'. RIH w/ 1 11/16" cutter, could not get past 2537'. POH & PU wt bar. RIH, but still could not get past 2537'. POH w/ WL. Pump 100 BFW down tbg, check wt - 8.4 in & 8.4 out. Had 1 spot 8.8 heavy. RIH w/ 1 11/16" cutter. Would not go. POH & PU 1 ½" cutter. RIH, still could not get past 2537'. POH w/ WL.				
10/15/11 - Pump 40 BFW down tbg. RIH w/ 1 3/8" cutter w/ wt bar 15' of tools. Tag @ 2537'. Could not work through. POH & LD wt bar. RIH w/ 1 3/8" cutter 8' of tools, no go. POH & RIH w/ 1 ½" spud bars & Hyd jars, 20' of tools. Could not spud through. POH w/ spud bars & jars. RIH w/ 1 11/16" cutter & cut off @ 2410'. TOH, recovered 83 jts + 22'. * Continued on attached sheet				
Spud Date:	Rig Release Da	ite:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Lisa 7	Furt	tory Analyst	DATE	12/13/2011
Type or print name Lisa Hunt	E-mail address	: lhunt@celeroenerg		E: (432)686-1883
For State Use Only		. <u>manageorer</u> oenerg	<u>J.com</u> THON	L. <u>172/000-1005</u>
APPROVED BY Conditions of Approval (if any):	TITLE ST	nff Ma	DATE_	12-15-2011

r

DEC 1 5 2011

Rock Queen Unit #108 - C103 continued

<u>10/17/11</u> - PU 3 3/8" overshot w/ pack off, 2 3/8" grapple, 4' sub, x-over, x-over jars, BS, x-over, 6- 2 7/8" DC's. x-over, total BHA 202.40. TIH w/ 71 jts 2 3/8" WS. Workover & latch onto fish @ 2410'. Would not jar up, but got fish to jar down. Jarred down 20' & pumped down tbg & reverse, got tbg moving up. LD 4 jts & TOH w/ fish. Recovered 11 jts IPC tbg, arrowset pkr & on/off tool. Two slips missing in pkr & rubbers torn, 9 jts 2 3/8" IPC tbg bent.

<u>10/18/11</u> - TIH w/ 86 jts 2 3/8" 4.7# IPC tbg & LD same. TIH w/ 2 7/8" DC's & LD same. TIH w/ 2 3/8" pef sub, BP & 88 jts 2 3/8" WS (2771'). Taking 6 to 8K going down & tbg started turning taking 10K to pull back out. From jt 90 down took 16K down & 30K up. Worked tbg down to 4" csg shoe @ 3052'. Pump down & clear tbg. TOH w/ 2 3/8" WS. Had 30K-35K drag for first 5 stds, then drag fell off to 4K -6K. LD 9 bent jts.

<u>10/19/11</u> - TIH w/ 2 3/8" WS to 3060'. Had to work 9 jts down. Lead w/ 30 BFW & spot 25 sx plug Class "C" smt w/ 2% CaCl2. Displace w/ 11 bbls. Initial psi 500# @ 1.5 BPM, "0" psi on cmt. TOH to 1983' & clear tbg. Pipe would not go back down. TOH & LD bad jts. WOC 4 hrs. TIH, but could not tell if we tagged cmt. TOH & LD bad jts. RIH w/ Rotary W/D to tag plug w/ 1 11/16" spud bar, but could not get past 2761'. TIH w/ tbg to 3060' & spot 25 sx Class "C" cmt w/ 2% CaCl2. Displace w/ 9 bbls. TOH to 2000' & rev tbg clear. Finish TOH & LD 9 bad jts.

<u>10/20/11</u> - RIH w/ 1 11/16" spud bar & 7' of tools. Could not go past 2761', but did not tag plug. TIH w 2 3/8" perf sub & BP to 3057'. Lead w/ 35 BFW, spot 50 sx Class "C" cmt w/ 2% CaCl2. Displace w/ 7.5 bbls & TOH. WOC 4 hours. RIH w/ 1 11/16" spud bar. Tag plug @ 1954'. POH. TIH w/ 3 3/8" RR Hanson bit. Ran 8 stds in hole.

<u>10/21/11</u> - TOH. PU Hanson FBO RR bit, BS, 6- 2 7/8" DC's, x-over, 58 jts 2 3/8" WS. Tag @ 1960'. LD pipe. PU swivel & drill cmt from 1960'-2193'. ROP 38.9 FPH. 100% cmt in returns.

<u>10/22/11</u> - TOH for bit. PU Hanson FBI bit SN HB 2571 & TIH w/ same BHA to 2193'. PU swivel & drill cmt from 2193'-2413'. Circ hole clean. LD swivel & TOH. PU 4" AS1-X pkr & TIH w/ 74 jts 2 3/8" WS to 2326'. Set pkr & test plug to 1000#, tested ok. LD 10 jts & TOH.

<u>10/24/11</u> - TIH open ended & circ brine mud. TOH & RU WL. Load 4"x5 ½" annulus & SI. RIH w/ 2 ½" csg gun & shoot 4 holes @ 2253'. PU 4" AS1-X pkr & TOH to 2012'. Set pkr & establish inj rate w/ 4"x5 ½" annulus open well circ w/ 4"x5 ½" annulus closed established injection rate of 1.2 BPM @ 500#.

<u>10/25/11</u> - Open well, 400# on csg, 350# on tbg. Bleed off psi to pit. RU & pkr squeeze 40 sx Class "C" cmt w/ 2% CaCl2. Displace w/ 8.5 bbls. Well went on vacuum. Over displaced w/ 12 bbls past perfs @ 2253'. SI & WOC 2 hrs. Pump 280 sx Class "C" cmt w/ 2% CaCl2. Displace w/ 8 bbls, well still on vacuum @ 1 BPM. Over displaced w/ 15 bbls. Unseat pkr & TOH.

<u>10/26/11</u> - Open well, 100# on csg. Bleed off to pit. TIH w/ 72 jts of 2 3/8" WS, perf sub & BP. Tag cmt @ 2258'. RU swab & RIH, hit fluid @ 500'. Made 3 runs, fluid level remained @ 500'. LD 6 jts.

<u>10/27/11</u> - Open well, 300# on csg. Bleed off to pit. Pump 25 sx Class "C" cmt w/ 2% CaCl2. Displace w/ 6 bbls on gravity. Well on vacuum. TOH & WOC for 4 hrs. TIH w/ PS & BP, tag the same as yesterday @ 2258'. Pump 30 sx Class "C" cmt w/ 2% CaCl2. Displace w/ 5 bbls on gravity, well on vacuum. TOH.

10/28/11 - Open well, well static. TIH w/ PS, BP & 61 jts 2 3/8" WS. Tag @ 1925'. TOH LD WS. NDBOP & remove 4" WH. NUBOP on 5 $\frac{1}{2}$ " WH. Change rams to 4" & RIH w/ freepoint tool & tag @ 1860'. Pipe free @ 1834'. POH & RIH w/ string shot & backoff 4" @ 1834'. LD 42 jts 9.5# 4" J55 UFJ, total pipe 1841' + 16' stub w/ 4 $\frac{1}{2}$ " bell nipple for total of 1857'.

10/31/11 - NDBOP, install 1 jt 2 3/8" tbg in 5 1/2" WH & NU same. RD workover unit. Waiting for P&A Company.