•~	Office	ate of New Me			Form C-103				
	<u>District I</u> – (575) 393-6161 Energy, Mi	inch Dr., Hobbs, NM 88240   (575) 748-1283   IOBBS OCD   St., Artesia, NM 88210   - (505) 334-6178   razos Rd., Aztec, NM 87AN 1 8 2012   - (505) 476-3460       1220 South St. Francis Dr.   Santa Fe, NM 87505			Revised August 1, 2011 WELL API NO.				
	District II – (575) 748-1283 HOBBS OCD SLL S. First St. Artonia NM 88210 OIL CON					30-005-			
	District III $= (505) 334-6178$ 1000				5. Indicate 7 STAT		FEE 🔀		
	District TV = (303) + 70 - 3400				6. State Oil				
	1220 S. St. Francis Dr., Santa Fe, NM 87505								
ſ	SUNDRY NOTICES AND REPORTS ON WELLS					me or Unit A	greement Name		
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI			Rock Queen	Unit				
	PROPOSALS.) 1. Type of Well: Oil Well 🕅 Gas Well 🔲 Ot	her			8. Well Nur	nber 312	/	-	
ŀ	2. Name of Operator Celero Energy II, LP	ne of Operator				9. OGRID Number			
ŀ	3. Address of Operator 400 W. Illinois, Ste. 1601					247128 //			
	Midland, TX 79701		Caprock; Queen						
ŀ	4. Well Location								
Unit Letter B : 500 feet from the N line and 1650 feet from the E line									
Section 34 Township 13S Range 31E NMPM County Chaves   11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)									
11. Elevation (Snow whether DR, RKB, R1, GR, etc.)									
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data									
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF							OF:		
	PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK					— — —			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A   PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB I							A L		
	DOWNHOLE COMMINGLE				100				
OTHER: OTHER: Release rig								<u> </u>	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of								ate	
proposed completion or recompletion.									
12/5/11 - DP tagged at 615'. Ream & wash to 1512' where we got a kick and SWI, lost circulation.									
12/6/11 - Ream & wash from 2173 to 3115. TOH to 2800' to set cement plug.								r	
12/7/11 - Set 1st cmt plug w/ 200 sx @ 2800'. Tag cmt @ 2950', pull out to 2800'. Set plug #2 w/150 sx, pump 5 bbls brine @ 2800'. Pull 10 stds, pump 10 bbls & pull 6 stds. WOC plug. Tag @ 2950'. Pumped 1.5 times annular capacity & did not have any returns.									
12/8/11 - TOH 6 stands to 2450'. Pump plug #3 with 200 sx cement 2% cacl @ 2450'. Pull 13 stands to 1418' and got stuck (27 total stands out). Ream back through tight spot from 1418' to 1544'. Tag cmt @ 2446'. Drl cmt to 2550'. Ream w/ full returns.									
	12/9/11 - LD 12 joints. TOH to csg shoe @ 377'. R	Leam from 450' to	2550	. Drl cmt fron	n 2550' to 261	0'.			
12/10/11 - Drl cmt from 2610' to 2670'. Mix LCM pills, pump & spot on btm at 2670', regain circulation. Mix LCM pills, pump & spot on bottom at 2670', had full returns. Trip out 8 stands & wait 3 hrs. TOH to 500'. TIH & tag btm @ 2950'. Pump LCM pill @									
	2950', had full returns during pumping operations. 7	ГОН to 1400'.			-	0			
	12/11/11 - TIH to 2550'. Mix & pump 60 bbl, 20 #/ @ 1637'. LD 10 joints. Drl cmt from 1637' to 2237		; #4 @	2550' w/ 200	sx cmt. WOC	C. TOH to 14	00'. TIH & tag		
	* Continued on attached sheet								
ç	Spud Date: 11/24/2011	Rig Release Da	te [	12/13/2011					
	Spud Date: 11/24/2011	Rig Release De		12/13/2011					
-									
I	I hereby certify that the information above is true and c	complete to the be	est of r	ny knowledge	and belief.				
S	SIGNATURE Lus Hunt		TITLE Regulatory Analyst			DATE/	10/2012		
	Fype or print name Lisa Hunt	_ E-mail address	: <u>lhur</u>	nt@celeroener	gy.com	_ PHONE: _(	432)686-1883		
_	For State Use Only			- Actual Barrenston	antida	i	AN 1 9 20	12	
	APPROVED BY:	_TITLEP	THE	LETIM ENOUT	WSF2F9;1	_DATE	AN 19 20	<del></del>	
	Jonations of Approval many					0.0			

WAN 2 3 2012

Rock Queen Unit #312 - C103 Continued

•

<u>12/12/11</u> - Drl cmt to 2500' then went into OH but did not lose circulation. TIH & tag @ 2802'. Trip out 4 stands. Circulate & condition mud.

<u>12/13/11</u> - LD DP & DC's. Ran 5 ½", 15.50#, J-55 csg & set @ 2775'. Cmt two stage cmt job as follows:  $1^{st}$  stage: 125 sx class C. Bump plug w/ 700# psi, release got ½ bbl back, floats held, dropped bomb, opened DV tool & circ 82 sx cmt off top of DV tool to surf. Circ 5 hrs prior to doing  $2^{nd}$  stage:  $2^{nd}$  stage: 450 sx Class C. Cmt job had full circ throughout job but did not circulate cmt to surf. Bump plug w/ 2070 psi released pressure, got ½ bbl back floats held. Set csg slips with 40k, nipple down stack.

12/14/11 - LD BOP, install tbg head & cap. Release rig at 09:30am on 12/13/11.