

Submit 1 Copy To Appropriate District Office
District I (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II (575) 748-1283
811 S. First St., Artesia, NM 88210
District III (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Minerals and Natural Resources
CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED
FEB 16 2012
HOBBS OCD

Form C-103
Revised August 1, 2011

WELL API NO 30-041-00244
5. Indicate Type of Lease STATE ☒ FEL ☒
6. State Oil & Gas Lease No
7. Lease Name or Unit Agreement Name Milnesand Unit
8. Well Number 163
9. OGRID Number 257420
10. Pool name or Wildcat Milnesand, San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DILPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator EOR Operating Company	
3. Address of Operator 200 N. Torame, STE 1440 Midland, TX 79701	
4. Well Location Unit Letter 1 1980 feet from the S line and 1980 feet from the E line Section 12 Township 08S Range 34E NMPM Roosevelt County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
DOWNHOLE COMMINGLE ☐			
OTHER ☐		OTHER ☐	

13. Describe proposed or completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15 7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion

EOR Operating requests approval to plug and abandon this well according to attached proposed procedure and wellbore diagram

EOR will notify OCD 24 hours prior to the beginning of plugging operations

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jana True TITLE Production Analyst DATE 1/20/12

Type or print name Jana True E-mail address: jtrue@enhancedoilres.com PHONE: 432-687-0303

For State Use Only

APPROVED BY Mary Brown TITLE Compliance Officer DATE 2/16/2012

Condition of Approval: The operator shall give 24 hour notice to the appropriate District office before work begins

FEB 16 2012



Plugging Procedure
Milnesand Unit #163
API No - 30-041-00244

1. Prepare location and test anchors
2. MIRU plugging rig
3. Notify OCD/BLM 24 hours prior to commencement of P & A procedure
4. NDWH/NU BOP
5. RIH w-4 1/2 CIBP on 2 3/8 WS @ 4500' (+/-) - within 100' of top perf - 4574'
a. Spot 35' of cement on CIBP **BY WIRELINE OR 25'sx's BY TBG.**
b. WOC - bump plug @ 4465' (+/-)
6. Load well with a minimum of 9 lb. mud and conduct MIT to 500 psi., test for leak off.
a. Bleed pressure off after MIT.
7. MIRU WL and RIH w/perf gun to 3000'
a. perforate @ 2 JSPF
b. POOH w/WL
c. RDWL
8. TIH w/WS - Squeeze 40 SX cement plug @ 3000' to 2900' (+/-)
a. Wait on cement
b. Tag plug @ 2900' or above.
9. MIRU WL and RIH w/perf gun to 1500'
a. perforate @ 2 JSPF
b. POOH w/WL
c. RDWL
10. TIH w/WS - Squeeze 40 SX cement plug @ 1500' to 1400'
a. Wait on cement
b. Tag plug @ 1400' or above
11. MIRU WL and RIH w/perf gun to 400'
a. perforate @ 2 JSPF
b. POOH w/WL
c. RDWL
12. TIH w/WS - Squeeze 40 SX cement plug @ 400' to 300'
a. 8 5/8 csng. Shoe @ 350'
b. Wait on cement
c. Tag plug **300'**
13. TIH to tag plug @ ~~340'~~ **300'** or above
a. Perforate @ 60'
b. Squeeze 25 SX and circulate to surface to have solid plug from 60' to surface
14. RDMO Plugging Rig
a. Install P & A marker plate **P.C. AREA**
b. Cut off dead men
c. Remediate Location

