,										
Form 3160-5 UNITED STATES OCD-H6BBS CD (August 2007) DEPARTMENT OF THE INTERIOR					FORM APPROVED OMB No. 1004-0137 Expires July 31, 2010					
	EAU OF LAND MAN		MAD 0	<b>G</b> 2012	5. Lease Serial No. NM27508	<u>^</u>				
BUREAU OF LAND MANAGEMENT MAR <b>0 6</b> 2012 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such propose						6. If Indian, Allottee or Tribe Name N/A				
						Toomo	nt, Name and/or No.			
SUBMIT IN TRIPLICATE – Other instructions on page 2.					N/A					
1. Type of Well       Image: Oil Well     Image: Gas Well       Image: Oil Well     Image: Gas Well					8. Well Name and No. Wilder 28 Federal # 2H					
2. Name of Operator ConocoPhillips Company	-	9. API Well No. 30-025-40329								
3a. Address P O Box 51810 Midland, Tx 79710	3b. Phone No. <i>(incl</i> 432-688-6943	ude area code	e)	10. Field and Pool or Exploratory Area Wildcat Bone Spring						
4. Location of Well (Footage, Sec., T., R, M., or Survey Description) 330 FNL & 2160 FEL UL B of Section 28-26S-32E					11. Country or Parish, State Lea County, NM					
12. CHE0	CK THĖ APPROPRIATE BO	X(ES) TO INDICAT	E NATURE	OF NOTIC	E, REPORT OR OT	HER	DATA			
TYPE OF SUBMISSION	E OF ACT	· · · · · · · · · · · · · · · · · · ·								
	Acidıze			iction (Start/Resume)	Г	Water Shut-Off				
✓ Notice of Intent	Alter Casing	Deepen Fracture Tr	reat	=	amation Well Integrity					
Subsequent Report	Casing Repair	New Const	truction	Recor	omplete					
Subsequent Report	Change Plans	Plug and A	bandon	Temp	orarily Abandon	•	• •			
Final Abandonment Notice	Convert to Injection	Plug Back		Water Water	r Dısposal					
the proposal is to deepen direction Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for ConocoPhillips Company respectfu	work will be performed or proved operations. If the operati Abandonment Notices must or final inspection )	ovide the Bond No. o on results in a multip be filed only after all	n file with BI le completion requirements	LM/BIA. R or recompl , including	equired subsequent letion in a new inter reclamation, have be	reports val, a F	must be filed within 30 days form 3160-4 must be filed once			
	сч	Submit the pr alls@blm.gov reques	ressure we for 2 mont t thereafte	uis and c	ipon					
,			,	1						
14. I hereby certify that the foregoing is	true and correct. Name (Printe	d/Typed)								
Donna Williams		Title	Sr. Regul	atory Advis	sor					
Signature	Signature Date 02/22/2012									
	TE OFF	ICE USE		APPRUVLU						
Approved by										
			Title		,	Date	FEB 2 8 2012			

1 MAR 0 7 2012

	Title		Date	FEB 20	LUIL	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify				Chris	11/2118-	Ē
	Office	2	. ]	IS/ CIIIIS	VVGLET	
entitle the applicant to conduct operations thereon.	<i>[</i> *			FALL OF LAND	MANAGEME	<u>N</u> I
Title 18 U.S C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person k	nowingly and willfully to	make to any departme	ent or age	ency of the United	States any fals	e,
		· · L		Ontre		

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

## Notice of Intent Sundry 21-Feb-2011

Subject: Proposal to leave the top of cement on the production casing as it is and to continue with completion of the well and the process of placing it on production.

Wilder Federal 28 # 2H API # 30-024-40329

On Wilder Federal 28 # 2H, the top of cement on the 5-1/2" production casing is at approximately 7200' MD. Therefore the top of cement on this string is within the Delaware group and above the top of the Bone Spring horizon, but is below the 9-5/8" intermediate casing shoe.

Our well configuration is:

- Conductor: 20" set at 37 ft below ground level
- Surface Casing: 13-3/8" 54# BTC set at 780' MD and cemented to surface
- Intermediate Casing: 9-5/8" 40# L-80 BTC set at 4360' MD and cemented to surface
- 8-3/4" hole Kick Off Point = 8580' MD
- Horizontal Landed at 91.6 deg inclination at 10775 MD, 9301' TVD
- Lateral Drilled to 13584' MD, 9286' TVD
- Production Casing: 5-1/2" 17# P-110 BTC set at 13564' MD, 9286' TVD and cemented. We did not have full
  returns during the cement job and top of cement was found at 7200' MD via Cement Bond Log. The reason the
  top of cement on the Production Casing is at 7200' instead of being lapped back inside the 9-5/8" intermediate
  casing was because we experienced loss of circulation on the production casing cement job.

Current Status: The fracture stimulation for this well has been performed. The fracture stimulation was ten stages. The first stage was pumped on 13-Feb-2012, and the final (10<sup>th</sup>) stage was pumped on 17-Feb-2012. The well is currently shut-in waiting for the fracture stimulation to heal / dewater.

We propose a revision to our approved program for this well as follows:

- 1. We propose to leave the top of cement on the production casing as it is at approximately 7200', and to continue with completion of the well and the process of placing it on production.
- 2. We propose to monitor the pressure on the production casing x intermediate casing annulus on a once per week basis. Recently the pressure on this annulus was 80 psi.
- If the pressure on the production casing x intermediate casing annulus shows evidence of communication with any water injection well or other well or gives other indications of a problem, we will report it to the BLM and propose a course of action to address the problem.

Our reasons for this proposal are as follows:

- We plan to put the well on gas lift and we are concerned that perforating the production casing in order to circulate in a cement job to tie the top of cement back into the intermediate casing may result in an inadequate or unreliable seal for the planned gas lift operations.
- We have considered the possibility of pumping a braden head squeeze, but we feel that a braden head squeeze would leave a gap between the top of cement on the original job and the bottom of cement that would occur from the braden head squeeze and we are concerned that having such a gap may complicate any future remediation that might be needed.
- We do not think that any damage would occur from leaving the top of cement where it is.

Steven O. Moore Chief Drilling Engineer - Mid-Continent Business Unit ConocoPhillips Company Phone 832 486 2459 Cell Phone 281 467 7596