Submit 1 Copy To Appropriate District State of New Me	xico Form C-103 ral Resources Revised August 1, 2011
Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	WELL AITNO.
District II - (575) 748-1283 811 S. Furst St., Artesia, NM 88210 R 0 9 2012 OIL CONSERVATION District III - (505) 334-6178 APR 0 9 2012 1220 South St. Fran	DIVISION 30-025-26518 5. Indicate Type of Lease
1000 Dia Dragos Dd. Artos: NM 97410	STATE THE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NECEIVED 87505	505 6. State Oil & Gás Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	G BACK TO A7. Lease Name or Unit Agreement Name East Vacuum GB-SA UnitR SUCHTract 3202
PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other Injection	8. Well Number 009
2. Name of Operator ConocoPhillips Company	9. OGRID Number 217817
3. Address of Operator <sub>3300 N</sub> "A" St	10. Pool name or Wildcat '
. Midland, TX 79705	Vacuum; Grayburg-San Andres
4. Well Location	
Unit Letter O: 175feet from the Southline and 1650feet from the EastlineSection 32Township 17SRange 35ENMPMCounty LEA	
Section 32 Township 17S Range 35E Town W   11. Elevation (Show whether DR. RKB, RT, GR, etc.) 11. Elevation (Show whether DR. RKB, RT, GR, etc.)	
3956' GR	
12. Check Appropriate Box to Indicate Na	ature of Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🔄 PLUG AND ABANDON 🗌	REMEDIAL WORK
TEMPORARILY ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS	
OTHER: X	Per Underground Injection Control Program Manual 11.6 C Packer shall be set within or less than 100
13. Describe proposed or completed operations. (Clearly state all p feet of the uppermost injection perfs or open hole.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.	
Job proposal is to locate and repair leak, causing pressure on the production casing. Notify NMOCD prior to	
RU on well. RU WSU, NDWH, NUBOP, RU wireline and run and set 1.875 plug in F profile nipple. Test tubing and on/off toot to 1000 psi, if leak is not detected, then RU pump truck to casing and	
pressure test casing/packer to 550 psi to verify possible casing leak. It should be noted that in Feb 2007	
while cleaning out to 4453 that the casing could possible be collapsed. Once the leaking component has been identified, insure well is dead, if tubing leak, unlatch from on/off tool and pull tubing out of hole. If	
packer leak, pull tubing out of hole w/packer, lay tubing down, repair or replace packer, inspect liner. MI 2 7/8 work string and tally,	
TIH with bit to 4453', and clean out if needed. TOOH laying down workstring and bit, Pickup injection tubing, on/off tool and packer RIH and set at current depth <u>+/- 4290'</u> . Test tubing GIH. Note: Packer need to be set as close to 100' above the top perf as possible.	
RU and test packer/packer to 550 psi, if test ok, unlatch from on/off tool and circulate packer fluid. Latch back on to on/off tool and	
test with chart recorder. Use 1000 psi chart, test at 550 psi for 30 mins. Notify NMOCD of test, give chart to Production Specialist. RU and pump 2000 gals	
Spud Date: Rig Release Da	te
I hereby certify that the information above is true and complete to the be	st of my knowledge and belief.
i $i$ $i$ $i$ $i$ $i$ $i$ $i$ $i$ $i$	
SIGNATURE Concernitien DATE_04/04/2012	
Type or print name <u>Rhonda Rogers</u> E-mail address: <u>rogerrs@conocophillips.com</u> PHONE: <u>(432)688-9174</u>	
Condition of Approval: The operator shall give 24 hour notice to the appropriate District office before work begins office 24 hours prior to running MIT Test & Chart PR 1 0 2012	
	24 hours prior to running MIT Test & Chart

Ø