Office State of New Mexico	Form C-103
District L. Energy, Minerals and Natural Resources	June 19, 2008
1625 N French Dr., Hobbs, NM 88240 HOBBS OCD DISTRICT II	WELL API NO. 30-025-12191
1201 W. C. TA A. NY 100210 UII UUNNEK VALIUN DI VINIUN	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 8741APR 1 9 2012 1220 South St. Francis Dr. District IV Santa Fe, NM 87505	STATE STEE
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr , Santa Fe, NM	
SUNDRY NO PICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name of Other Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Amoco State S
PROPOSALS.) 1. Type of Well: Oil Well	8. Well Number 3
2. Name of Operator	9. OGRID Number 012024
John H. Hendrix Corporation	
3. Address of Operator	10. Pool name or Wildcat DHC – HOB - 0475
P. O. Box 3040, Midland, TX 79702-3040	BDAS, Blinebry, Tubb
4. Well Location	
Unit LetterE :1980feet from theNorth line and	_660feet from theWestline
Section 32 Township 22S Range 38E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, et	c.)
3373' DF	
10 Cl 1 A	D of D
12. Check Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	
	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	
DOWNHOLE COMMINGLE	-
OTHER: DHC E	Blinebry, Tubb and BDAS
13. Describe proposed or completed operations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions:	nd give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC 	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 658 	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Ind Tubb zone w/9 shots. GIH w/tbg and pkr.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 656 Mar 26: Swab dry. POOH w/pkr and RBP. 	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Ind Tubb zone w/9 shots. GIH w/tbg and pkr.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 656 Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. 	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Ind Tubb zone w/9 shots. GIH w/tbg and pkr.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 656 Mar 26: Swab dry. POOH w/pkr and RBP. 	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Ind Tubb zone w/9 shots. GIH w/tbg and pkr.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 656 Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. 	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Ind Tubb zone w/9 shots. GIH w/tbg and pkr.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 656 Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. 	Attach wellbore diagram of proposed completion Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. and Tubb zone w/9 shots. GIH w/tbg and pkr. ISIP 0#.Let set ON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 659 Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. 	Attach wellbore diagram of proposed completion Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. and Tubb zone w/9 shots. GIH w/tbg and pkr. ISIP 0#.Let set ON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 659 Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. 	Attach wellbore diagram of proposed completion Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. and Tubb zone w/9 shots. GIH w/tbg and pkr. ISIP 0#.Let set ON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 65a Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475: Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D 	Attach wellbore diagram of proposed completion Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. and Tubb zone w/9 shots. GIH w/tbg and pkr. ISIP 0#.Let set ON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 659 Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. 	Attach wellbore diagram of proposed completion Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. and Tubb zone w/9 shots. GIH w/tbg and pkr. ISIP 0#.Let set ON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 65a Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475: Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D 	Attach wellbore diagram of proposed completion Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. and Tubb zone w/9 shots. GIH w/tbg and pkr. ISIP 0#.Let set ON.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 656 Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475; Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D Spud Date: Rig Release Date:	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Ind Tubb zone w/9 shots. GIH w/tbg and pkr. I ISIP 0#.Let set ON.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 65a Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475: Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D 	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Ind Tubb zone w/9 shots. GIH w/tbg and pkr. I ISIP 0#.Let set ON.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 656 Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475: Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D Spud Date: Rig Release Date:	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Id Tubb zone w/9 shots. GIH w/tbg and pkr. If ISIP 0#.Let set ON.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 656 Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475; Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D Spud Date: Rig Release Date:	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Ind Tubb zone w/9 shots. GIH w/tbg and pkr. I ISIP 0#.Let set ON.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 65: Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475: Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled. SIGNATURE And And Anguer Title Engineer	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Id Tubb zone w/9 shots. GIH w/tbg and pkr. I ISIP 0#.Let set ON. I Isip 0#.Let set ON. I Isip 0#.Let set ON.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 65; Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475: Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Academy Academy Academy TILE Engineer Type or print name Carolyn Doran Haynes E-mail address: cdoranhayne	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Id Tubb zone w/9 shots. GIH w/tbg and pkr. I ISIP 0#.Let set ON. I Isip 0#.Let set ON. I Isip 0#.Let set ON.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 65: Mar 26: Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475; Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Approximately Approximately Approximately Engineer Type or print name . Carolyn Doran Haynes . E-mail address; cdoranhayne For State Use Only	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Ind Tubb zone w/9 shots. GIH w/tbg and pkr. I ISIP 0#.Let set ON. I Isip 0#.Let set ON.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Mar 20-22: POOH, GIH w/ pkr and set @ 6254'. Acidize Drinkard w/2000 gal 15% HC Mar 23: GH w/ RBP and pkr. Set RBP @ 6300'. Test ok. Mar 24: Spot 1500 gal 15% HCl nefe. POOH. Perforate Blinebry zone w/22 shots ar Set pkr @ 5395'. Acidize w/3000 gal 15% HCl nefe. 3.5-5 bpm. PMax, 65s Swab dry. POOH w/pkr and RBP. Mar 27: GIH w/production tbg to 6510'. Swab EFL @ 6210'. Mar 28: GIH w/pump and rods. Hang on. Load tbg. RDMO. This well is now DHC – HOB – 0475: Blinebry Oil & Gas, Tubb Oil & Gas, Brunson D Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE August Data August TILE Engineer Type or print name Carolyn Doran Haynes . E-mail address: cdoranhayne For State Use Only	Attach wellbore diagram of proposed completion I nefe. Let set ON. Swab back. POOH. Id Tubb zone w/9 shots. GIH w/tbg and pkr. I ISIP 0#.Let set ON.