Submit-4 Copy To Appropriate District State of New Mex	kico Form C-103							
Office District I – (575) 393-6161 Energy, Minerals and Natur	al Resources Revised August 1, 2011 WELL API NO.							
1625 N French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283 811 S First St., Artesia, NM 88240BBS OCD OIL CONSERVATION	DIVISION 30-025-38555							
<u>District III</u> ~ (505) 334-6178 1220 South St. France	aid \mathred \tau \tau \tau \tau \tau \tau \tau \tau							
1000 Rio Brazos Rd , Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 MAY 1 0 2012 Santa Fe, NM 87.	STATE TEE							
1220 S St. Francis Dr , Santa Fe, NM 87505								
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name							
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FO								
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INJECTION								
	8. Well Number 145							
2. Name of Operator CHEVRON U.S.A. INC.	9. OGRID Number 4323							
3. Address of Operator	10. Pool name or Wildcat							
15 SMITH ROAD, MIDLAND, TEXAS 79705	VACUUM GRAYBURG SAN ANDRES							
4. Well Location								
Unit Letter C: 1286 feet from the NORTH line and 1831 feet from the WEST line Section 2 Township 18-S Range 34-E NMPM County LEA								
11. Elevation (Show whether DR,								
· · · · · · · · · · · · · · · · · · ·								
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data								
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □	REMEDIA! WORKER TO UNIT REPORT OF THE REMEDIA! WORKER TO UNIT REPORT OF THE REMEDIA!							
TEMPORARILY ABANDON	COMMENCE CENTRAL COMMENCE COMM							
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB [] feet of the uppermost injection perfs or open hole.							
DOWNHOLE COMMINGLE	reet of the appermost injection peris or open noie.							
OTHER: CLEAN OUT & STIMULATE	OTHER							
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date								
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.								
CHEVRON U.S.A. INC. INTENDS TO CLEAN OUT & STIMULA	ATE THE SUBJECT WELL							
PLEASE FIND ATTACHED, THE INTENDED PROCEDURE, WELLBORE DIAGRAM; & C-144 INFORMATION. The Oil Conservation Division Condition of Approval: notify								
MUST BE NOTIFIED 24 Hours OCD Hobbs office 24 hours								
Spud Date: 'rior to the beginning of operations Rig Release Date								
Spud Date.	prior of running MIT Test & Chart							
<u> </u>	· ·							
I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
$Q_{ij} = Q_{ij} = Q_{ij}$								
SIGNATURE YOU'SE JAKEL TON TITLE: REGULATORY SPECIALIST DATE: 05-09-2012								
Type or print name: DENISE PINKERTON E-mail address: leakejd@chevron.com PHONE: 432-687-7375								
APPROVED BY: Somewhat TITLE STATE MAJE DATES-10-2012								
Conditions of Approval (if any):								

Well:

VGSAU No. 145

Field:

Vacuum (Grayburg-San Andres) Field

API No .:

30-025-38555

Lea County, New Mexico

Description of work: CT CO from top of fill @ 4,488' to 4,915', pump xylené across perfs from 4,520' - 4,790'. Dump acid. RTI.

Coiled Tubing Unit is to only be on the injector for 1 day regardless of CO depth reached. Allow enough time to complete steps 10-12, and move CT unit to next injector.

Pre-Job Work:

- Check location, anchors (if they haven't been tested in the last 24 months, retest) and any overhead electrical lines (possible variance needed)
- Set water supply tanks and flow back tanks prior to job
- Have fluid transportation trucks on location to bring in / haul off fluid
- Manifold rated and tested to BOP working pressure:
- Man lift on location for use as needed

Procedure:

- 1. MIRU coiled tubing unit w/ 1.25" coil.
- 2. Dress the tubing end and install the coiled tubing connector. Use testing tool to pull test / pressure test the connector. Test low (200 psi, 5 minutes) and then high (working pressure of BOP system, 10 minutes) pressure.
- 3. Perform a surface function test on the down hole tools (hip trippers and motors):
- Before equalizing pressures with the wellbore, the BOP, riser, stripper head, and surface connection are to be tested. Anything below the BOP is to be low (200 psi, 5 minutes) / high (working pressure of BOP system, 10 minutes) tested. Above the BOP (lubricator and stripper head) are to be tested to the rates working pressure of the stripper head.
- 5. Open well and RIH with hip tripper.
- 6. Slow to 20'/min when within 200' of PN/packer (packer set at 4,458') and continue at reduced speed while below the end of tubing.
- Once the tubing has been exited, 'take a bite' into the production casing (enter casing and then pull back into the upper tubing section), and continue to do this in increments during the CO.
- 8: Clean out fill from 4,488' to 4,915'...
- 9. Circulate hole clean with 125% of annular volume.
- 10. Begin pumping xylene. Wash over perforations from 4,790' 4,520', from bottom-up with 850 gals xylene at a maximum bottom-hole rate of 1 BPM and a maximum surface

Well:

VGSAU No. 145

Field:

Vacuum (Grayburg-San Andres) Field

API No.:

30-025-38555 Lea County, New Mexico

> pressure of 5000 psi (do not exceed equipment maximum rated working pressure), Displace xylene.

- 11. POOH and continue to circulate.
- RDMO coiled tubing unit. 12.
- Shut in overnight. 13.
- Flow back to tanks. Catch samples when well starts to flow back, after one volume of 14. tubing has been displaced, and after 2 volumes of tubing have been displaced. Send samples in for analysis.
- Pump 165 gals of WOC-603 (Baker solvent), neat. Flush with 1,050 gals fresh water: Let 15. stand 15 minutes.
- 16. Pump 6:000 gals of acid down injection tubing. Shut in for one hour to allow acid to spend.
- 17. Flow back to tank.
- Return well to injection. Report injection rates, choke sizes and injection pressures. 18.

RRW 4/10/2012

Contacts:

(432-687-7650 / Cell: 432-208-4772) Remedial Engineer - Larry Birkelbach Production Engineer - Paul Brown (432-687-7351 / Cell: 432-238-8755) (432-687-7452 / Cell: 281-460-9143) Production Engineer - Ryan Warmke (Cell: 575-631-9033) ALCR - Danny Acosta (432-687-7402 / Cell: 432-238-3667) D&C Ops Manager - Boyd Schaneman D&C Supt. - Heath Lynch (432-687-7857 / Cell: 281-685-6188) OS - Nick Moschetti (Cell: 432-631-0646)

VGSAU 145 Wellbore Diagram

Created: Updated: Lease: Field: Surf. Loc.: Bot, Loc.: County: Status:	Vacuum C	By: By: Brayburg San Grayburg San FNL & 1831' F St.: _ Injector	Andres			Well.#: API Unit Ltr.: TSHP/Rng: Unit Ltr:: TSHP/Rng: Directions: CHEVNO: OGRID:	145 30-025-3855 C S-18 E-34	St. Lse: _ 55 Section: _ Section: _ Buckeye, N LA7426 4323		
Production of Size: Wt., Grd:: Depth: Sxs Cmt: Circulate: TOC: Hole Size: Tubing: 2-3/8" fiberli 4" nickel-pla Perfs: 4520 Perf details 4520-24,45; 4582-88, 45 4616-4620, 4684-4694;	8 5/8" 24#, J-55 1630' 990 297 sx Surface 12 1/4" /2" 33 jts down 15-1/2" 12 jts. Casing 5:1/2" 17#, J-55 5006' 1,100 130 sx Surface 7 7/8" ine tbg, ted sub 0-4790' 28-30,4534-36, 96-4610, 4622-4624, 465 4698-4717', 40-48, 4752-62	2-4666,	-74,				History: 3/3/09 Initial 24,4528-30,4 74,4582-88,4 4620,4622-46 15% HCL. Pe 4694, 4698-4 15% HCL. Pe 4752-62, 476 Pump 4500 g	534-36, 454 4596-4610,4 524, Pump 5 erf 4652-466 717: Pump erf 4726-32, 0-68, 4770-7 jals 15% HC	2-56,4568- 616- 500 gals 6,4684- 3500 gals 4740-48, 78,4782-90.	
PBTD: 4915' TD: 5006'										