Submit 1 Copy To Appropriate District	To Appropriate District State of New Mexico		Form C-103
Office			Revised August 1, 2011
			WELL API NO. 30-025-22794
			5. Indicate Type of Lease
1000 Bio Brotros Bd. Artee NM 974 MAL 2/112 1200 South St. Thanking Dit			STATE FEE
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name MIDWAY STATE
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			MIDWAYSIAIE
PROPOSALS.) 1. Type of Well: Oil Well Image: Second			8. Well Number 1
2. Name of Operator			9. OGRID Number 241333
CHEVRON MIDCONTINENT, L.P.			10. Pool name or Wildcat
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705			LOVINGTON; DEVONIAN
4. Well Location			
Unit Letter F: 2310 feet from the NORTH line and 2310 feet from the WEST line			
Section 12 Township 17-S Range 36-E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSE			SEQUENT REPORT OF: K
			— — —
PULL OR ALTER CASING I MULTIPLE COMPL CASING/CEMEN			—
OTHER: INTENT TO ADD PERFS & ACIDIZE OTHER			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
CHEVRON MIDCONTINENT, L.P. INTENDS TO ADD PERFS IN THE DEVONIAN AND ACIDIZE THE SUBJECT WELL.			
PLEASE FIND ATTACHED, THE INTENDED PROCEDURE, WELLBORE DIAGRAM, & C-144 INFORMATION.			
Spud Date:	Rig Release Da	ate:	
			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE MASS HIN FOR TITLE: REGULATORY SPECIALIST DATE 05-10-2012			
Type or print name: DENISE PINKERTON E-mail address: leakejd@chevron.com PHONE: 432-687-7375			
APPROVED BE THE SALANGE DATES-14-2012			
Conditions of Approval (if any):			

~

• •

Description of work: Set CIBP at 11,461'. Perforated and acidized from 11,320' - 11,330', and swab test.

- Caliper all handling tool daily or when sizes change and note in JSA & TGSM.
- Check location, anchors (if they haven't been tested in the last 24 months, retest) and any overhead electrical lines (possible variance needed)

Procedure:

- 1. Rig up pulling unit. Check wellhead pressure, and kill well as necessary. Drop bar on ESP drain valve.
- ND wellhead. NU 5,000 psi BOP with 2-3/8" pipe rams over blinds with hydrill on top. POOH with 1 joint of tubing, cut cable and band to tbg, install 5 ½" pkr, RIH with 1 joint of tubing and 5-1/2" packer. Set packer. Test BOP to 500 psi high / 250 psi low.
- 3. Rig up cable spooler and TOH with 2-3/8" production tubing and ESP. Send pump to Centrilift to salvage parts.
- 4. TIH with 2-3/8" work string w/ 4-5/8" MTB to 11,470'. POH.
- 5. Rig up wireline truck and set CIBP at 11,461'. Get on depth with Schlumberger -Perforating Depth Control log dated 12/21/1968 (copy attached). RU Lubricator, close blind rams and test lubricator to 500 psi. RIH with 3-3/8" Gunslinger. Perforate the 5-1/2" casing with 2 JSPF (90 degree phasing) as follows:

11,320' - 11,330' (20 total holes)

- 6. POOH with perforating gun.
- 7. RIH with wireline set RBP (tubing retrieve) and set at 11,340'.
- 8. Rig down wireline truck. Prepare to acid stimulate.
- 9. RIH with 5-1/2" treating packer and retrieving head for RBP on 2-3/8" workstring. Test tubing to 6,000 psi below slips while RIH.
- 10. Test RBP to 500 psi with packer. PU and set packer at 11,220'.
- 11. Acidize Devonian perfs from 11,320 11,330' with 2,000 gal 15% HCL. Divert using 30, 1.2 SG 7/8" bio-balls and spread evenly throughout the job. Pump acid at 2-4 BPM. Max Pressure = 6,000 psi. Displace acid with FW to bottom perf at 11,330'. Monitor casing pressure for communication around packer.
- 12. Shut-in for 2 hours to allow acid to spend and bio-balls to break.
- 13. Flow or swab load back monitoring fluid entry and oil cut.
- 14. Release packer and RIH to release RBP. POOH with packer and RPB. Lay down RBP.

Page 1 of 2

- 15. RIH with 5-1/2" packer on 2-3/8" workstring and swab well for one day and report back fluid volumes recovered for ESP sizing. Release packer and POOH with packer and workstring.
- 16. PU and RIH with tubing and downhole equipment. RIH with test sub-pump. RD BOP and install WH.
- 17. Put on production and test.

RRW 3/6/2012

Contacts:

Remedial Engineer – Larry Birkelbach Production Engineer – Ryan Warmke ALCR – Danny Acosta D&C Ops Manager – Boyd Schaneman D&C Supt. – Heath Lynch OS – Nick Moschetti Baker Hughes Rep – Doug Lunsford (432-687-7650 / Cell: 432-208-4772) (432-687-7452 / Cell: 281-460-9143) (Cell: 575-631-9033) (432-687-7402 / Cell: 432-238-3667) (432-687-7857 / Cell: 281-685-6188) (Cell: 432-631-0646) (432-570-1050 / Cell: 432-559-0396)

Midway State No. 1 Wellbore Diagram

÷

.



١