

Submit 1 Copy To Appropriate District Office:
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised August 1, 2011

JUN 06 2012

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

WELL API NO.
30-041-00031

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Milnesand Unit

8. Well Number 124

9. OGRID Number
257420

10. Pool name or Wildcat
Milnesand-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

EOR Operating Company

3. Address of Operator

200 N. Lorraine, STE 1440 Midland, TX 79701

4. Well Location

Unit Letter K 1980 feet from the S line and 1980 feet from the W line
Section 7 Township 08S Range 35E NMPM County Roosevelt

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPS ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

EOR Operating Company requests approval to plug and abandon this well according to the attached proposed procedure and wellbore diagram.

EOR Operating will contact OCD 24 hours prior to the beginning of plugging operations.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Jana True

TITLE Regulatory Mgr.

DATE 6/6/12

Type or print name Jana True

E-mail address: jtrue@enhancedoilres.com PHONE: 432-687-0303

For State Use Only

APPROVED BY:

Mary Brown

TITLE

Compliance Officer

DATE

6/6/2012

Conditions of Approval (if any):

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS

JUN 07 2012

Chm



Plugging Procedure
Milnesand Unit #124
API No. - 30-041-00031

1. Prepare location and test anchors
2. MIRU plugging rig
3. Notify OGD/BLM 24 hours prior to commencement of P & A procedure.
4. NDWH/NU-BOP
5. RIH w/ 4 1/2 CIBP on 2 3/8 WS @ 4500' (+/-) - within 100' of top perf - 4596'
 - a. Spot 35' of cement on CIBP **by w.l. OR 25 SKS by Tbg.**
 - b. WOC - bump plug @ 4465' (+/-)
6. Load well with a minimum of 9 lb. mud and conduct MIT to 500 psi; test for leak off.
 - a. Bleed pressure off after MIT
7. MIRU WL and RIH w/perf gun to 3465'
 - a. perforate @ 2 JSPF
 - b. POOH w/WL
 - c. RDWL
8. TIH w/WS - Squeeze 40 SX cement plug @ 3465' to 3365' (+/-)
 - a. Wait on cement
 - b. Tag plug @ 3365' or above.
9. MIRU WL and RIH w/perf gun to 2465' **2600'**
 - a. perforate @ 2 JSPF
 - b. POOH w/WL
 - c. RDWL
10. TIH w/WS - Squeeze 40 SX cement plug @ 2465' to 2365' **2600' - 2500'**
 - a. Wait on cement
 - b. Tag plug @ 2365' or above
11. MIRU WL and RIH w/perf gun to 1465' **2150'**
 - a. perforate @ 2 JSPF
 - b. POOH w/WL
 - c. RDWL
12. TIH w/WS - Squeeze 40 SX cement plug @ 1465' to 1365' **2150' - 2050'**
 - a. Wait on cement
 - b. Tag plug @ 1365' or above
13. MIRU WL and RIH w/perf gun to 380'
 - a. 8 5/8 csg. Shoe @ 352'
 - b. perforate @ 2 JSPF
 - c. POOH w/WL
 - d. RDWL
14. TIH w/WS - Squeeze 40 SX cement plug @ 380' to 280'
 - a. Wait on cement
 - b. Tag plug
15. TIH to tag plug @ 280' or above
 - a. Perforate @ 60'
 - b. Squeeze 25 SX and circulate to surface to have solid plug from 60' to surface
16. RDMO Plugging Rig
 - a. Install P & A marker plate
 - b. Cut off dead men **→ P. CHICKEN AREA**
 - c. Remediate Location

