Submit 1 Copy To Appropriate District Office	State of New Mexico				Form C-103
District 1 - (575) 393-6161	Energy, Minerals and Natural Resources			WELL API NO.	Revised August 1, 2011
1625 N French Dr , Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION			30-025-05293	Ŷ
811 S. Fust St., Artesta, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.			5. Indicate Type of L	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fc, NM 87505			6. State Oil & Gas L	FEE X
<u>District IV</u> – (505) 476-3460 1220 S St Francis Dr., Santa Fe, NM				18164	
87505 SUNDRY NOTICE	S AND REPORTS ON	WELLS		7. Lease Name or Ur	it Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Deuse Hume of Of	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Denton	
	Gas Well Other HOBBS OCD			8. Well Number	6
2. Name of Operator Fasken Oil and Ranch, Ltd.	۰ ۲	16111 m -		9. OGRID Number 151416	
3. Address of Operator	JUN 1 5 2012			10. Pool name or Wi	Idcat
303 W. Wall Ave., Suite 1800, Midla	nd, Tx. 79701 🔒	Tx. 79701		Denton; Devonian	
4. Well Location C		RECE	VED		
Unit Letter: 659			line and198		
Section 11	Township 15	0			ounty Lea
	 Elevation (Show whet 3797' GR 	ther DR, RI	<i>KB</i> , <i>RT</i> , <i>GR</i> , etc.,		
KUNEDICATE ALL AND SAVEN SEEL ALL ALL ALL ALL ALL ALL ALL ALL ALL		··· ·		Managara Managaran	
12. Check Ap	propriate Box to Indi	icate Natu	re of Notice,	Report or Other Da	ta
		1			
			SUB EMEDIAL WOR		TERING CASING
	CHANGE PLANS				
	MULTIPLE COMPL		ASING/CEMEN	т јов 🔲	
OTHER [.]			THER:		
13. Describe proposed or complete					
of starting any proposed work) proposed completion or recom		INMAC. I	For Multiple Cor	npletions: Attach wellt	ore diagram of
Fasken Oil and Ranch, Ltd. Proposes to Plug and abandon wellbore diagrams.	Plug and Abandon the De	enton No. 6	. Please see atta	iched procedure and cu	rrent and proposed
They and adardon wenebore diagrams.					
				···	
Spud Date:	Rig Rel	lease Date:			
I hereby certify that the information abo	we is true and complete t	to the best of	of my knowledge	e and belief.	
110					
SIGNATURE Stanse	TITLE_	Workover a	and Completion	Superintendent_DATE	06/14/12
SIJE			1 0 -		
Type or print name:) tephen Frag	oso E-mail	address:	stevet@forl.	COM PHON	Е: <u>(432) 687-177</u>
$=$ M_{1} γ	K	Com	pliance	Streer.	6/15/2012
APPROVED BY: Y afey	ANOUT LAITLE		F	DATE	
Conditions of Approval (if any):					
Ű					

DENTON NO. 6 P&A Wellbore A.F.E. No. 2435

KB: 15' above GL TD: 12,700', PBTD: 12390' Casing: 13-3/8"@349' TOC circulated 8-5/8" @ 4650' TOC circulated 5-1/2" 15.5-20#/ft @ 12,700' cemented with 300 sxs DV tool @ 8915' cemented with 885 sxs. TOC @ 1750' from surface. Perfs: 11,559'-11,556', 11,570'-11,577', 11,583'-11,590', 11,616'-11,630', 11,669'-11,676', 11,720'-11,746', 11,780'-11,796', 11,818'-11,837', 12,085'-12,110', 12,130'-12,140'. Perforations 12,200'-12,240'. Perforations 12,500'-12,600' Plugged with 70 sxs. Cement on top of Baker Model D at 12.470' NOTE: Top of 2-7/8" tubing fish at 10,080'. Junk 4-5/8" mill, bit sub and partial hydraulic jar body 10,152'. Junk RBP without mandrel at 10,160'. RBP Mandrel with bull plug on top of Model "D" packer at 12,170'. Baker Model 415 "D" packer at 12,170' with seal assembly and 2 its bull plugged tail pipe. 70 sx cement from 12,390'-12,470'. Baker Model 415 "D" packer at 12,470'.

- 1. Notify NMOCD of intent to plug and abandon. Confirm with Kim Tyson that pit permits have been obtained.
- 2. RIW with 2-7/8" perforated sub and tubing and tag 2-7/8" tubing fish at 10,080' and spot 50 sx Class "H" neat cement (s.w. 16.4 ppg, yield 1.13 cuft/sk) to 10,048' and displace with fresh water. POW to 8000' and WOC 4 hrs and tag cement at 9650'.
- 3. RIW and tag TOC and displace well with 9.5 ppg mud laden brine water to 4000'. Mix and spot 40 sx Class "H" cement (s.w. 16.4 ppg, yield 1.13 cuft/sk) from 9100' to 8755'. POW to 7600' and WOC 4 hrs and tag plug.
- 4. POW to 6190' and spot 25 sx Class "C" cement (s.w. 14.8 ppg, yield 1.32 cuft/sk) with 2% CaCl2 from 6190' to 5937'. POW to 4000' and WOC 4 hrs and tag plug.
- 5. POW while laying down tubing to 4776' and spot 25 sx Class "C" cement (s.w. 14.8 ppg, yield 1.32 cuft/sk) with 2% CaCl2 from 4776' to 4524'. POW to 4400' and WOC for 4 hrs and tag plug.
- 6. Displace well with 9.5 ppg mud laden brine water to 400' and POW to 1800' while laying down remainder of tubing.
- 7. Spot 25 sx Class "C" cement (s.w. 14.8 ppg, yield 1.32 cuft/sk) with 2% CaCl2 from 1800' to 1535' and POW while laying down all tubing.
- 8. RUWL and RIW and shoot 4 squeeze holes at 400'. POW and RDWL.
- 9. RIW with AD-1 tension packer and tubing to 30' and circulate 100 sx Class "C" cement (s.w. 14.8 ppg, yield 1.32 cuft/sk) with 2% CaCl2 and displace cement to 30'.
- 10. Release packer and POW with tubing and packer.
- 11. RIW with tubing to 30' and fill casing with Class "C" cement (s.w. 14.8 ppg, yield 1.32 cuft/sk) to surface. RDPU and release all rental equipment.
- 12. Dig out and cut off wellheads, cap casing and install dry-hole marker. Dig out and cut off mast anchors and clean and level location.

