State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 5-27-2004

HOBBS OCD OIL CONSERVATION DIVISION FILE IN TRIPLICATE WELL API NO DISTRICT I 1220 South St. Francis Dr. 1625 N French Dr , Hobbs, NM 88240 30-025-07364 Santa Fe, NM 87505 5 Indicate Type of Lease 1301 W Grand Ave, Artesia, NM 88210 6 0 2 2012 STATE FEE X 6 State Oil & Gas Lease No DISTRICT_III 1000 RIO Brazos Rd, Aztec, NM 87410 7 Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs (G/SA) Unit DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 19 1 Type of Well 8 Well No. Oil Well Gas Well Other Temporarily Abandoned 241 9. OGRID No 157984 2 Name of Operator Occidental Permian Ltd. 10 Pool name or Wildcat 3 Address of Operator Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4 Well Location Unit Letter N Feet From The Line . 330 Feet From The South 2310 West Section 19 Townshin 18-S Range 38-E NMPM County Lea 11 Elevation (Show whether DF, RKB, RT GR, etc.) 3661' DF Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well Distance from nearest surface water Pit Type ____ Depth of Ground Water Below-Grade Tank: Volume _____ bbls; Construction Material Pit Liner Thickness mil Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. **PLUG & ABANDONMENT** CASING TEST AND CEMENT JOB PULL OR ALTER CASING **Multiple Completion** OTHER: OTHER: Casing repair/TA status request 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU. 2. Pressure tested 7" casing, water coming out of intermediate valve. This Approval of Temporary ND WH, function test BOP (good), NU BOP. 3. Abandonment Expires 6-14-2016 4. RIH w/2-7/8" tbg to 1368'. Set 7" test packer @1368' 5. Pressure tested casing from 1368-3980' (good). Tested casing from 1368' to surface and leaked between 22' & 28'. Layed down 7" test packer. 6. RIH w/cable tool. Logged from 1000' to surface. 7. 8 Set RBP @1000'. POOH w/2-7/8" tubing and retrieving head. ND BOP. 9. RIH w/7" spear. POOH w/13' of 7" casing. Unable to back off csg. POOH w/spear. 10. RIH w/packer @15'. Pressure tested csg from 13' to 1000' (RP) 540 PSI (good). POOH w/7" test packer. 11. RIH w/8-1/2" conventional shoe. Wash over 7" casing from 14-18'. POOH w/shoe. ***see attached sheet for additional data*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE หมา TITLE Administrative Associate DATE 07/31/2012 TYPE OR PRINT NAME Mendy E-mail address: TELEPHONE NO ohnson mendy johnson@oxy.com 806-592-6280 For State Use Only Det Mos DATE 5-2-2012 APPROVED BY TITLE . CONDITIONS OF APPROVAL IF ANY AUG 0 2 2012

NHU 19-241

- 12. Pressure tested 7" casing to 550 PSI. Lost 150 PSI in 30 minutes. RIH w/7" internal cutter, cut casing @24'.
- 13. RIH w/8-5/8" bowl over with rubber inside. Latched on and pulled w/30,000 #s of tension and tested to 580 PSI (good).
- 14. ND BOP, set 7" slips w/30,000#'s tension. Put 540 PSI with chart recorder and lost 5#'s.
- 15. Ran in hole w/retriever head, washed over sand, POOH w/RBP.
- Ran MIT,. RIH w/packer tested plug patch. Isolated leak found @2736-2768'. Pin pointed hole @2760-2768'. POOH w/packer. RIH w/CICR set @2668'.
- 17. Sting out of CICR. At 2668' spot cement to retainer. Sting in. Squeeze casing lea w/300 sx cement w/1200 PSI. Sting out. Reverse out 7 bbls cement.
- 18. RIH w/6-1/8" bit tagged @2666'. Drill on CICR @2666'-2668' and cement from 2668' to 2694'. Circ clean.
- 19. Continue drilling cement from 2694', fell out @2778'. POOH w/tubing.
- 20. ND BOP/NU wellhead.
- 21. Test casing to 535 PSI for 30 minutes and chart for the NMOCD. Mark Whitaker w/NMOCD on location for test.
- 22. RDPU & RU. Clean location. Well is TA'd.

RUPU 05/25/2012

RDPU 06/14/2012

4



Work Plan Report for Well:NHSAU 241-19

Survey Viewer



· · · · · ·