Calmid 2 Commer To A	_	~
Submit 3 Copies To Appropriate District Office State of New Me		C-103
Energy Minerals and Natu		27, 2004
1625 N French Dr., Hobbs, NM 88240 CD District II CONSEDVATION	WELL API NO.	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION	DIVISION 30-025-23082 5. Indicate Type of Lease	_
District III 1220 South St. Ever	ncis Dr. STATE FEE S	
1000 Rio Brazos Rd , Aztec, NM 87 AUG 09 2012 District IV Santa Fe, NM 87		
1220 S. St. Francis Dr., Santa Fe, NM 87505	685270	
SUNDRY NECENEEND REPORTS ON WELLS		lame:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU	G BACK TO A Skelly Penrose A Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	R SUCH	-
PROPOSALS.) 1. Type of Well: Oil Well ☐ Gas Well ☐ Other Injection	8. Well No. 61	,
2. Name of Operator	9. OGRID Number	
Legacy Reserves Operating LP	240974	
3. Address of Operator	10. Pool name or Wildcat	
PO Box 10848, Midland, TX 79702	Langlie Mattix; 7 Rvrs-Queen-C	rybg
4. Well Location		
Unit Letter F: 1900 feet from the North	line and 1870 feet from the West	line
	inge 37E NMPM County Lea	
11. Elevation (Show whether DR,	RKB, RT, GR, etc.)	14
3325	GR	a di di di
Pit or Below-grade Tank Application or Closure		
	fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Material	
12. Check Appropriate Box to Indicate Na	ture of Notice, Report or Other Data	
NOTICE OF INTENTION TO	CUROCCUENT DEPORT OF	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE BLANCE	REMEDIAL WORK ALTERING CASIN COMMENCE DRILLING OPNS. P AND A	IG ∐ ⊠
TEMPORARILY ABANDON	CASING/CEMENT JOB	
COMPLETION	O'NO INO O E IN ENTITO DE	
	1	
		_
OTHER:	OTHER:	
OTHER: 13. Describe proposed or completed operations. (Clearly state all perti	nent details, and give pertinent dates, including estimated	
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Com	nent details, and give pertinent dates, including estimated	
OTHER: 13. Describe proposed or completed operations. (Clearly state all perti starting any proposed work). SEE RULE 1103. For Multiple Comrecompletion.	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions	on or
OTHER: 13. Describe proposed or completed operations. (Clearly state all perti starting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 13. Operation of the proposed work of the pertinguished operation operation of the pertinguished operation of the pertinguished operation of the pertinguished operation operation of the pertinguished operation of the pertinguished operation of the pertinguished operation	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345	on or 6'.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 13. Operation of the state of the	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested of	on or 6'. asing
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 13. Operation of the proposed work of the pertistant of	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested color. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105	on or 6'. asing
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 15. MIRU plugging equipment. Dug out cellar. ND wellhead. 15. Circulated hole w/ mud laden fluid. Spotted 25 sx cement 15. 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-11. 15. Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345@ 3456-3088. POH w/ tbg to 2500'. Pressured tested of 030. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off.	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistanting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345@ 3456-3088. POH w/ tbg to 2500'. Pressured tested of 030. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off.	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 15. MIRU plugging equipment. Dug out cellar. ND wellhead. 15. Circulated hole w/ mud laden fluid. Spotted 25 sx cement 15. 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-11. 15. Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345@ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistanting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345@ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistanting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345@ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistanting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Illhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistanting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: Attach wellbore diagram of proposed completions: Attach wellbore diagram of proposed completions: NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested completions: POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging)	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistanting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Illhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistanting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Illhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistanting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Illhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistanting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Illhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under	on or 6'. asing 7.
OTHER: 13. Describe proposed or completed operations. (Clearly state all perti starting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we Removed deadmen. Cleaned location and moved off.	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Illhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.	on or 6'. easing 7. r.
OTHER: 13. Describe proposed or completed operations. (Clearly state all perti starting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we Removed deadmen. Cleaned location and moved off.	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Illhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.	on or 6'. easing 7. r.
OTHER: 13. Describe proposed or completed operations. (Clearly state all perti starting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we Removed deadmen. Cleaned location and moved off.	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: Attach wellbore diagram of tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested of 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.atate.nm.us/ocd. y knowledge and belief. I further certify that any pit or below-greeneral permit or an (attached) alternative OCD-approved place.	on or 6'. asing 7. r. rade tank an .
OTHER: 13. Describe proposed or completed operations. (Clearly state all perti starting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we Removed deadmen. Cleaned location and moved off.	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Illhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.	on or 6'. asing 7. r. rade tank an .
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we Removed deadmen. Cleaned location and moved off.	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: Attach wellbore on the well of the surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. y knowledge and belief. I further certify that any pit or below-greneral permit or an (attached) alternative OCD-approved plegulatory Tech DATE 08/08/2019	rade tank
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1- Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we Removed deadmen. Cleaned location and moved off. I hereby certify that the information above is true and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g SIGNATURE	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. NU BOP. RIH w/ workstring and tagged CIBP @ 345 @ 3456-3088. POH w/ tbg to 2500'. Pressured tested to 300. POH w/ tbg. ND BOP. WOC. Tagged plug @ 105 to surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. y knowledge and belief. I further certify that any pit or below-greeneral permit or an (attached) alternative OCD-approved plegulatory Tech DATE 08/08/201	rade tank
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we Removed deadmen. Cleaned location and moved off.	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: Attach wellbore on the well of the surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. y knowledge and belief. I further certify that any pit or below-greneral permit or an (attached) alternative OCD-approved plegulatory Tech DATE 08/08/2019	rade tank
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1 Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we Removed deadmen. Cleaned location and moved off. I hereby certify that the information above is true and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a general true	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: Attach wellbore on the well of the surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. y knowledge and belief. I further certify that any pit or below-greneral permit or an (attached) alternative OCD-approved plegulatory Tech DATE 08/08/2019	rade tank
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertistarting any proposed work). SEE RULE 1103. For Multiple Comrecompletion. 07/26/12 MIRU plugging equipment. Dug out cellar. ND wellhead. 07/27/12 Circulated hole w/ mud laden fluid. Spotted 25 sx cement @ 1500 psi. Held for 20 minutes. Spotted 100 sx @ 2500-1- Perf'd csg @ 350'. Set packer @ 34'. Sqz'd 120 sx cement 08/02/12 Moved in welder and backhoe. Dug out cellar. Cut off we Removed deadmen. Cleaned location and moved off. I hereby certify that the information above is true and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g SIGNATURE	nent details, and give pertinent dates, including estimated pletions: Attach wellbore diagram of proposed completions: Attach wellbore on the well of the surface. Rigged down and moved off. Ilhead. Welded on "Above Ground" Dry Hole Marke Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. y knowledge and belief. I further certify that any pit or below-greneral permit or an (attached) alternative OCD-approved plegulatory Tech DATE 08/08/2019	rade tank

AUG 1 4 2017