Submit 1 Copy To Appropriate District State of Net	
Office District I – (575) 393-6161 Energy, Minerals and	I Natural Resources Revised August 1, 2017
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283	WELL API NO. 30-005-00825
811 S. First St., Artesia, NM 88210 HOBBS OOD CONSERVA	TION DIVISION 5 Indicate Type of Lease
$\frac{\text{District III} - (505) 334-61/8}{1220 \text{ South St}}$. Francis Dr. STATE STATE FEE
$\frac{\text{District IV}}{1220 \text{ S. st. Francis Dr., Santa Fe, NM}} SEP 04 2012 Santa Fe, N37505 Santa Fe, NM SEP 04 2012 Santa Fe, NM S7505 Santa Fe, NM S750$	M 87505 6. State Oil & Gas Lease No.
87505	303735
SUNDRY NOTICES AND REPORTS ON W	/ELLS 7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPORTS OF DEVILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-	
PROPOSALS.)	
1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other	21
2. Name of Operator Celero Energy II, LP	9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste. 1601	10. Pool name or Wildcat
Midland, TX 79701	Caprock; Queen
4. Well Location	
Unit Letter M : 660 feet from the Sou	
Section 23 Township 13S	Range 31E NMPM County Chaves
11. Elevation (Show wheth	er DR, KKB, KI, GR, eïc.)
12. Check Appropriate Box to Indic	ate Nature of Notice, Report or Other Data
PERFORM REMEDIAL WORK PLUG AND ABANDON	
PULL OR ALTER CASING MULTIPLE COMPL	
DOWNHOLE COMMINGLE	
OTHER:] OTHER:
13. Describe proposed or completed operations. (Clearly sta	te all pertinent details, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 1	
 Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 1 proposed completion or recompletion. 	te all pertinent details, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 1	te all pertinent details, and give pertinent dates, including estimated date
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul. 	te all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 	te all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 	Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM 3" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP &
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & 	Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM 3" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2"
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at 	te all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM 3" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ 	te all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM 3" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at 	te all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM 3" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ 	te all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM 3" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ 	te all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM 3" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 1 proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well 	 Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of Ius. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM "DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ 	 Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of Ius. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM "DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 1 proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well 	 Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of Ius. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM "DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well Spud Date: 	 ate all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM "DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well Spud Date: 	 ate all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM "DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production
 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annulestablish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well Spud Date: 	 ate all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM "DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') OBPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well Spud Date: 	 ate all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM "DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/ 2" x 1 1/2" x 16' RWBC /4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 1 proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annulestablish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') GPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well Spud Date: Rig Release Rig Releas	Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of Ius. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM I" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/·2" x 1 1/2" x 16' RWBC '4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production ase Date:
13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 19.15.7.14 1 proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annul establish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') of BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well Spud Date: Rig Releater T hereby certify that the information above is true and complete to SIGNATURE TITLE F Type or print name Lisa Hunt E-mail a	Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of lus. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM "DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/·2" x 1 1/2" x 16' RWBC '4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production
 13. Describe proposed or completed operations. (Clearly sta of starting any proposed work). SEE RULE 19.15.7.14 1 proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annulestablish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') GPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well Spud Date: Rig Release Rig Releas	Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of Ius. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM I" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/·2" x 1 1/2" x 16' RWBC '4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production ase Date:
 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 19.15.7.14 I proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annulestablish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6- 1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well Spud Date: Rig Release Rig Release Rig Release Rig Release Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to SIGNATURE Right that the information above is true and complete to Right that the information above is true and complete to Right the right that the righ	Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of Ius. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM I" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/·2" x 1 1/2" x 16' RWBC '4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production ase Date:
13. Describe proposed or completed operations. (Clearly station of starting any proposed work). SEE RULE 19.15.7.14 1 proposed completion or recompletion. 8/2 -8/15/12 TIH w/ tbg & pkr. Set pkr at 224 '. Place 500# on tbg-csg annulestablish an injection rate. Pump 100 sx of Class "C" cmt with 2 & 650#. WOC. TOH w/ pkr. TIH w/ tbg, 3 7/8" bit & 6-3 1/8 TOH w/ same. Run & LD 2 3/8" IPC tbg. Clean ends of tbg & x 2 3/8" larkin type WH. TIH, testing to 6000#, 97 jts (3011') BPPN. Set SN from 3011-12', BPPN from 3021-16' & EOT at pump with 6" strainer nipple, 6-1 1/2" x 25' sinker bars, 70 - 3/ with 1 1/2" x 8' polish rod liner. Space out pump and hung well Spud Date: Rig Releat I hereby certify that the information above is true and complete to SIGNATURE TITLE F Type or print name Lisa Hunt E-mail a	Ite all pertinent details, and give pertinent dates, including estimated date NMAC. For Multiple Completions: Attach wellbore diagram of Ius. Pump 5 BFW into csg leaks from 383' to 570' at 2 BPM & 800# to 2% CaCl2 at 14.8 ppg, yield of 1.32 & displaced cmt to 285' at 1 BPM I" DC's. Tag cmt at 353'. Circ WB w/ clean PW. Release RBP & install thread protectors. NDBOP, remove new WH & re-install 4 1/2" of 2 3/8" OD 4.7# 8rd EUE J-55 tbg with 2 3/8" x 1' SN & 2 3/8" x 4' 3016'. NDBOP & NU tbg head. TIH w/·2" x 1 1/2" x 16' RWBC '4" X 25' "D" rods, 42- 7/8" x 25' "D" rods with 1 1/4 x 16' polish rod on. Place on production ase Date:

.