State of New Mexico

FILE IN TRIPLICATE GOBBS OCD OIL CONSERVATION DIVISION	Revised 5-27-2004
DISTRICT 1220 South St. Francis Dr.	WELL API NO
1625 N French Dr., Hobbs, NM 88240 Santa Fe, NM 87505 DISTRICT II OCT 0 2012 Santa Fe, NM 87505	30-025-20167
DISTRICT II 1301 W Grand Ave, Artesia, NM 88210	5 Indicate Type of Lease STATE FEE X
	6 State Oil & Gas Lease No
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	South Hobbs (G/SA) Unit
1 Type of Well	8 Well No. 90
Oil Well / Gas Well Other Temporarily Abandoned	
2 Name of Operator Occidental Permian Ltd.	9. OGRID No 157984
3 Address of Operator	10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	· · · · · · · · · · · · · · · · · · ·
4 Well Location	
Unit Letter O 890 Feet From The South 1650 Fee	t From The East Line
Section 9 Township 19-S Range 38-E	E NMPM Lea County
11 Elevation (Show whether DF, RKB, RT GR, etc.) 3611' RDB	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Pit time Distance from nearest fresh water well	
Pit Liner Thickness mil Below-Grade Tank. Volume bbls; Construction Ma	terial
12. Check Appropriate Box to Indicate Nature of Notice, Report, or C	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	NS PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA second	IT JOB X Status request X , including estimated date of starting any
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA second	IT JOB X Status request X , including estimated date of starting any
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well.	IT JOB X Status request X , including estimated date of starting any
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP.	IT JOB X Status request X , including estimated date of starting any
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well.	IT JOB X Status request X , including estimated date of starting any completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. Killed well. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/tubing. RU wireline and dump 20' of cement on top of CIBP.	IT JOB X Status request X , including estimated date of starting any completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. Killed well. POOH w/packer RIH w/CIBP, would not set. 5. 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. 6. POOH w/tubing. RU wireline and dump 20' of cement on top of CIBP. 7. 7. RUH w/macker Inplate leak from 1027 1057'.	IT JOB X Status request X , including estimated date of starting any completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RÜPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. 4. Killed well. POOH w/packer RIH w/CIBP, would not set 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/tubing. RU wireline and dump 20' of cement on top of CIBP. 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandonia	IT JOB X Status request X , including estimated date of starting any completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RÜPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. Killed well. POOH w/DOH w/packer RIH w/CIBP, would not set 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/LIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandoni 10. 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. Abandoni 10.	IT JOB X Status request X , including estimated date of starting any completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RÜPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. 4. Killed well. POOH w/packer RIH w/CIBP, would not set 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/tubing. RU wireline and dump 20' of cement on top of CIBP. 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandonia	IT JOB
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. Killed well. POOH w/packer RIH w/CIBP, would not set. 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/Lubing. RU wireline and dump 20' of cement on top of CIBP. 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandont 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. 11. RU HES and spotted 25 sack of class C cement across leak ***see attached sheet for add	IT JOB
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. 4. Killed well. POOH w/packer RIH w/CIBP, would not set. 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/tubing. RU wireline and dump 20' of cement on top of CIBP. 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandont 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. 11. 11. RU HES and spotted 25 sack of class C cement across leak ****see attached sheet for add Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	IT JOB
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. Killed well. POOH w/packer RIH w/CIBP, would not set. 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/Lubing. RU wireline and dump 20' of cement on top of CIBP. 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandont 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. 11. RU HES and spotted 25 sack of class C cement across leak ***see attached sheet for add	IT JOB
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. Killed well. POOH w/packer RIH w/CIBP, would not set. 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/LiBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. 11. RU HES and spotted 25 sack of class C cement across leak ***see attached sheet for add Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative <td>IT JOB X Status request X , including estimated date of starting any completion or recompletion. eaked down to 0 in 2 min. roval of Tempore // 12-2013 ment Expires // 2013 litional data*** that any pit or below-grade tank has been/will be e OCD-approved</td>	IT JOB X Status request X , including estimated date of starting any completion or recompletion. eaked down to 0 in 2 min. roval of Tempore // 12-2013 ment Expires // 2013 litional data*** that any pit or below-grade tank has been/will be e OCD-approved
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. ND wellhead/NU BOP. 4. Killed well. POOH w/packer RIH w/CIBP, would not set. 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/LIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandont 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. ****see attached sheet for add 11. RU HES and spotted 25 sack of class C cement across leak ****see attached sheet for add Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or or an (attached) alternative plan	IT JOB X Status request X , including estimated date of starting any completion or recompletion. eaked down to 0 in 2 min. roval of Tempo Zol3 ment Expires Zol3 litional data*** that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 10/05/2012
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. 4. Killed well. POOH w/packer RIH w/CIBP, would not set. 5. 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and 1 6. POOH w/Lubing. RU wireline and dump 20' of cement on top of CIBP. 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandont 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. ***see attached sheet for add 11. RU HES and spotted 25 sack of class C cement across leak ***see attached sheet for add Interesting that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or classed according to NMOCD gu	IT JOB X Status request X , including estimated date of starting any completion or recompletion. eaked down to 0 in 2 min. eaked down t
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER. TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. Killed well. POOH w/packer RIH w/CIBP, would not set. 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and I 6. 6. POOH w/Libing. RU wireline and dump 20' of cement on top of CIBP. This Appr 7. RIH w/packer. Isolate leak from 1027-1057'. 8. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandont 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. 11. 11. RU HES and spotted 25 sack of class C cement across leak ****see attached sheet for add Vertify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or clased according to NMOCD guidelines SIGNATURE TITLE Administrative	IT JOB X Status request X , including estimated date of starting any completion or recompletion. eaked down to 0 in 2 min. eaked down t
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. ND wellhead/NU BOP. 4. 4. Killed well. POOH w/packer RIH w/CIBP, would not set 5. 5. POOH w/CIBP and RIH w/new CIBP set @3964'. Circulate well. Tested at 600 PSI and I 6. POOH w/Libing. RU wireline and dump 20' of cement on top of CIBP. 7. RIH w/packer. Isolate leak from 1027-1057'. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appr 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandont 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. 11. 11. RU HES and spotted 25 sack of class C cement across leak ***see attached sheet for add 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or or an (attached) alternative plan SIGNATURE TITLE	IT JOB X Status request X , including estimated date of starting any completion or recompletion. eaked down to 0 in 2 min. eoval of Tempor roval of Tempor ment Expires litional data*** that any pit or below-grade tank has been/will be e OCD-approved Associate DATE
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER OTHER TA well/TA S 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. 14. RUPU & RU. 2. Test casing #500PSI. Did not hold. Shot drain hole and killed well. 3. 3. ND wellhead/NU BOP. 4. Killed well. POOH w/packer RIH w/CIBP, would not set. 5. POOH w/CIBP and RIH w/new CIBP set @3964*. Circulate well. Tested at 600 PSI and 1 6. 6. POOH w/LIBP and RIH w/new CIBP set @3964*. Circulate well. Tested at 600 PSI and 1 6. 7. RIH w/packer. Isolate leak from 1027-1057*. 8. 8. Pump 2 BPM @1000 PSI. Only able to get 2 bbls into it. This Appor 9. Spotted 500 gal of acid to break down leak. Pressured up to 2000 PSI. Abandont 10. POOH w/packer. RU wireline and run CIL. RD wireline RIH w/kill pipe. 11. 11. RU HES and spotted 25 sack of class C cement across leak ****see attached sheet for add Attached sheet for add Interby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit </td <td>IT JOB X Status request X , including estimated date of starting any completion or recompletion. eaked down to 0 in 2 min. eoval of Tempor roval of Tempor ment Expires litional data*** that any pit or below-grade tank has been/will be e OCD-approved Associate DATE</td>	IT JOB X Status request X , including estimated date of starting any completion or recompletion. eaked down to 0 in 2 min. eoval of Tempor roval of Tempor ment Expires litional data*** that any pit or below-grade tank has been/will be e OCD-approved Associate DATE

OCT 1 0 2012

Form C-103 ed 5-27-2004 D/

.

Energy, Minerals and Natural Resources Department

۹,	4	

.

SHU 90 30-025-20167

....

12. POOH w/tubing. Pressured up to 1000 PSI. Bled down to 750 PSI and started holding. Left pressure on well and SION.

Ľ

- 13. RIH w/drill collars and bit. Drill out cement from 811-1080'. Circulate clean. Tested casing to 630 PSI and held. POOH w/bit & drill collars.
- 14. RIH & tagged @3944'. Circulate well w/80 bbl of fresh water. RIH w/packer. Tested casing to 560# and held.
- 15. Tested casing to 560 PSI for 30 minutes and charted for the NMOCD.
- 16. ND BOP/NU wellhead.
- 17. RDPU & RU. Clean location and leave well TA'd.

RUPU 09/04/2012 RDPU 09/12/2012

į,



October 4, 2012

Work Plan Report for Well:SHOU-90009



Survey Viewer