

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-025-34096

5. Indicate Type of Lease

STATE ☒ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

C.H. WEIR "A"

8. Well Number 20

9. OGRID Number 4323

10. Pool name or Wildcat

SKAGGS; DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

CHEVRON U.S.A. INC.

3. Address of Operator

15 SMITH ROAD, MIDLAND, TEXAS 79705

4. Well Location

Unit Letter F: 2510 feet from the NORTH line and 2225 feet from the WEST line

Section 12

Township 20-S

Range 37-E

NMPM

County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐

OTHER: INTENT TO ACIDIZE, SONIC HAMMER, & SC SQZ

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

CHEVRON U.S.A. INC. INTENDS TO ACIDIZE, SONIC HAMMER, & SCALE SQUEEZE THE SUBJECT WELL.

PLEASE FIND ATTACHED, THE INTENDED PROCEDURE, WELLBORE DIAGRAM, & C-144 INFORMATION.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE: REGULATORY SPECIALIST

DATE: 10-16-2012

Type or print name: DENISE PINKERTON

E-mail address: leakejd@chevron.com

PHONE: 432-687-7375

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

C.H. Weir A #20 – [30-025-34096]

Skaggs field

T20S, R37E, Section 12

N 32° 35' 16.548", W -103° 12' 21.744" (NAD27)

Job: Sonic Hammer, Acidize & Scale Squeeze

*This procedure is meant to be followed. It is up to the WSM, Remedial Engineer and Production Engineer to make the decisions necessary to do SAFELY what is best for the well. In the extent that this procedure does not reflect actual operations, please contact RE, PE and Superintendent for possible MOC.

It should be noted, the anticipated maximum amount of H₂S that an individual could be exposed to on location is as follows for given Radius of Exposure:

100 PPM ROE = $0.001589 \times 950 \text{ PPM} \times 194 \text{ MCF}^{0.6258} = 35 \text{ FEET}$

500 PPM ROE = $0.0004546 \times 950 \text{ PPM} \times 194 \text{ MCF}^{0.6258} = 16 \text{ FEET}$

PREWORK:

1. Utilize the rig move check list.
2. Check anchors and verify that pull test has been completed in the last 24 months.
3. Ensure location of & distance to power lines are in accordance with MCA SWP. Complete an electrical variance and electrical variance RUMS if necessary.
4. Ensure that location is of adequate build and construction.
5. Ensure that elevators and other lifting equipment are inspected. Caliper all lifting equipment at the beginning of each day or when sizes change.
6. When NU anything over an open wellhead (EPA, etc.), ensure the hole is covered to avoid dropping anything downhole.
7. For wells to be worked on or drilled in an H₂S field/area, include the anticipated maximum amount of H₂S that an individual could be exposed to along with the ROE calculations for 100' and 500'.
8. If the possibility of trapped pressure exists, check for possible obstructions by:
 - Pumping through the fish/tubular – this is not guaranteed with an old fish as the possibility of a hole above the obstruction could yield inconclusive results.
 - Dummy run – make a dummy run through the fish/tubular with sandline, slickline, e-line or rods to verify no obstruction. Prior to making any dummy run contact RE and discuss.

If unable to verify that there is no obstruction above the connection to be broken, or if there is an obstruction:

- Hot Tap at the connection to check for pressure and bleed off.

Observe and watch for signs/indicators of pressure as connection is being broken. Use mud bucket (with seals removed) and clear all non-essential personnel from the floor.

Procedure:

1. MI & RU Workover unit.
2. Verify that well does not have pressure/flow. If well has pressure, record tubing and casing pressures on WellView report. Bleed down well; if necessary, kill with cut brine fluid (8.6 ppg).
- **Caliper elevators and tubular EACH DAY prior to handling tubing/rods/tools. Note in JSA & WellView when and what items are callipered within the task step that includes that work.**
3. Unseat pump. POOH with rods & pump. Examine rod string for paraffin/corrosion. Do not hot water, unless significant paraffin is seen. ND wellhead, unset TAC, NU BOP [*Blinds on bottom, pipe rams on top*].
4. POOH & LD 1 joint, PU 7" packer and set @ ~ 25'. Close and test BOP pipe rams to 250psi (low)/ 500psi (high). Record testing pressures on WellView report. Release and LD packer.
5. PU tubing and run back in hole to tag for fill.
Depths: (TAC 6,730', Bottom Perfs 6,902', EOT 6,929', PBTB 6,955')
6. RU Scanners and POOH while scanning all 2-7/8" 6.5# J-55 production tubing. LD all non-yellow band joints. If fill is tagged:
 - a. Above 6,950' proceed to step #7.
 - b. Below 6,950' skip to step #8.

Strap pipe out of the hole to verify depths. Send scan report to lgbi@chevron.com.

- **Caliper elevators and tubular EACH DAY prior to handling tubing/rods/tools. Note in JSA & WellView when and what items are callipered within the task step that includes that work.**
7. PU and RIH with 6-1/8" Milled Tooth (MT) Bit, 4 (3-1/2') drill collars on 2-7/8" 6.5# L-80 Workstring. RU power swivel and C/O to 6,955'. POOH with 2-7/8" WS and bit. LD bit and BHA.

*Note: If circulation is not expected/achieved, notify Remedial Engineer and proceed to C/O utilizing foam/air unit (continue to supplemental procedure at end).
8. Contact sonic tool representative to be on-site during job. PU and RIH with Sonic Hammer tool and 2-7/8" Workstring to 6,910' or enough depth to cover the bottom stimulation interval (@ 6,902') with a whole stand. Hydrotest tubing to 6,000 psi. Stand back tubing to top perforations (@ 6,828'). Install stripper head and stand pipe with sufficient treating line to move tools vertically ~ 50'. RU pressure gauges to allow monitoring of tubing and casing pressures during job.
9. MI and RU Petroplex equipment. Titrate acids and verify concentration ($\text{HCl} \pm 1.5\%$). Treat all intervals from 6,825' to 6,905' with ~20 bbls of 8.6 ppg cut brine water per interval (**see Table 1**). Pump down Sonic Hammer tool at 5 BPM while reciprocating tool across intervals. Do not exceed 5,000 psi tubing pressure. Leave annulus open in circulation mode while treating intervals with brine water.

Perf Intervals for Acid			
Interval (#)	Depth	Net Feet (ft)	Acid Volume (gal)
1	6,825' - 6,865'	40	1,750
2	6,865' - 6,905'	40	1,750
Total		80	3,500

Table 1

10. Follow the brine water wash with 3,500 gals 15% NEFE HCl of total acid for all intervals. Spot 3 bbls of acid outside tubing, shut in casing, pump 1,750 gals of acid @ 5 BPM over first treating interval from 6,825' – 6,865', monitor casing pressure not exceeding 500 psi on backside. Flush tubing with brine water after every acidizing interval, make a connection and continue with remaining interval. **Refer to Table 1.**

11. Shut in well for 1 hr to allow time for acid to spend. Monitor and bleed off excess pressure at surface if necessary to keep casing pressure below 500 psi.
12. Scale squeeze well with a total of 140 bbls 8.6 ppg brine water mixed with 2 drums (110 gallons) Baker SCW-358 Scale Inhibitor Chemical. Pump down Sonic Hammer tool at a max rate of 5 BPM. Start from lowest interval of 6,905' – 6,865' and continue moving uphole per pump schedule (**see Table 2**). Ensure top of tubing is flushed with brine water before making a connection.

Scale Squeeze Pump Schedule						
Step	Interval (ft)	Max Rate (BPM)	Volume Brine (bbl)	Volume Scale Chem. (gal)	Cum Volume (bbl)	
1 Pump Chemical/brine while moving from	6905' - 6865'	5	13	55	14	
2 Pump Brine while moving from	6905' - 6865'	5	47		61	
3 Move pipe to next interval of	6865' - 6825'				61	
4 Pump Chemical/brine while moving from	6865' - 6825'	5	13	55	76	
5 Pump Brine while moving from	6865' - 6825'	5	67		143	

Table 2

13. PU workstring to higher than top perforations. Displace tubing volume with 8.6 ppg cut brine water. Do not exceed 500 psi casing pressure or 5 BPM while pumping scale squeeze or casing flush. Release Petroplex.
14. TOH and LD 2-7/8" WS and Sonic Hammer tool.
15. RIH with 2-7/8" J-55 production tubing and hydrotest to 6,000 psi. **Pump 8.6 ppg cut brine water containing soap and biocide per ALCR.**
16. ND BOP, set TAC, NU WH. RIH with rods and pump per ALCR's recommendation/Rodstar design. Hang well on.
17. RD and release Workover unit. Turn well over to production.

FOAM / AIR CLEANOUT PROCEDURE

- This procedure is an addition to the original procedure.
 1. Install flowback manifold with two chokes. All components on flowback manifold must be rated to at least 5,000 psi. If possible, flowback manifold components should be hydrotested before delivery. Hardline pipes from 2" casing valve to manifold to half pit with gas buster.
 2. Install flowback tank downwind from rig.
 3. Position Air unit upwind from Rig next to water tanks. Have vacuum truck on standby to empty halfpit. (if needed)
 4. RIH with 6-1/8" MT bit, 4 (3-1/2") drill collars on 2-7/8" 6.5# L-80 WS.
 5. NU stripper head with **NO Outlets** (Check stripper cap for thread type - course threads preferred). **Stripper head to be stump tested to 1,000 psi before being delivered to rig.** Check chart or test at rig.
 6. RU foam air unit. Make quality foam on surface before going down hole with foam/air. Install flapper float at surface before beginning to pump. Break circulation with foam/air. Evacuate fluid from well.

Pump high quality foam at all times. Do not pump dry air at any time. Fluid injection rates will generally be above 12 gallons per minute.

Whenever there is pressure on the stripper head, have a dedicated person continuously monitor pressure at choke manifold and have a dedicated person at accumulator ready to close annular BOP in case stripper leaks. Do not allow pressure on stripper head to exceed 500 psi. If pressure cannot be controlled below 500 psi, stop pumping, close BOP and bleed off pressure.

7. Clean out fill to 6,955' with low RPM's rotation and circulation, always keep pipe moving. Short trips can be beneficial to hole cleaning. Circulate well clean for at least 1 hour at the end of the day and pull up above the perforations before shut down for night. If the foam/air unit goes down, pull above the perforations.
8. When tripping out of hole, have special float bleed off tool available to relieve trapped pressure below float.

Ensure that high quality, stiff foam is pumped while circulating the fill. Stiff foam is required to prevent segregation while circulating. Monitor flow and pressures carefully when cleaning out.

Before rigging up power swivel to rotate, carefully inspect Kelly hose to ensure that it is in good condition. Ensure that swivel packing is in good condition.


Continue on with original procedure for completion.

Year	Stage 1 (Perfs)	Stage 2 (Perfs)
1982	6,825	6,865
1983	6,830	6,865
1984	6,835	6,865
1985	6,840	6,865
1986	6,845	6,865
1987	6,850	6,865
1988	6,855	6,865
1989	6,860	6,865
1990	6,865	6,865
1991	6,870	6,865
1992	6,875	6,865
1993	6,880	6,865
1994	6,885	6,865
1995	6,890	6,865
1996	6,895	6,865
1997	6,900	6,865
1998	6,905	6,865
1999	6,910	6,865

74

Chevron U.S.A. Inc. Wellbore Diagram : WEIRCHA20

Lease: OEU EUNICE		Well No.: WEIR, C. H. -A- 20		Field: FLD-SKAGGS	
Location: 2510FNL2225FWL		Sec.: N/A		Blk:	Survey: N/A
County: Lea	St.: New Mexico	Refno: BR7378		API: 3002534096	Cost Center: UCL211300
Section: 12		Township: 020 S			Range: 037 E
Current Status: ACTIVE				Dead Man Anchors Test Date: 03/26/2007	
Directions:					



Ground Elevation (MSL):: 3559.00	Spud Date: 09/17/1997	Compl. Date: 10/08/1998
Well Depth Datum:: CSI0000N	Elevation (MSL):: 0.00	Correction Factor: 21.00
Last Updated by: bujq	Date: 08/29/2012	