to Appropriate District Office	Energy Minerals and Natural Res	xico sources Department	Form C-103 Revised 1-1-89
DISTRICT I	OIL CONSERVATIO	N DIVISION	·
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 8		30-025-35066 5. Indicate Type of Lease
DISTRICT III			STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. B-10629
SUNDRY NOT	ICES AND REPORTS ON WELL	IS	
(DO NOT USE THIS FORM FOR PR DIFFERENT REBE (FORM C	OPOSALS TO DRILL OR TO DEEPEN (RVOIR. USE "APPLICATION FOR PER -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Weil: OIL WEIL X WELL	OTHER		Big Flat ASN State Com
2. Name of Operator			8. Well No.
YATES PETROLEUM CORPOR 3. Address of Operator			9. Pool name or Wildcat
105 South 4th St., Art	esia, NM 88210		Undesignated
4. Well Location	· · · · · · · · · · · · · · · · · · ·		
Unit Letter : 845	Feet From The South	Line and1980) Feet From The East L
Section 10	Township 16S Ran	ge 35E	NMPM Lea County
	10. Elevation (Show whether D	DF, RKB, RT, GR, etc.)	
		994' GR	
ii. Check	Appropriate Box to Indicate N	lature of Notice, R	cport, or Other Data
NOTICE OF IN	TENTION TO:	SUE	SEQUENT REPORT OF:
		REMEDIAL WORK	
	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
Press 3			
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB
			EMENTJOB
DTHER:	tions (Clearly state all pertinent details and	OTHER: Perfora	te, acidize & frac
DTHER: 12. Describe Proposed or Completed Operations work) SEE RULE 1103.		OTHER: <u>Perfora</u> give pertinent dates, inclu	te, acidize & frac
12. Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1	ocation and set anchors.	OTHER: Perfora give perlinent dates, inclu . Moved in and	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH
12. Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and	ocation and set anchors tubing to 7300'. Shut	OTHER: Perfora give pertinent dates, inclu . Moved in and well in for ni	te, acidize & frac cing estimated date of starting any proposed d rigged up pulling unit. TIH ight.
DTHER: 12. Describe Proposed or Completed Opera- work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and	OTHER: Perforation digive pertiment dates, incluined Moved in and well in for not d tubing and ta	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled tu
DTHER: 12. Describe Proposed or Completed Opera work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15%	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho	OTHER: Perforant digive pertiment dates, incluined Moved in and well in for nit d tubing and ta ole with 7% sup	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in
DTHER: 12. Describe Proposed or Completed Opera- work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline.	OTHER: Perfora d give periment dates, inclu . Moved in and well in for ni d tubing and ta ole with 7% sup ogging tools an	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with
DTHER: 12. Describe Proposed or Completed Opera- work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline. wireline with full lubra	OTHER: Perform give periment dates, inclu . Moved in and well in for no d tubing and ta ole with 7% sup ogging tools ar icator. TIH wi	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforat
DTHER: 12. Describe Proposed or Completed Opera- work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42	ocation and set anchors, tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline. wireline with full lubra " holes (6 SPF - <u>Atoka)</u> .	OTHER: Perform give periment dates, inclu . Moved in and well in for no d tubing and ta ole with 7% sup ogging tools ar icator. TIH with . TOOH with ca	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforat asing guns and rigged down wire
DTHER: 12. Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packe	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline. wireline with full lubra " holes (6 SPF - <u>Atoka)</u> r with 2.25" on/off tool	OTHER: Perform give perfinent dates, inclu- . Moved in and well in for ni- d tubing and ta- ole with 7% sup- ogging tools ar- icator. TIH wi- . TOOH with ca- l to 11870'. H	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforat asing guns and rigged down wire
DTHER: 12. Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packe Tested packer to 500	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline. wireline with full lubra " holes (6 SPF - <u>Atoka)</u> r with 2.25" on/off tool psi. Swabbed. Shut we	OTHER: Perform give periment dates, inclu- . Moved in and well in for ni- d tubing and ta- ole with 7% sup- ogging tools and icator. TIH with . TOOH with ca- l to 11870'. Hell in.	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in hd ran GR/CBL log. TOOH with ith 4" casing guns and perforat asing guns and rigged down wire Pulled up 4 joints and set pack
DTHER: 12 Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packet Tested packer to 500 9-7-2000 - Bled well	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline. wireline with full lubra " holes (6 SPF - <u>Atoka)</u> r with 2.25" on/off tool psi. Swabbed. Shut we down. Swabbed. Rigged	OTHER: Perform give periment dates, inclu- . Moved in and well in for ni- d tubing and ta- ole with 7% sup- ogging tools and icator. TIH wi- . TOOH with ca- l to 11870'. He 11 in. up slickline.	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled tw ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforat asing guns and rigged down wire Pulled up 4 joints and set pack TIH and set 2.25" blanking
DTHER: 12 Describe Proposed or Completed Opera- work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packe Tested packer to 500 9-7-2000 - Bled well plug in on/off tool a	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline. wireline with full lubri " holes (6 SPF - Atoka) r with 2.25" on/off too psi. Swabbed. Shut we down. Swabbed. Rigged t 11750'. NOTE: Change	OTHER: Perform give periment dates, inclue . Moved in and well in for no d tubing and ta ole with 7% sup ogging tools and icator. TIH with . TOOH with ca l to 11870'. He l in. up slickline. e of plans made	te, acidize & frac cing estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled tw ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforat asing guns and rigged down wire Pulled up 4 joints and set pack TIH and set 2.25" blanking e here. Pulled blanking plug.
DTHER: 12. Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packet Tested packer to 500 9-7-2000 - Bled well plug in on/off tool a Loaded tubing and rel	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline. wireline with full lubri " holes (6 SPF - Atoka) r with 2.25" on/off tool psi. Swabbed. Shut wel down. Swabbed. Rigged t 11750'. NOTE: Change	OTHER: Perform give periment dates, inclu- Moved in and well in for no d tubing and ta ole with 7% sup ogging tools ar icator. TIH with to 11870'. H lt in. up slickline. e of plans made n 6 joints and	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforat asing guns and rigged down wire Pulled up 4 joints and set pack TIH and set 2.25" blanking here. Pulled blanking plug. reset packer at 11556'. Loade
DTHER: 12 Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packe Tested packer to 500 9-7-2000 - Bled well plug in on/off tool a Loaded tubing and rel annulus and tested to	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline. wireline with full lubra " holes (6 SPF - <u>Atoka)</u> r with 2.25" on/off tool psi. Swabbed. Shut we down. Swabbed. Rigged t 11750'. NOTE: Change eased packer. Laid down	OTHER: Perform give periment dates, inclue . Moved in and well in for night d tubing and tag ole with 7% suppogging tools and icator. TIH with . TOOH with cass 1 to 11870'. He 11 in. up slickline. e of plans made n 6 joints and tree. Shut well	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforat asing guns and rigged down wire Pulled up 4 joints and set pack TIH and set 2.25" blanking here. Pulled blanking plug. reset packer at 11556'. Loade
DTHER: 12 Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packe Tested packer to 500 9-7-2000 - Bled well plug in on/off tool a Loaded tubing and rel annulus and tested to	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced ho p wireline. TIH with lo ged down wireline. wireline with full lubri " holes (6 SPF - Atoka), r with 2.25" on/off too psi. Swabbed. Shut we down. Swabbed. Rigged t 11750'. NOTE: Change eased packer. Laid down 1000 psi. Flanged up t	OTHER: Perform give periment dates, inclue . Moved in and well in for night d tubing and tag ole with 7% suppogging tools and icator. TIH with . TOOH with cass 1 to 11870'. Hell 1 in. up slickline. e of plans made n 6 joints and tree. Shut well ever to an	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in ad ran GR/CBL log. TOOH with ith 4" casing guns and perforate asing guns and rigged down wire Pulled up 4 joints and set pack TIH and set 2.25" blanking be here. Pulled blanking plug. reset packer at 11556'. Loade 11 in. CONTINUED ON NEXT PAGE:
DTHER: 12. Describe Proposed or Completed Opera- work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packe Tested packer to 500 9-7-2000 - Bled well plug in on/off tool a Loaded tubing and rel annulus and tested to 1 hereby certify that the information above with	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced he p wireline. TIH with lo ged down wireline. wireline with full lubra " holes (6 SPF - Atoka) r with 2.25" on/off tool psi. Swabbed. Shut we down. Swabbed. Rigged t 11750'. NOTE: Change eased packer. Laid down 1000 psi. Flanged up to and complet to the best of my knowledge and be	OTHER: Perform give periment dates, inclue . Moved in and well in for night d tubing and tag ole with 7% suppogging tools and icator. TIH with . TOOH with cass 1 to 11870'. Hell 1 in. up slickline. e of plans made n 6 joints and tree. Shut well ever to an	te, acidize & frac cing estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled tw ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforate asing guns and rigged down wire Pulled up 4 joints and set pack TIH and set 2.25" blanking here. Pulled blanking plug. reset packer at 11556'. Loade 11 in. CONTINUED ON NEXT PAGE:
DTHER: 12 Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packe Tested packer to 500 9-7-2000 - Bled well plug in on/off tool a Loaded tubing and rel annulus and tested to 1hereby certify that the information above with SHONATURE WALLY WILLING TYPEOR PRINT NAME Rusty Klein	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced he p wireline. TIH with lo ged down wireline. wireline with full lubra " holes (6 SPF - Atoka) r with 2.25" on/off tool psi. Swabbed. Shut we down. Swabbed. Rigged t 11750'. NOTE: Change eased packer. Laid down 1000 psi. Flanged up to and complet to the best of my knowledge and be	OTHER: Perform give periment dates, inclue . Moved in and well in for nid d tubing and ta ole with 7% sup ogging tools and icator. TIH with . TOOH with ca l to 11870'. H l1 in. up slickline. e of plans made n 6 joints and tree. Shut well end. <u>e Operations T</u>	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforate asing guns and rigged down wire Pulled up 4 joints and set pack TIH and set 2.25" blanking here. Pulled blanking plug. reset packer at 11556'. Loade 11 in. CONTINUED ON NEXT PAGE: echnician DATE Oct. 31, 2000
DTHER: 12 Describe Proposed or Completed Operative work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packe Tested packer to 500 9-7-2000 - Bled well plug in on/off tool a Loaded tubing and rel annulus and tested to Thereby certify that the information above with SHONATURE	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced he p wireline. TIH with lo ged down wireline. wireline with full lubra " holes (6 SPF - Atoka) r with 2.25" on/off tool psi. Swabbed. Shut we down. Swabbed. Rigged t 11750'. NOTE: Change eased packer. Laid down 1000 psi. Flanged up to and complet to the best of my knowledge and be	OTHER: Perform give periment dates, inclue . Moved in and well in for no d tubing and ta ole with 7% sup ogging tools and icator. TIH with . TOOH with ca l to 11870'. H l1 in. up slickline. e of plans made n 6 joints and tree. Shut well end. OPERATIONS T	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled to ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforate asing guns and rigged down wire Pulled up 4 joints and set pack TIH and set 2.25" blanking here. Pulled blanking plug. reset packer at 11556'. Loade 11 in. CONTINUED ON NEXT PAGE: echnician DATE Oct. 31, 2000 TELEPHONE NO. 505/748 TD BY
work) SEE RULE 1103. 8-31-2000 - Cleaned 1 with bit, scraper and 9-1-2000 - Finished T with 1000 gallons 15% 9-2-5-2000 - Rigged u logging tools and rig 9-6-2000 - Rigged up 11850-11862' w/72 .42 line. TIH with packe Tested packer to 500 9-7-2000 - Bled well plug in on/off tool a Loaded tubing and rel annulus and tested to 1hereby certify that the information above for SKONATURE WALLY AND	ocation and set anchors tubing to 7300'. Shut IH with bit, scraper and HCL acid. Displaced he p wireline. TIH with lo ged down wireline. wireline with full lubra " holes (6 SPF - Atoka) r with 2.25" on/off tool psi. Swabbed. Shut we down. Swabbed. Rigged t 11750'. NOTE: Change eased packer. Laid down 1000 psi. Flanged up to and complet to the best of my knowledge and be	OTHER: Perform give periment dates, inclue . Moved in and well in for nid d tubing and ta ole with 7% sup ogging tools and icator. TIH with . TOOH with ca l to 11870'. H l1 in. up slickline. e of plans made n 6 joints and tree. Shut well end. <u>e Operations T</u>	te, acidize & frac ding estimated date of starting any proposed d rigged up pulling unit. TIH ight. agged up at 12350'. Pickled tw ber fluid. TOOH. Shut well in nd ran GR/CBL log. TOOH with ith 4" casing guns and perforate asing guns and rigged down wire Pulled up 4 joints and set pack TIH and set 2.25" blanking e here. Pulled blanking plug. reset packer at 11556'. Loade 11 in. CONTINUED ON NEXT PAGE: echnician DATE Oct. 31, 2000 TELEPTIONE NO. 505/748

YATES PETROLEUM CORPORATION Big Flat ASN State Com #3 Section 10-T16S-R35E Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

3

9-8-2000 - Bled well down. Swabbed. Shut well in. 9-9-12-2000 - Shut in. Prep to frac. 9-13-2000 - Rigged up treesaver. Frac'd perforation sl1850-11862' (via 2-7/8" tubing - Atoka) with 23600 gallons of 70Q foam and 40000# 20-40 interprop with 20-40 econoflex. Started pressuring up & cut sand & went to flush. 3500# econoflex in formation. Opened well to pit and began flowing back frac. 9-14-2000 - Flowed for cleanup. Shut well in. 9-15-2000 - Flowing for cleanup. Shut well in. 9-16-18-2000 - Bled well down and loaded tubing with 7% super fluid. Released packer. Nippled down tree and nippled up BOP. TOOH and rigged up wireline. TIH with CIBP and set CIBP at 11750'. Shut well in. 9-19-2000 - Rigged up wireline. TIH with 4" casing guns and perforated 11573-11584' w/66 .42" holes (6 SPF - Atoka). TOOH with caising guns and rigged down wireline. TIH with packer with 2.25" on/off tool and 3-1/2" tubing to 11500'. Shut well in. 9-20-2000 - Finished TIH with tubing to 11580'. TOOH and laid down 10 joints. Set packer at 11269'. Nippled down BOP and nippled up tree. Flanged up. Swabbed tubing Shut well in. down. 9-21-2000 - Rigged up treesaver. Frac'd perforations 11573-11584' (Atoka - via 3-1/2" tubng) with 46500 gallons 700 foam and 45000# 20-40 interprop. Rigged down treesaver. Shut well in for 2-1/2 hours. Opened well up and began flowing back for cleanup. 9-22-2000 - Flowing back for cleanup. Shut well in. 9-23-25-2000 - Flowing well for cleanup. Shut well in. 9-26-2000 - Bled well down and loaded tubing with 7% KCL water. Released packer. Nippled down tree and nippled up BOP. TOOH with 3-1/2" tubing. Shut well in. Changed rams in BOP to 2-7/8". 9-27-2000 - Bled well down. Pumped 50 bbls 7% down casing. TIH with bit and drill collars and tubing and tagged sand at 11674'. Rigged up swivel. Washed sand to 11750'. Drilled on CIBP for 2 hours and cut top slips. Lost circulation. Pumped 200 bbls and caught fluid. Pumped 3 BPM and had 1-1/2 BPM returns. Pushed CIBP down to 12014'. Tagged sand from lower frac 152' below bottom perforation. TOOH to 11300'. Shut well in. 9-28-2000 - Bled well down. Pumped 7% to hold well. TOOH and laid down drill colalrs and bit. TIH with packer with 1.81" on/off tool. Pumping to keep well down. Installed hanger. Nippled down BOP and nippled up tree. Set packer at 11490'. Loaded and tested annulus. Shut well in. 9-29-2000 - Flow tested. Shut well in. 11573-11584' and 11850-11862' (Atoka) 9-30-10-2-2000 - Flow tested. Shut well in. 10-3-2000 - Rigged up slickline. TIH with 1.87" blanking plug and set in on/off tool at 11490'. TOOH. Well would not bleed down. TIH with pulling tool - plug was not in on/off tool. Bottom dogs were not latched into locking groove. Plug fell through packer to TD. TIH with 2nd plug and set. Bled well down. Loaded tubing and tested to 500 psi. Released on/off tool. Reversed tubing capacity. Nippled down tree and nippled up BOP. TOOH. Started in hole with RBP with ball catcher. Shut well in. 10-4-2000 - Finished TIH with RBP with ball catcher and set RBP at 11390'. TOOH. Rigged up wireline with full lubricator. TIH with 4" casing guns and perforated 11255-11302" w/38 .42" holes (<u>Straw</u>n). TOOH with casing guns and rigged down wireline. TIH with packer with 2.25" seating nipple. Shut well in. 10-5-2000 - Pumped 30 bbls 7% - did not circulate. Pulled up and set packer at 11170'. Nippled down BOP and nippled up tree. Loaded and tested annulus to 1000 psi. Swabbed tubing. Flow tested. Shut well in. 10-6-2000 - Opened well and flow tested. Acidized perforations 11255-11302' (Strawn)

YATES PETROLEUM CORPORATION Big Flat ASN State Com #3 Section 10-T16S-R35E Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

with 2500 gallons of 15% iron control HCL acid. Swabbed & flow tested. Shut well in. 10-7-9-2000 - Flow tested. Shut well in. 10-10-2000 - Loaded with 50 bbls 7% KCL. Released packer and nippled down tree. Nippled up BOP. Ran 3 joints of tubing and released RBP. Moved up and set RBP at 11100'. Tested to 1000 psi - had slight leak. Released packer. Tested RBP to 1500 psi down casing, OK. TOOH. Rigged up wireline. TIH with 4" casing guns and perforated 10818-10889' w/38 .42" holes (1 SPF - Cisco). TOOH with casing guns and rigged down wireline. TIH with packer and tubing. 10-11-2000 - Bled well down. Finished TIH with packer and tubing. Pumped 10 bbls did not circulate. Pulled up and set packer. Nippled down BOP and nippled up tree. Loaded and tested annulus to 500 psi. Swabbed dry. Shut well in. 10-12-2000 - Bled well down. Flow tested. Acidized perforations 10818-10889' (Cisco) with 10000 gallons 15% iron control HCL acid. Swabbed. Shut well in. 10-13-2000 - Flow tested & swabbed. Shut well in. 10-14-16-2000 - Flow tested. Shut well in. 10-17-2000 - Bled well down. Loaded with 7% KCL. Nippled down tree and nippled up BOP. TIH with 4 joints tubing. Released RBP and TOOH and laid down 2-7/8" tubing. Pulled up to 2000' and reset RBP. Loaded and tested to 500 psi. Slight leak. Shut well in. 10-18-2000 - RBP not holding. Released RBP and TOOH. Well kicked. Pumped 50 bbls 2%. TIH with new RBP to 1000' and set RBP. Tested to 500 psi. TOOH. Nippled down BOP and tubinghead. Nippled up dual head and BOP. TIH and released RBP. TOOH and laid down 2-7/8". Changed rams in BOP to 2-3/8" offset. TIH with retrieving tool with O J-slot, tubing and blast joints to cover Strawn and Cisco zones, dual packer and 2-3/8" tubing. Set packer at 11490'. Shut well in. 10-19-2000 - Pumped 7%. TIH with 100 joints of 2-3/8" tubing and tagged packer at 11490'. Spaced out. Installed hanger in tubinghead with 15000# compression. Loaded and tested to 500 psi. TIH with snap latch assembly and <u>326 joints of tubing (short</u> string). Sting into dual at 10691' and spaced out. Landed short string. Flanged up dual tree. Rigged up slickline. TIH with 1.81" check valve and set in 1.81" R nipple. Pressured to 3000 psi. Set dual packer. Blew hole in slickline lubricator. Pulled check valve. TOOH and rigged down slickline. Loaded annulus and tested to 1000 psi. Rigged up & swabbed long string down to 4600'. Shut in long string (Atoka). Rigged up and swabbed short sting (Strawn/Cisco). Shut in short string (Strawn/Cisco). 10-20-2000 - Opened short string and bled down. Rigged up slickline on long string. TIH with pulling tool. Pulled equalizing prong. Slight blow. Rigged down slickline. Swabbed & flow for cleanup. Shut in. Rigged up wireline. TIH with plug pulling tool and latched onto plug and pulled. Swabbed & flow tested short string (Strawn). 10-21-23-2000 - Flow tested Strawn side. Shut well in. 10-24-2000 - Flow tested Strawn side. Shut in. Flow tested Atoka side. Shut in. 10-25-2000 - Released well to production.

Perforations Open:

Commingled: 10818-10899' (Cisco) and 11255-11302' (Strawn) DHC-2840

11573-11862' (Atoka)

Rusty Klein, Operations Technician October 31, 2000

and a start of the start of the

.

-(g,g) = -(g,g)a 🗋

and the second second