ronn 5100-4 (August 199		۰ ^۱		ARTME	TED STATI	INTER					/	1	Fr	FORM AI OMB NO	PROVED 1004-0137 mber 30, 2000	
•	WEL		PLETIO	N OR R	ECOMPLE	TION F	REPORT	AND L	-OG	i /			. Lease	e Serial No. 078278	<u>1104 30, 2000</u>	
la. Type of					☐ Dry Oth Work Over □			- Deel	<u></u>		Resvr				e or Tribe Name	
b. Type of	Completio	m	Other				m 🖬 Più	g Back		Din. 1	KCSVI,.				ement Name and	no.
	of Operator coPhillip											5	3. Lease	178416 18 e Name and	Well No.	 -
3. Addres							3.a Phone			e area c	code)			<u>an 29-6 U</u>	nit 90M	1
	Box 2197	<u> </u>)486-2	463					Well No. -27560		
					accordance with		requiremen	ts)*				1	0. Field	and Pool, o	or Exploratory	
At Sur	face Sec 1	5 T29N	R6W NI	ENW 129	95 FNL 2325	FWL									de/Basin Dake on Block and	ota
At top	prod. inter-	val reporte	d below										Surv	ey or Area	<u>Sec 15 T29N </u>	<u>R6W</u>
At tota	l depth					·				<u> </u>		4	Rio Ar	riba		
14. Date S	pudded			e T.D. Rea		-	16. Date C		d XIF	Ready to	o Prod.	L.		-	, RKB, RT, GL)*	
12/12/		2009	12	/20/2004		: MD {	04/12/	2005	20.	Dent	h Bridge P	-+	6593' (GL ID		
18. Total I	T\	<u>/D</u>			Plug Back T.D.:	TVD			20. 	Depu	- Bridge P	iug Se		<u>VD</u>		
21. Type o CBL;]	f Electric & TDT; GR	k Other M /CCL	echanical I	Logs Run (S	Submit copy of	each)			22.	Was	well cored DST run?	Х	No C	Yes (Sul	ıbmit analysis) bmit analysis)	
		n1/0				<u> </u>				Direc	tional Sur	vey?	KI No) 🗌 Yes	(Submit copy)	
<u>23. Casing</u> Hole Size	Size/Gra	- T -		Top (MD)	Bottom (MI	D) Stag	e Cementer Depth	No. o Type	of Ske of Ce		Slurry (BBI		Cerne	ent Top*	Amount Pull	ed
12.25	9.625 I				229			150					0			
8.75	7 J-55	$\frac{20}{11.6}$			8005			630 465			<u> </u>		0 2580	iiiiiiiii		
6.25	4.5 N-8	0 11.6			8003			403					2260			
				·												
24. Tubin	Record				<u> </u>			<u>ا</u>			L		<u> </u>			
Size		Set (MD)	Packer I	Depth (MD)) Size	Dep	th Set (MD)	Packer	Dept	h (MD)	Si	ze	De	pth Set (MI) Packer Dept	h (MD)
2.375	7852															
25. Produc			- -		Bettom	26.	Perforatio Perforated		1	- -	0	NI-	TT-1			
A)Blance	Formation Mesave		5278	Top	<u>Bottom</u> 5768	527	78' - 5521'	Interval	;	.34	Size	<u>No.</u> 38	Holes	Open	Perf. Status	
<u>B)</u>	· · · · · · · · · · · · · · · · · · ·					550	56' - 5768'			.34		42		Open		
<u>c)</u>	<u> </u>				<u> </u>											
<u>D)</u> 27. Acid, I	racture, Tr	eatment, (Cement Soc	eze, Etc.	L					_ <u>_</u>				L		
	Depth Inter	val				11.00		mount a		-						
5278	- 5521'	·	Frac	000# 20	40 Brady Sa	$\frac{W/1G/N}{and 1}$	AG FR, 10	0,000# F N2	# <u>16/</u> & 11	30 Br	ady Sand	1; 1,2	58,100	<u>) SCF N2</u>	5 1096 bbls fl	uid;
5566'	- 5768'											FN2	: 1420	bbls fluid	1; 150,000# 20	/40
			Brad	ly sand; 2	2,053,300 SC	CF N2 a	nd 1714 b	bls flui	id.					کر چر	20 - C	
Date First	<u>ction - Inte</u> Test	Hours	Test	Oil BBL	Gas MCF	Water	Qil Gray	ity		Gas	Proc	duction	Method			
Produced 4/12/05	Date 4/07/05	Tested 24	Production	■ BBL	MCF 2178	BBL 5	Corr. Al	9 1 .		Bravity	FIL		rom W		< ~	
Choice Size	Tbg. Press.	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas : O	1	V	Well Stat		JWS I	rom w		<u> </u>	
1/2	Flwg. SI ()	330		• BDC	MCI	500	Ratio			GSI				NK	0	
Produ Date First	ction - Inte		·			·							ACC	EPTEN P	INP DECON	
Produced	Test Date	Hours Tested	Test Production		Gas MCF	Water BBL	Oil Grav Corr. A	/ity Pl	0	Jas Fravity	Proc	luction	Method		STI NEGUN	
Choke	Tbg. Press	Csg.	24 Hr.	► Oil		Water				1/-11-0			ļ	APR 2	6_2005	1
Size	Flwg. SI	Press.	Rate	BBL	Gas MCF	BBL	Gas : O Ratio	.		Vell Stat	us		•		FIELD OFFICE	
(See Instruc	tions and spa	ices for add	ttional data	on reverse si	de)			TIME	166	;				ريمن	· · · · · · · · · · · · · · · · · · ·	

Date First	Ction - Inter Test Date	Hours	Test	Oil	Gas	Water	Oil Gravite	16.	Production Method	,
roduced	Date	Tested	Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Con. API	Gas Gravity		-
hoke ize	Tbg. Press.	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas: Oil	Well Status	h	
	Fiwg. SI) · · · ·		· ·
	ction - Inter		· <u>···</u> ···	·····	······	+				
ate First roduced	Test Date	Hours Tested	Test Production) Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API	Gas Gravity	Production Method	•
	à.				<u> </u>		<u></u>	<u> . </u>	· · ·	· · · · · · · · · · · · · · · · · · ·
hoke ze	Tbg. Press. Flwg. SI	Csg. Press.	24 Hr. Rate	Oil - · BBL	Gas MCF	BBL	Gas : Oil Ratio	Well Status		,
	osition of G	as (Sold, u	sed for fuel	, vented, et	c.)	L				<u></u>
Vent Summ	ary of Poro	us Zones (Include Act	nifere).					on (Log) Markers	
Show tests,	all importation	nt zones or	porsity and	contents th	nercof: Cores , time tool op	d intervals a en, flowing :	nd all drill-stem and shut-in pressures		on (Log) Markers	
and re Form	coveries. ation	Тор	Bottom		Descri	ptions, Cont	ents, etc.		Name	Top
·				+						Meas. Depth
							• • •	Nacimiento		1468
	-		х		• • •	1		Ojo Alamo	-	2555
			;			•		Kirtland		2783
•				l'		·	۰۰,	Fruitland		3188
							, ,	Pictured Cl	iff	3503
	1	-		-			· · · ·	Chacra/Ote	00	4492
			, · ·			•		Cliffhouse		5291
			· · .		-	ć	 	Pt. Lookou	t	5664
	·	· -				:	-	Gallup		6970
	-		-			-		Greenhorn		7651
				Į.		•	1 	Lower Cub	ero	.7885
						e Blanco l	Mesaverde and E	Basin Dakota.	. Wellbore schematic an	d Daily Summary i
			1 *				· · ·			
3. Circle	enclosed at	tachments		- ,		•		· .		
	ectrical/Mec andry Notice					cological Re ore Analysis	1.1	port 4. D	irectional Survey	^o
4. I here	by certify th	at the fore	going and a	ttached info	ormation is c	omplete and	correct as determine	d from all availa	ble records (see attached instr	uctions)*
No	(please pri	ne) C'hrin	tine Guet	artis	• •		Title Ac Ar	Sent for Conc	coPhillips Co	· .
INALLIC	piease pri -	111) <u>Cuus</u>	una Unsu	44,410	1	· <u>····</u> ·······························			2 2 2 2	
Signa	ture	his a	Zmi	<u>inti</u>	, 1	; ;	Date04/	20/2005		· · · · · · · · · · · · · · · · · · ·
Title 18 U States an	J.S.C. Secti d false, ficti	on 101 and tious or fra	Title 43 U. dulent state	S.C. Section ments or re	n 1212, mak presentations	e it a crime f s as to any m	for any person knowi atter within its jurise	ngly and willful liction.	ly to make to any department	or agency of the United
فر	SDI	द्वे ४ हेर् सम्पर्कत्वक	u u u	•			ι,			

4

SAN JUAN 29 6 UNIT #090M

5

۰÷ 🗸

*



Initial Completion

					D	aily	Summa	iry					leaon
API/UWI 300392756000			ARRIBA	State/Prov	AEXICO	INMPM-	gal Location 29N-06\V-1 <u>5-</u>	C la i	, N/S Dist. (1 -1295	ft) -∓ NVS Re .0 ()		V Dist. (ft) E 2325.0	W Ref. W
Ground Elevation (ft) 6595.00)		Spud Date 12/12/	2004	Rig Release Da 12/22/		Latitude (DMS) 36° 43' (45.8	04" N	<u></u>	Longitude	(DMS) 7' 2.7" W		
							100 10 (C)-		•×				
Start Date							Oos Th						
12/24/2004 07:00	TOP O	FCE					(GER PRES) 96' TO 2400'.						' <u>TO 2300'</u> . '
01/02/2005 12:00	HELD TOOL	PRE- SW	-JOB SAFET /I.										
03/21/2005 07:00	GUN. - 7941' TESTE BPM @ RATE 1062 # DAKO PRESS JET. F MESA W/ 1/2	PER W/2 D LII 0 399 TO 2 . 20 TA W SURE NH W VERI SPF	RFORATED 2 SPF. A TC NES TO 774 29 #. STEPF 20 BPM @ 2 MIN 961 #. V/ SLICKWA 5 4092 #. M V/ 4 1/2° COI DE W/3 1/8° 5, 5643' - 56	FROM 7 DTAL OF 2 #. SET PED DOW 431 #. ST 25 MIN 8 NTER @ 1 AX PRES MPOSITE 90 DEGF 49' W/ 1/2	7774' - 7779' \ 78 HOLES (POP OFF (WN RATE TO EPPED DOV 867 #. 30 MIN 1.25 g/mg FR SSURE 4379 ; PLUG. SET REE SELECT	W/ 2 SPF 2 0.34 DI. 5956 #. 40 BPM (VN RATE 1773 # 1773 # 40,000 # #. MAX S PLUG @ FIRE PEI	ED THE DAKC , 7846' - 7855' A. RU ISOLA' BROKE DOW @ 3622 #. STE TO 10 BPM @ PUMPED 1000 # 20/40 CARB SAND CONS & 5870'. TESTE RFORATING (W 1/2 SPF, 57	W/2 SPF, 7 TION TOOL. IN FORMATI EPPED DOW 2022 #. ISI 0 GALS OF 1 OLITE SANE 40 # PER GA ED PLUG TO GUN. PERFO	891' - 7897' RU SCHLU ON @ 4 BPI N RATE TO IP 1764 #. 5 15% HCL AC 0 & 4106 BB L. ISIP 224 4800 #. HEI DRATED FR	W/ 2 SPF IMBERGE M @ 2110 30 BPM @ MIN 1372 DD @ 6 BI SLS FLUID 3 #. FRA LD OK. PE OM 5566'	, 7909' - 7 R. FRAC'I # PUMI 9 2990 # # 10 MIN PM @ 147 AVG RA C GRADIE ERFORATI - 5572' W/	915' W/ 2 S D THE DAK PED PRE P STEPPED I N 1204 #. 1 25 #. FRAC ITE 55 BPN ENT .66. RL ED THE LC 1/2 SPF, 56	SPF, 7928' (OTA. (AD @ 45 DOWN 5 MIN 5 MIN (D THE 1. AVG I BLUE WER 626' - 5632'
03/22/2005 08:00	HELD 3 POP O TO 32 SLICK WITH I PRISS RIH W/ 90 DEC 5346' V FRACT PUMPE STEPP & MEN PROPF 50 BPA RD SC HELD 3 POP O GALS 0 BRAD CONTE	Safe FF (BPM FO/ PRO URE: V 4 1/ GRE W 1/ D TH ED P PED I I. W/ PANT SAFE (SAFE C 5 C 6 C 7 C 7 C 7 C 7 C 7 C 7 C 7 C 7	2 4500 #. F 1 @ 0 #. ISI AM W/ 1 G/N PNET FOR 1927 #. MA 2' COMPOS E SELECT F 2 SPF, 535 E UPPER M RE PAD @ DOWN RATH 65 Q SLICK T VOLUME N VG PRISSU <u>MBERGER</u> TY MEETIN 2 6000 #. F 5% HCL AC ND AND TR 5% ACL AC	IG. RU 5 PUMPED F P 0 #. F MG FR, 12 PROPPA X PRESS IT PLUG. FIRE PER 7' - 5373' IV. TEST 42 BPM (E TO 10 E C FOAM KITH PR (FOAM IG. RU 5 VMPED F IG. RU 5 PUMPED F SCF N2 &	PRE PAD @ 4 PUMPED 100 25,000 # OF NT FLOWBA SURE 2300 #. SET PLUG (RFORATING (W/ 1/2 SPF, ED LINES TC @ 903 #. STEI 3PM @ 0 #. W/ 1 G/MG F OPNET FOR #. MAX PRES FION TOOL. SCHLUMBER PRE PAD @ 1 BPM @ 0 #. HE LAST 15% & 1714 BBLS	42 BPM (0 GALS (16/30 BR/ CK CONT MAX SA @ 5536'. GUN. PEI 5428' - 5 0 5800 #. PPED DC ISIP 0 #. R, 100,00 PROPPA SSURE 3 START F GER & IS 31 BPM (FRAC'D 6 OF TOT FLUID. /	 90 196 #. STEP 97 15% HCL A 96 ADY SAND AN 97 RFOL. 1,520,30 98 ND CONS 1.5 97 TESTED PLUE 98 RFORATED F 9442' W/ 1/2 SI 98 SET POP OFI 98 WN RATE TO 90 PUMPED 10 90 # OF 16/30 96 TH. MAX S 96 WACK. 	PED DOWN ACID @ 10 BI ND TREATED 00 SCF N2 & 5 # PER GAL G TO 4800 # ROM 5278' - 5F @ 4500 #. 9 32 BPM @ : 000 GALS OF BRADY SAN CK CONTRO GAND CONS OL. FRACD PED DOWN MV W/ 65 Q IT VOLUME ' BPM. AVG	RATE TO 37 PM @ 40 #. 0 THE LAST 1420 BBLS . ISIP 819 # HELD OK. 5282' W/ 1/2 521' W 1/2 BROKE DC 335 #. STEF 515% HCL / ID AND TRE L. 1,258,100 1.5 # PER C THE LOWEI RATE TO 25 SLICK FO/ WITH PROP PRISSURE	8 BPM @ 7 FRAC'D 1 15% OF 1 FLUID. A FRAC G PERFOR 2 SPF, 529 SPF. A T OWN FORI 2 SPF, 529 SPF. A T OWN FORI 3 SPF. A T SPF. A T S	76 #. STEF THE POINT TOTAL PR VG RATE RADIENT ATED THE 2' - 5296' \ TOTAL OF WATION @ VN RATE 1 BPM @ C E LAST 1! A 1096 BBL 3789 #. FI STED LINE STED LINE A SIP VMG FR, 7 PROPPAN AX PRESS	PED DOW COOKOU OPPANT \ 45 BPM. A 45 BPM. A 44. RU BL EUPPER M 12 SPF, 38 HOLES 3 3 BPM @ CO 22 BPM 3 4 CO 5 5 CO 7000 0 4. PUM 150,000 # CO 150,000 #	N RATE T W/ 65 Q /OLUME VG UE JET. IV W/3 1/8" , 5336' - 5 W/ 0.34. 1985 #. @ 109 #. 0 THE CH FAL AVG RATE DIENT .44. #. SET PED 1000 DF 20/40 ACK #. MAX
03/23/2005 06:00	5536'. GUN. 5428' - HELD S POP O RATE PUMPE # OF 20 FLOWI 2811 #	TES PER 544: SAFE FF @ TO 2 ED 1 0/40 BACI BACI	TED PLUG 1 FFORATED 2' W/ 1/2 SP ETY MEETIN 0000 #. E 5 BPM @ 49 000 GALS C BRADY SAM K CONTROI	FO 4800 # FROM 52 FF, <u>5505'</u> IG. RU \$ BROK DO' 91 #. STE DF 15% H ND AND T L. 1,501,3	4. HELD OK. 278' - 5282' W - 5521' W 1/ SCHLUMBER WN FORMAT EPPED DOWI ICL ACID @ ^ IREATED TH 100 SCF N2 &	PERFOR 2 SPF. A 3 GER & IS 10N @ 4 N RATE T 13 BPM @ E LAST 1 1112 BB	ATED THE UF F, 5292' - 5296 A TOTAL OF 3	PPER MV W S'W/ 1/2 SPF 18 HOLES W OL. FRACD #. PUMPED 243 #. STEP 2 THE UPPE 2 THE UPPE 2 PROPPANT /G RATE 45	//3 1/8" 90 DE 5, 5336' - 534 / 0.34. SWI / 0.34. SWI PRE PAD @ PRE PAD @ PRE DOWN R MV W/ 65 T VOLUME V BPM. AVG	EGREE SE 46' W/ 1/2 MV. TES 35 BPM RATE TC Q SLICK WITH PRO PRISSUR	ELECT FIR SPF, 5357 E JET. TED LINES @ 936 #. S 0 10 BPM (FOAM W/ PNET FOF E 2693 #.	E PERFOR 7 - 5373' W S TO 7000 # S TEPPED D @ 0 #. ISI 1 G/MG FF R PROPPAI MAX PRES	ATING / 1/2 SPF, // 1/2 SPF, // SPF, // SPF, // SPF, // SURE
WellView®						F	2age 1			Repo	rt genera	ted on 04	¥/19/2005

	Daily Summary
PWW 00392756000	County State/Province Surface Legal Location NS Dist. (ft) NS Ref. EW Dist. (ft) EW Ref. RIO ARRIBA NEW MEXICO NMPM-29N-06W-15-C 1295.0 N 2325.0 W
round Elevation (ft)	Spud Date Rig Release Date Latitude (DMS) Longitude (DMS)
6595.00	
Start Date	Cos This Rot
3/31/2005 07:00	Hold BISA meeting with crews. Talked about conducting safe rig move operations. Talked about possible nazards, and now to
2	laugid those bezards. Outlined general safety topics relating to planned operations. Move Key #11 ng and associated equipment
	onto location. Start rigging up unit and all equipment. L & R located, retested missing anchors under mud. Flowback well thru the choke assembly to reduce pressure. Killed well with 15 bbls of 2% kcl water. Installed tubing hanger assembly with BPV.
۰	Secured lockdown pins. Ninnie down frac valve, spool assembly, Nipple up BOP assembly. Pressure test BOP blind and pipe r
	with a low (250 Pei, 10 min) and a high (2,000 Psi- 30 min.) test, Tests were successful. Rig up floor assembly. Lay bloole lif
-	assembly, set concrete anchors with L & R roustabout crew. Blind rams closed and locked. Drained lines of fluid. Secured less Shutdown operations for the day.
4/01/2005 07:00	
26 ····	Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Kill casing with
	bble of 2% kd water. Remove tubing hanger assembly. Nipple up milling assembly. Install new stripping rubber. Start into well
ŕ.	hut 1-3 875" O X 2 30' Three Bladed Mill, 1-2 3/8" x 1.81' Bit sub, 1-2 3/8" x .90' string float, and 2 3/6" tubing tailed from
, ,	tubing trailer. Tagged fill at 5,510' (26' on bridge plug). Rig up air unit to tubing. Pressure test air lines to 1,400 Psi. Tested good Start air unit at 1,200 CFM with 3 BPH foam/mist. Cleaned out to 5,540'. Well unloaded kill fluid then made light sand and light the sand sand light fluid then made light sand and light sand sand light fluid then made light sand and light sand sand light sand sand sand light sand sand sand sand sand sand sand sand
**	returns' Continued with air until returns were clean and reduced. Shutdown air unit. Rig down off tubing. Pulled 2 3/8" tubing
	above Upper Mesa Verde perfs to 5,190'. Installed TIW valve onto tubing, closed pipe rams. Drained lines. Secured lease.
4/04/2005 07:15	Shutdown operations for the day.
A(04/2000 01110	Hold PISA meeting with crew Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid
	those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Trip into well to tag fill. Tag fill at 5,530' (10' of fill on plug). Rig up air unit, start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out to 5,540'. W
· ·	made light send fluid Continued with air until returns were clean. Shutdown air unit. Rig down on tubing. I noped tubing to 5,
	to test Linner Mesa Verde zone. Rig up flowback line, Installed new 1/2" choke into flowback line. How tested Upper Mesa Verde
	zone (5,278'- 5,521') up tubing/casing annulus to atmosphere thru 1/2" choke. FCP Avg 240 Psi. (Choke coefficient: 6.6) Tes indicated Mesa Verde production at 1,584 MCFPD with 5- Bbls water per day, 0- Bbls of Oil per day, with no sand returns. Te
,	was witnessed by Sergio Sema (Rig Operator). Testing completed. Trip tubing into well to tag fill. Lagged fill at 5,530. Rig up
۰ 	Incruer survey assembly, air unit. Start air at 1 200 CFM with 3 BPH foam/mist, Clean to top of plug. Increased mist to 10 PPH to
· · · · ·	power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blooie lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until actume were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu
	power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blocie lines returns when plug was drilled, well also made light sand, fluid. Continued wit air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu block air dir at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubir
	power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blocie lines returns when plug was drilled, well also made light sand, fluid. Continued wit air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubir above Mesa Verde perfs to 5,190'. Install T/W valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations fo
04/05/2005 06:00	power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blooie lines returns when plug was drilled, well also made light sand, fluid. Continued wit air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubir above Mesa Verde perfs to 5,190'. Install T/W valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations fo day.
04/05/2005 06:00	power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blooie lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubir above Mesa Verde perfs to 5,190'. Install T/W valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations fo day. 0 SICP- 550 Psi Held B ISA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid
04/05/2005 06:00	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blocie lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plug Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubir above Mesa Verde perfs to 5,190'. Install T/W valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations fo day. O SICP- 550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubirs out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' x 2 3
04/05/2005 06:00	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blocie lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install T/W valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations fo day. O SICP- 550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' x 2 3
04/05/2005 06:00	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blocie lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install T/W valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations fo day. O SICP- 550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' x 2 3 Mule shoe, 182' x 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert Silckline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to planet on the slick of 2 mus. 1- with plug pulling tool. Rig down and
04/05/2005 06:00	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blocie lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plug Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP- 550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' x 2 3 Mule shoe, 1 82' x 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert Slickline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plankate plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and related fliw valve unit. Hit tubing with 4 bits 2% kcl water. Removed TIW valve, listall string float. Trip 2 3/8" tubing into the weat a lot of 2 weat and flow and flow and flow and the water to the start of the safe. Trip 2 3/8" tubing into the weat a start of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and the plug pullage unit 4 bits 2% kcl water. Removed TIW valve, install string float. Trip 2 3/8" tubing into the weat a start of the
04/05/2005 06:00	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blocie lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plug Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install T/W valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP- 550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' x 2 3 Mule shoe, 1 82' x 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert Slickline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plaaker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve. Install string float. Trip 2 3/8" tubing into the were slickline unit. The string is to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out the planned operation is the planned operation.
04/05/2005 06:00	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blocie lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plug Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP- 550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 1 -92' x 2 3 Mule shoe, 1 82' x 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert Slickline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to p Baker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve. Install string float. Trip 2 3/8" tubing into the well slig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out to ging up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. C
04/05/2005 06:00	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in blocie lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plug Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install T/W valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP- 550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' x 2 3 Mule shoe, 1 82' x 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert Slickline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plaaker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve. Install string float. Trip 2 3/8" tubing into the were slickline unit. The string is to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out the planned operation is the planned operation.
94/05/2005 06:00	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in bloole lines returns when plug was drilled, well also made light sand, fluid. Continued wit air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. O SICP- 550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' x 2 3 Mule shoe, 182' x 1.81" I.D. x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert Slickline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to p Baker plug from F-Nipple. Made a total of 2 runs. 1 - with pressure disc puncturing tool, 1 - with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve. Install string float. Trip 2 3/8" tubing into the wel 5,870'. Well unloaded kill fluid then made light fluid and light sand. Continued with air mist until returns were clean. Shutdown a unit, pull tubing above Mesa Verde perfs to 5,190': Installed TIW valve, close pipe rams. Secured lease. Shutdown operations unit, pull tubing above Mesa Verde perfs to 5,190': Installed TIW valve, close pipe rams. Secured lease. Shutdown operations
	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top or plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in bloole lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plug Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TiW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations fo day. D SICP-550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' x 2 3 Mule shoe, 182' x 1.81" I.D. x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert Slickline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to pl Baker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve. Install string float. Trip 2 3/8" tubing into the wet tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out 5,870'. Well unloaded kill fluid then made light fluid and light sand. Continued with air mist until returns were clean. Shutdown operations the day.
	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in bloole lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP-550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' × 2 3 Mule shoe, 182' × 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert SIIckline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plaker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve, Install string float. Trip 2 3/8" tubing into the wet tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out 5,870'. Well unloaded kill fluid then made light fluid and light sand. Continued with air mist until returns were clean. Shutdown au unit, pull tubing above Mesa Verde perfs to 5,190'. Installed TIW valve, close pipe rams. Secured lease. Shutdown operations the day.
	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in bloole lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP-550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' × 2 3 Mule shoe, 182' × 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert SIIckline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plaker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve, Install string float. Trip 2 3/8" tubing into the wet tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out 5,870'. Well unloaded kill fluid then made light fluid and light sand. Continued with air mist until returns were clean. Shutdown au unit, pull tubing above Mesa Verde perfs to 5,190'. Installed TIW valve, close pipe rams. Secured lease. Shutdown operations the day.
	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in bloole lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP-550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' × 2 3 Mule shoe, 182' × 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert SIIckline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plaker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve, Install string float. Trip 2 3/8" tubing into the wet tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out 5,870'. Well unloaded kill fluid then made light fluid and light sand. Continued with air mist until returns were clean. Shutdown au unit, pull tubing above Mesa Verde perfs to 5,190'. Installed TIW valve, close pipe rams. Secured lease. Shutdown operations the day.
04/05/2005 06:00	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in bloole lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP-550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' × 2 3 Mule shoe, 182' × 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert SIIckline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plaker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve, Install string float. Trip 2 3/8" tubing into the wet tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out 5,870'. Well unloaded kill fluid then made light fluid and light sand. Continued with air mist until returns were clean. Shutdown au unit, pull tubing above Mesa Verde perfs to 5,190'. Installed TIW valve, close pipe rams. Secured lease. Shutdown operations the day.
· · · · · · · · · · · · · · · · · · ·	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in bloole lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP-550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' × 2 3 Mule shoe, 182' × 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert SIIckline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plaker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve, Install string float. Trip 2 3/8" tubing into the wet tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out 5,870'. Well unloaded kill fluid then made light fluid and light sand. Continued with air mist until returns were clean. Shutdown au unit, pull tubing above Mesa Verde perfs to 5,190'. Installed TIW valve, close pipe rams. Secured lease. Shutdown operations the day.
· · · · · · · · · · · · · · · · · · ·	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in bloole lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP-550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' × 2 3 Mule shoe, 182' × 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert SIIckline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plaker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve, Install string float. Trip 2 3/8" tubing into the wet tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out 5,870'. Well unloaded kill fluid then made light fluid and light sand. Continued with air mist until returns were clean. Shutdown au unit, pull tubing above Mesa Verde perfs to 5,190'. Installed TIW valve, close pipe rams. Secured lease. Shutdown operations the day.
	 power swivel assembly, air unit. Start air at 1,200 CFM with 3 BPH foam/mist. Clean to top of plug. Increased mist to 10 BPH to thru plug. Noticed a slight increase in bloole lines returns when plug was drilled, well also made light sand, fluid. Continued with air/mist until returns were reduced. Shutdown air unit. Trip into well to tag fill on next plug. Tagged fill at 5,840' (30' on 2nd plu Start air at 1,200 CFM with 5 BPH foam/mist. Cleaned out to 5,870'. Shutdown air unit, rig down power swivel. Trip 2 3/8" tubin above Mesa Verde perfs to 5,190'. Install TIW valve, close pipe rams. Drain all lines. Secured lease. Shutdown operations for day. D SICP-550 Psi Hold PJSA meeting with crew. Talked about conducting safe rig operations. Talked about possible hazards, and how to avoid those hazards. Outlined general safety topics relating to planned operations. Blowdown well into flowback pit. Continue tripp 2 3/8" tubing out of the well. Kill casing with 15 bbls of 2% kcl water to trip out last 10 stands. Start into well with 192' × 2 3 Mule shoe, 182' × 1.81" I.D.x 2 3/8" F-Nipple with Baker plug installed, 2 3/8" tubing from derrick. Tripped tubing to 5,062'. Installed TIW valve onto tubing. Rig up Expert SIIckline unit. Pump 3 bbls of 2% kcl water down tubing. Run in with slickline to plaker plug from F-Nipple. Made a total of 2 runs. 1- with pressure disc puncturing tool, 1- with plug pulling tool. Rig down and released slickline unit. Kill tubing with 4 bbls 2% kcl water. Removed TIW valve, Install string float. Trip 2 3/8" tubing into the wet tag fill. Tagged fill at 5,865' (5' of fill on plug). Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Cleaned out 5,870'. Well unloaded kill fluid then made light fluid and light sand. Continued with air mist until returns were clean. Shutdown au unit, pull tubing above Mesa Verde perfs to 5,190'. Installed TIW valve, close pipe rams. Secured lease. Shutdown operations the day.

: •

1^

,

SAN JUAN 2	96 UN	IT #0901	V						Initi	al Com	pletion
				State Contraction		Summa	пу				
API/UWI 300392756000	County RIO A	ARRIBA	State/Province	100	NMPM-	gal Location 29N-06W-15-	c	N/S Dist. (ft) 1295.0	N/S Ref.	E/W Dist. (ft) 2325.0	E/W Ref. W
Ground Elevation (ft) 6595.00)	Spud Date 12/12/2		lg Release D 12/22		Latitude (DMS) 36° 43' 45.8	04" N		Longitude (DMS) 107° 27' 2.7		
Start Date		i in the second	aroson constants			Ops Th	ie Rol	9889767388.65168	ausonation at the		naliatanan an an se
04/06/2005 07:15											
								iked about po Blowdown we			
		•						ibing to unloa Iown air unit.			
	to 5,061' to	test Overal	li Mesa Vero	de zone. I	Kill tubing	with 3 bbls o	f 2% kcl wate	r. Remove st	ring float, ins	tall TIW valve	e and
								d. Flow well υ ridge plug. Τα			
	5,061'. Inst	alled ProTe	chnics spini	ner surve	y logging	tools onto sli	ckline. Flow	tested the Me	esa Verde pe	rfs (5,278'- 5	,768') thru
		•	•	-	•			ce (Choke co Iction enginee	•	•	
								ols. Rig dowr ing rubber. S			2 3/8" tubing " O.D. x
	2.30' Three	Bladed Mill	l, 1- 2 3/8" x	1.81' Bit	sub, 1-2	3/8" x .90' str	ing float, and	2 3/8" tubing			
04/07/2005 07:00	SICP- 550 I	Psi					s for the day.				
								lked about po llowdown wel			to avoid to well to tag
	fill. No fill m	ade on plug	. Rìg up aìr	unit, start	air at 1,20	0 CFM with 3	BPH foam/n	nist. Cleaned Ibing. Tripped	out to 5,870'.	Well unloade	ed about 3
	Verde zone	e. Rig up flo	wback line.	Installed	new 1/2"	choke into flo	wback line. I	Flow tested C	verall Mesa	Verde zone ((5,278'-
		-	-	-		•		ient: 6.6) FCP /ith 5- Bbis wa	•		· · ·
								sting complete CFM with 3	•	-	- A
	Increased r	mist to 10 Bl	PH to mill th	nu plug. N	Noticed a	slight increas	e in blooie lin	es returns wh	en plug was	drilled, well a	ilso made
								utdown air un FM with 5 BF	•		
	Could not g	et any furth	er than 7,93	30'. Possi	ble tight, l	oad spot in ca	asing. Contine	ued with air/m	nist until retur	ns were redu	iced.
	Secured le	ase. Shutde		-			7,000 . Install	I TIW valve, c	lose pipe ran		nes.
04/08/2005 07:00			ng on locati	on. Talke	d about o	onducting saf	e rig operatio	ns. Talked at	out possible	hazards, and	t how to
								ons. Blowdov mbly. Start air			
	Cleaned ou	it to 7,930'. \	Well unload	ed about	3 bbls of f	luid, then ma	de light fluid, l	light sand. Sta	art milling on	bad spot in c	asing at
								u bad area in Shutdown air			
04/11/2005 07:00			TIW valve,	close and	d lock pipe	e rams. Secu	red lease. St	nutdown oper	ations for the	day.	
	Hold PJSA	meeting wit				· · ·		ked about po			
	out of the w	vell. Kill casi	ing with 15 l	bbls of 2	% kcl wate	er to trip out la	ast 10 stands	Continue trip . Out of well	with tubing,	nipple down	milling
								193' x 2 3/8 unloading kill			
	7,980' (15' d	of fill on 7,99	95'). Rig up a	air unit to	tubing. St	art air unit at	1,200 CFM w	ith 3 BPH foa	am/mist. Clea	ned out to 7,	995'. Well
	kcl water to	remove stri	ing float. Dro	opped ba	ll to pump	out expenda	ble check as	n. Shutdown sembly. Reins	stall string floa	at assembly.	Rig up air
								low with air at Resumed air/			
	Psi surface	. Continued	with air/mis	st to clear	n up any f	luid, sand ret	urns. Shutdo	wn air unit, ri	g down off tu	bing. Trip 2 3	3/8" tubing
	above Dako day.				vaive, clo	sea pipe ram	s. Drain all lif	nes. Secured	ease. Shuto	iown operatio	Dris for the
											1974 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 - 1984 -
										1	
WellView®	5.5Q				P	age 3			Report ge	nerated on	04/19/2005

SAN JUAN 29 6 UNIT #090M Initial Completion **Daily Summary** VS Dist. (ft) E/W Dist. (ft) APM NA/ N/S Ref. F/W Ref State/Province Surface Legal Location Coulor NMPM-29N-06W-15-C 300392756000 **RIO ARRIBA** NEW MEXICO 1295.0 2325.0 N W atitude (DMS) ongitude (DMS) Ground Elevation (ft) Soud Date se Date 6595.00 12/12/2004 12/22/2004 36° 43' 45.804" N 107° 27' 2.7" W art Dat One This Po 04/12/2005 07:00 FINAL REPORT SICP- 500 Psi Hold PJSA meeting on location with crews. Outlined general safety topics related to planned operations. and at Blowdown well into flowback pit: Trip 2 3/8" tubing into the well to tag fill. No fill at 7,995". Rig up air unit, start air at 1,200 CFM with 3 BPH foam/mist. Unloaded about 5 bbls of fluid, with light sand. Tripped tubing to 7,670' to test. Install TIW valve, rig up flowback line off of tubing with a new 1/2" choke installed. Flow well up tubing until ProTechnics, slickline unit were rigged up and ready to start test. Ran slickline end of tubing tool and tagged at 7,992'. End of tubing at 7,670'. Installed ProTechnics spinner survey logging tools onto slickline. Flow tested the Dakota perfs (7,774-7,941') thru the spinner tool up the tubing to atmosphere thru a 1/2" choke (Choke coefficient; 6.6), SICP Avg.- 520 Psi, FTP Avg.- 180 Psi. Test was witnessed by Sergio Serna (Rig Operator). Spinner survey results to be verified by Lucas Bazan. Testing completed, check tools to verify data was recorded. Data recorded. Rig down, release ProTechnics and slickline unit. Dakota production results to be determined. Rig down flowback assembly. Trip 2 3/8" tubing to PBTD to unload well. Rig up air unit to tubing. Start air at 1,200 CFM with 3 BPH foam/mist. Unloaded fluid from well, made light Dakota sand. Shutdown air unit. Rig down off tubing. Pull 5 joints of tubing to land. Install tubing hanger assembly with BPV. Land hanger into wellhead; lockdown pins secured. Tubing landed at 7,851.92' K.B. Top of 1.81" I.D. F-Nipple at 7,850.17' K.B. Nipple down BOP, nipple up wellhead. Wood Group tested seals, removed BPV from hanger. Let well flow up tubing while rigging down completion unit and equipment. Shut well in. Location cleaned and secured. Operations completed. Will move equipment off location on 4-13-05. Will notify facilities supervisor of completion of services on 4-13-05 Report generated on 04/19/2005 WellView[®] Page 4