r 🔺			
Form 3160 DEPARTME	ED STATES ENT OF INTERIOR AND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993	
SUNDRY NOTICE AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals		5. Lease Designation and Serial No. SF-078772	
·		6. If Indian, Allottee or Tribe Name	
SUBMIT IN T	RIPLICATE MAR	7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Well X Gas Well Other	0 0 2005	8. Well Name and No. ROSA UNIT #240	
2. Name of Operator WILLIAMS PRODUCTION COMPANY	E. 281.3011.	9. API Well No. 30-039-25031	
3. Address and Telephone No. PO BOX 3102 MS 25-1. TULSA. OK 74101 (918) 573-6254		10. Field and Pool, or Exploratory Area BASIN FRUITLAND COAL	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1900' FSL & 900' FEL, NW/4 SE/4 SEC 01-31N-06W		11. County or Parish, State RIO ARRIBA, NM	
CHECK APPROPRIAT	TE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
X Subsequent Report Plugging Back		New Construction Non-Routine Fracturing	
Final Abandonment	Casing Repair Altering Casing Other <u>Install Pumping Unit & artificial</u>	Water Shut-Off Conversion to Injection lift Dispose Water (Note: Report results of multiple completion	
		on Well Completion or Recompletion Report and Log form.)	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

04-09-2005 Begin MIRU, SD till 4/11/2005.

<u>04-11-2005</u> RU Tefteller, RIH w/ 1.906 GR to 3118', POH, RIH w/ 1.81" BP x 5K shear disc & set in 1.81" F-nipple, POH, load 2 ½" tbg w/ prod water & test 1050#, 5 min= 1000#, 10 min= 950#, 15 min= 900#, no visible leaks @ surface, BO press, RIH & equalize plug, POOH, RIH & retrieve plug. RD Tefteller, complete RU, ND tree, NU BOP, RU floor & tongs. Pull tbg hanger, check for fill, tag 15' in. Estimate top of fill @ 3181', establish circ w/ 12 bph mist. CO to 3193', had 5K to 30K drag coming up, bypass air. Pull 2 ½" tbg up in 7", SDFN, release crew.

<u>04-12-2005</u> TIH from LT to 3081', est circ w/ 12 bph mist. CO to 3190', pulling 5k to 15k over coming up. Continue to work pipe, still dragging, tally on TOOH, 100 jts tbg = 3128.67', 1.81" "F" nipple = 0.92", 1 jt tbg = 31.13', ½" MS = 0.72", total tally on 2 $\frac{34}{22}$ prod string = 3161.44', tbg looks good, no signs of scale. TIH w/ 4 ¾" tooth bit @ 3072', bit take a little weight & fall, acts like were knowking off alum plugs, pull BHA up in 7", PU swivel off rack & hang in derrick, SIWFN, release crew.

		Continue on Back		ī
14.	I hereby certify that the foregoing is true and correct Signed <u>ACL CL ROSS</u> Tracy Ross	Title Sr. Production Analyst	FARMINGTON FIELD OFFICE	
	(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	Date	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



<u>04-13-2005</u> Csg pressure 800 psi, BD to FB tank, TIH from LT, RU power swivel, CO w/ 12 bph mist from 3071' to PBTD @ 3190' (24' in on jt 102), circ clean 1 ¼ hr off bottom, RD swivel, pull BHA up in 7" & WOF, TIH & tag @ 3190', TOH, TIH as follows: 2 ¼" MS, 1.78" F-nipple, 101 jts 2 ¾" tbg, tag up 9' out jt 101 @ 3182', made 8' of fill in 2.25 hr, TOH, TIH w/ 4 ¾" bit, tag fill @ 3179', CO to PBTD @ 3190' w/ 14 bph mist, pull BHA up in 7", SDFN.

<u>04-14-2005</u> Csg pressure 800#, BD to FB tank, TIH from LT & tag @ 3188' (2' of fill), RU power swivel, CO to 3193' w/ 14 bph mist, pump 3-5 bbls sweeps, bypass air, pull BHA up in 7". Flow well nat 2 hr, TIH & tag up (1' of fill), pull BHA up in 7". Flow well nat 2 more hrs. TIH & tag up (1' of fill), total of 4 hr nat flow made 2' of fill. CO 2' of fill to PBTD @ 3193' w/ 14 bph mist, pump 1-5 bbl sweep, bypass air, TOH, rabbit prod tbg on TIH. Land tbg as follows: 2 %", 4.7#, J-55 mud anchor @ 3190', 2 %" x 1.78" F-nipple @ 3163', 99 its 2 %", 4.7#, J-55 tbg, 10', 8' & 4' pup its, 1 it 2 %", 4.7#, J-55 tbg. RD rig floor, ND BOP, NU B-1 adapter & install 2" valve, SDFN.

<u>04-15-2005</u> Csg pressure 800#, BD to FB tank, NU ratigun & flow T, PU rods & TIH as follows: 6' dip tube, 2 x 1.25 x 8 x 12 RHACZ pump w/ top hold down, 4' pony rod, 125- ¼" rods, 8'- 6'- 4'- 2' pony rods, 1.25" x 22' PR w/ 1.5" x 10' long liner, install load cell & rod rotator, seat pump, pump jack not lined up w/ well head, load tbg w/ rig pump & test 500# 15 min, bleed off, stroke pump w/ rig & press to 500# 15 min, bleed off press, turn well over to production department, release rig @ .1530 hrs.

·_`,