Submit 3 Copies To Appropriate District	State of New Mex	X1CO	Form C-103
Office District I	Energy, Minerals and Natur	al Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONCEDIATION	DIMEION	WELL API NO. 30-025- 09073 09194
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION		5. Indicate Type of Lease Federal
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	505	6. State Oil & Gas Lease No. 025432
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name SOUTH EUNICE UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		8. Well Number 43	
1. Type of Well: Oil Well Gas Well Other (Injection)			
2. Name of Operator BRECK OPERATING CORP.		9. OGRID Number 002799	
3. Address of Operator		10. Pool name or Wildcat	
P.O. BOX 911, BRECKENRIDGE, TEXAS 76424		EUNICE 7 RIVERS QUEEN, SO	
4. Well Location			n a . a . d . m.am . H
	1980 feet from the SOUTH) feet from the <u>EAST</u> line
Section 29	Township 22S 11. Elevation (Show whether DR,	Range 36E	NMPM LEA County
	3526 GL		
Pit or Below-grade Tank Application O		B - 10001 B1	
Pit type Steel Depth to Groundwater_			
Pit Liner Thickness: mil	Below-Grade Tank: Volume		nstruction Material
12. Check A	eppropriate Box to Indicate Na	ature of Notice, l	Report or Other Data
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	-
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🔲
. OLL OKALLEK GAGING			
	×	OTHER:	
OTHER: Repair Casing Leak 13. Describe proposed or complete.		ertinent details, and	give pertinent dates, including estimated date
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo		ertinent details, and	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: Repair Casing Leak 13. Describe proposed or complete.		ertinent details, and	
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M.	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50	ertinent details, and e Completions: Att 00-450 in 30 minute	es, resulting in a failed test. Breck Operating
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeen	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on	ertinent details, and e Completions: Att 00-450 in 30 minute this well in order to	es, resulting in a failed test. Breck Operating comply with MIT requirements.
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following sque 1. Set RBP @ 1800'. Dump 1 sx san	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP.	e Completions: Att 00-450 in 30 minute this well in order to	es, resulting in a failed test. Breck Operating comply with MIT requirements. w/tbg & close well in 24 to 48 hrs.
OTHER: Repair Casing Leak 13. Describe proposed or complosed of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following sque 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi.	ectinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH v 6. Rig up.	es, resulting in a failed test. Breck Operating occupily with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer.
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following sque 1. Set RBP @ 1800'. Dump 1 sx san	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi.	oertinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ	es, resulting in a failed test. Breck Operating comply with MIT requirements. w/tbg & close well in 24 to 48 hrs.
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to	octinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run injo	es, resulting in a failed test. Breck Operating comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Pull retainer?
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav cement on top of retainer.	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of	octinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run injo	es, resulting in a failed test. Breck Operating comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Pull retainer!
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of	octinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run injo	es, resulting in a failed test. Breck Operating comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Pull retainer?
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav cement on top of retainer.	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean.	ertinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run inja 10. Run Mi	es, resulting in a failed test. Breck Operating o comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. petion equipments IT & place on injection.
OTHER: Repair Casing Leak 13. Describe proposed or complosed of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following sque 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav cement on top of retainer. 4. Pull out of retainer and reverse tul. On June 27, 2005 AFE's to Repair C	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean.	ertinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run inja 10. Run Mi	es, resulting in a failed test. Breck Operating o comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. petion equipments IT & place on injection.
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and even ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav cement on top of retainer. 4. Pull out of retainer and reverse tults.	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean.	ertinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run inja 10. Run Mi	es, resulting in a failed test. Breck Operating o comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Poll retainer? ection equipments IT & place or injection.
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav cement on top of retainer. 4. Pull out of retainer and reverse tulton June 27, 2005 AFE's to Repair C	rk). SEE RULE 1103. For Multiple IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean. asing Leak were sent to all the work	ortinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run inja 10. Run Mi	es, resulting in a failed test. Breck Operating o comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Pull retainer? Pull retainer? The place on injection.
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav cement on top of retainer. 4. Pull out of retainer and reverse tulton June 27, 2005 AFE's to Repair C Attempt 23 copy of the PLA Supplementary of the PLA Supplementar	IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean. asing Leak were sent to all the work above is true and complete to the be	octinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run inje 10. Run Mixing interest owners	es, resulting in a failed test. Breck Operating o comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. petion equipments IT & place on injection.
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav cement on top of retainer. 4. Pull out of retainer and reverse tulton June 27, 2005 AFE's to Repair C Attempt 23 copy of the PLA Supplementary of the PLA Supplementar	IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean. asing Leak were sent to all the work above is true and complete to the beclosed according to NMOCD guidelines.	octinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run inje 10. Run Mixing interest owners	es, resulting in a failed test. Breck Operating o comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Pull retainer? rection equipments IT & place or injection.
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav cement on top of retainer. 4. Pull out of retainer and reverse tult. On June 27, 2005 AFE's to Repair C Attended to the PLAN Supplement of the PLAN Su	IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean. asing Leak were sent to all the work above is true and complete to the belosed according to NMOCD guidelines TITLE P	ertinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run injulation of the complete th	es, resulting in a failed test. Breck Operating of comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Pull retainer? The place on an injection. and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . ERK DATE July 7, 2005
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a McCorp is proposing the following squeton: 1. Set RBP @ 1800'. Dump 1 sx san (T/cmt @ 1475' by T.S.) Test RB 2. Set cement retainter @ 350' and ensure you can pump into leak. 3. Mix & pump 75 sxs cement. Leav cement on top of retainer. 4. Pull out of retainer and reverse tult. On June 27, 2005 AFE's to Repair Company of the RLM Special Company of the RLM Spe	IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean. asing Leak were sent to all the work above is true and complete to the belosed according to NMOCD guidelines TITLE P	ertinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run injulation of the complete th	es, resulting in a failed test. Breck Operating of comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Pull retainer? The place on an injection. and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . ERK DATE July 7, 2005
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton of the follo	IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean. asing Leak were sent to all the work above is true and complete to the belosed according to NMOCD guidelines TITLE P	ertinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run injulation of the complete th	es, resulting in a failed test. Breck Operating of comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Pull retainer? The place on an injection. and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . ERK DATE July 7, 2005.
OTHER: Repair Casing Leak 13. Describe proposed or complete of starting any proposed wo or recompletion. During our recent attempt to run a M Corp is proposing the following squeton of the starting and the following squeton of the starting of the starting and the starting of the star	IT test the pressure dropped from 50 eze job to repair the casing leak on d on top of RBP. P to 500 psi. stablish rate to e one bbl of bing clean. asing Leak were sent to all the work above is true and complete to the belosed according to NMOCD guidelines TITLE P	ertinent details, and e Completions: Att 00-450 in 30 minute this well in order to 5. POOH 6. Rig up. 7. Test squ 8. Wash sa 9. Run injulation of the complete th	es, resulting in a failed test. Breck Operating o comply with MIT requirements. w/tbg & close well in 24 to 48 hrs. Drill out retainer. neeze to 500#. and off retainer. Pull retainer? ection equipments IT & place on injection. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan ERK DATE July 7, 2005