Submit 3 Copies To Appropriate District State of New Mexico	Form C-103		
Office Energy, Minerals and Natural Resources	May 27, 2004		
	WELL API NO.		
1301 W Grand Ave. Artagia NA 89210 OIL CONSERVATION DIVISION	<u>30-025-35570</u>		
District III 1220 South St Francis Dr	5. Indicate Type of Lease STATE STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
	B-2118		
	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name of Omt Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	LEAMEX		
1. Type of Well: Oil Well 🔲 Gas Well 🗌 Other Injection Well	8. Well Number 058		
2. Name of Operator	9. OGRID Number		
	217817		
	10. Pool name or Wildcat		
	Maljamar, GB/SA		
4. Well Location			
	2130 feet from the <u>East</u> line		
Section 24 Township 17S Range 33E	NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4104'GL, 4118.25' RKB	A CONTRACTOR OF THE OWNER OF THE		
Pit or Below-grade Tank Application or Closure			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance	ice from nearest surface water		
	struction Material		
12. Check Appropriate Box to Indicate Nature of Notice, R			
12. Check Appropriate Box to indicate Nature of Notice, K	eport of Other Data		
NOTICE OF INTENTION TO: SUBS	EQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL			
PULL OR ALTER CASING DIMULTIPLE COMPL CASING/CEMENT.			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and a	zive pertinent vales, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac	ch wellbore diagram of proposed completion		
or recompletion.			
07/29/2005 – Arrived on location, hold safety meeting. MIRU Pool DD unit. SDFN.	A CHARTER AND AN		
and a second start of the start of the second			
08/012005 - Arrived on location, hold safety meeting. Install blowdown line to frac tank, blo hole with 10# brine, install BOP. POOH with tubing and packer. GIH w/4.75" bit & drill col Envirovat pump broke down. SDFN.	w well down. Unseat packer and circulate llars and work string, run 20 stands.		
08/02/2005 Arrived on location hald a fit of the state of			
08/02/2005 - Arrived on location, hold safety meeting. Continue GIH w/drill bit, drill collars, drill from 4,499' to 4,660' and circulate hole clean. POOH w/work string, collars, and drill b	, and tubing. RU reverse circulating unit and		
SDFN.	it. Kill w/10 stands of tubing, close well in.		
(CONTINUED ON BACK*		
I hereby certify that the information above is true and complete to the best of my knowledge a grade tank has been/will be constructed or closed according to NMOCD guidelines \Box , a general permit \Box or	and belief. I further certify that any pit or below- an (attached) alternative OCD-approved plan .		
SIGNATURE Kennett M. Inderse_TITLE SHEAR Specialist			
	DATE <u>08/08/2005</u>		
Type or print name Kenneth N. Andersen E-mail address: ken.n.andersen@conocophil	lips.com, Trelatorie No. 505.391.5569		
Type or print name Kenneth N. Andersen E-mail address: ken.n.andersen@conocophillips.com, Triantike No. 505.391.5569 For State Use Only ADATE 5 2005			
APPROVED BY: Law (1) Win bog FIELD REPRESENTATION	Atl Onto Maria		
Conditions of Approval (if any):	AUSTE 5 2005		

APPROVE	DBY:	9N	an	-
Conditions	of Appro	val (if any	3

ADSTE	5 2	005
---------	-----	-----

LEAMEX # 058

08/03/2005 – Arrived on location, hold safety meeting. RU tubing testers and test tubing to 4,500 psi while GIH w/treating packer and 2 3/8" work string. Tubing tested OK. Lower tubing to 4,550' to spot acid across perfs. MI Schlumberger, hold tailgate safety meeting. RU Schlumberger and test all lines to 4,500 psi. Spot 2 bbls of acid across the perfs, then pull tubing and set packer @ 4,260'. Acidize Grayburg perfs @ 4,344'-4,553' w/6,000 gal of 15% NEFE HCL using 280 (7/8", 1.3 S.G.) Bioballs spaced evenly throughout treatment. Started treatment @ 5 bbls/min, pressure built up and held @ 4,000 psi, pressure broke to 2,900 psi, rate increased to 7 bbls/min, pressure built up to 4,,200 psi, reduced rate to 5 bbls/min, final pressure 3,800 psi @ 5 bbls/min, flushed acid to perfs with water. Total load including acid is 172 bbls. ISIP is 2,824 psi; 15 min later pressure is 1,918 psi. RD Schlumberger. Wait 1 hour, SIP is 1,500 psi. Installed choke in line and flow well back to frac tank, recover 70 bbls load water and spent acid in 5 hours. Close well in. SDFN.

08/04/2005 - Arrived on location, hold safety meeting. Tubing pressure is 600 psi, bleed pressure down to frac tank. Circulate well clean w/110 bbls of 10# brine. Unseat packer and POOH w/work string and treating packer, laid down 137 jts tubing. RU tubing testers & GIH w/packer and 137 jts IPC tubing, replaced top joint due to corrosion. RD tubing testers. Close well in. SDFN.

08/05/2005 - Arrived on location, hold safety meeting. ND BOP, NU well head. Circulate packer fluid to surface and set Guiberson G-6 packer @ 4,268' w/10 points tension. Connected chart recorder to annulus and perform casing integrity test on annulus for NMOCD inspector (Johnny Robinson) to 500 psi for 30 min, tested OK.

Chart enclosed

