Form 3160-5 (August 1999)						
	UNITED STATES ARTMENT OF THE INT REAU OF LAND MANGE		FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000 5. Lease Serial No. NMSF - 078513			
SUNDRY N Do not use this	OTICES AND REPORT form for proposals to driv Use Form 3160-3 (APD)	NMSF - 07851				
SUBMIT IN TRIPLIC	CATE – Other inst			Agreement, Name and/or No.		
Type of Well Oil Well	Gas Well Othe	JUL 3	8. Well Name an Arnaud A 3S			
Name of Operator AMERICA PRODUCTIO	N COMPANY	Convers	9. API Well No.			
Address D BOX 3092 HOUSTON, T	3b. Phone X 77253 281-366-4	~ //	10. Field and Pool, or Exploratory Area Basin Fruitland Coal			
Location of Well (Footage, Se 940' FSL & 1820' FEL; S			11. County or Parish, State SAN JUAN, NM			
12. CHEC	CK APPROPRIATE BOX	(ES) TO INDICATE NATUR	E OR NOTICE, REPORT, OR	OTHER DATA		
TYPE OF SUBMISSION		1	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen Fracture Treat	Production (Start/Resur	ne) 📮 Water shut-Off 🖵 Well Integrity		
	Casing Repair	New Construction	Recomplete	Other Add Liner		
Subsequent Report	Change Plans	Plug and Abandon	Water Disposal			
Final Abandonment Notice	Convert to Injectio	n 🖵 Plug Back				

3. Describe reprosed of completed operation (crearly state an permitted details, including estimated stating date of any proposed work and approximate duration interval. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

BP America Production Company requests permission to run 5.5" liner as per the attached procedure.

Should you have any questions please call Tom Boyce @505-326-9453

14. I hereby certify that the foregoing is true an dcorrect Management of the foregoing is true and correct Management of the foregoing is sued stipulations.	
Cherry Hlava	Title Regulatory Analyst
Signature (Livright lava	Date 07/15/2005
THIS SPACE FOR FEDE	RAL OR STATE OFFICE USE
Approved by	Title Petr. Enc Date 7/240/05
Conditions of approval, Kany, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter witin its jurisdiction.

1

Arnaud A 3S API # **3004531428** Sec 20 - T32N - R9W San Juan County, NM Contact: Tom Boyce 505-326-9453 office 505-326-9262 fax 970-420-4150 cell

Objectives: Clean out open hole, run blank liner

Procedure:

- 1. Check location, ID wellhead, and verify rig anchors are in place & tested.
- 2. Check and record tubing, casing, and bradenhead pressures. Rig up slickline unit. Set blanking plug in 1.78" F nipple at 3475', blow down tubing to verify plug is holding. Set second blanking plug in 1.87" "X" nipple at 3470'. RD slickline. LOTO meter run, separator, water line, and automation.
- 3. MIRU drilling rig.
- 4. Blow down casing to flare pit to minimize casing pressure. The operations of removal of wellhead and installation of BOP will be performed under a dispensation for one (1) barrier on the backside. ND wellhead, NU BOP stack and stripping head. Make sure adequate space exists between pipe rams and stripping rubber to "swallow" tubing hanger. Set test plug in tubing hanger and pressure test stack to 200 psi low, 1000 psi high. Run chart.
- 5. Blow down casing to minimize pressure. Screw handling sub into tubing hanger and secure stripping rubber. Unseat tubing hanger and pull to bottom of stripping rubber; close pipe rams. Relieve pressure above pipe rams and strip hanger above stripping head. Remove hanger. POH, laying down 2.375" tubing. Send tubing to yard for inspection.
- 6. TIH with 6.25" bit, string float, 4.75" collars, and 3.5" drill pipe. Clean out to original TD of 3753' using foam. Do not deepen below 3753'.
- 7. When returns are clean, pull above 7" shoe, and let well flow to pit for 1-2 hours without air circulation. When stable, RIH and tag for fill. If relatively minor fill

is encountered, run liner per step 9. If considerable fill is found, repeat clean out as above. · · · ·

- 8. When hole is stable, pick up and run liner assembly (listed top to bottom):
 - 1. Baker 5.5" x 7" liner hanger
 - 2. 5.5" 15.5# J-55 Hydrill 511 liner
 - 3. 5.5" X-over nipple
 - 4. 6.25" Rock Bit
- 9. Circulate liner down as required to reach TD of 3753'. Set liner hanger to provide 50'-80' overlap. TOH, LD drill string and liner setting tools.

. .

- 10. Land tubing hanger in wellhead with 2 way back pressure valve in place, tighten hold down screws. Nipple down BOP, nipple up wellhead.
- 11. Rig down, move out drilling rig.

and the second · · · · · · . •

· · · · · · ·

• • •

-. . ۱.

· . and the second 4 . .

33.1

Country Region: Bus: Unit:	UDA3S UNITED STATES County: GAN JUAN NORTH AMERICA State. NEW MEX ONSHORE US District: FARMING WESTERN SAN JUAN SOUTH BASIN-FRUITLAND COAL GAS POOL	ICO Even TON Even Objec	l Start: 12/6/ L End: 12/17	/2003 .BORE CLEAN OUT	Wellbore: Top TMD Bottom TMD. Spud. 6/16/200	он 0.0 h 3,750,0 h	Ong KB Elev: Ground Elev: KB to GL: Mud Line Elev:	6,782 00 ft 6,771.00 ft 11.0 ft 0.00 ft
[Tubing/CT/SS Components	Min ID	Too	Wellsket	ch (Perf In	erval / SPE / Pt	asing
110 - TUE 1 - PROF 1 - TUBIN 1 - PROF	Tubing/CT/SS Components IO HANGER, 2.375 BING, 2.375, 4.7#, J-55, EUE-BC TLE TOOL, 2.375 NO SUB, 2.375 X 4 FT TLE TOOL, 2.375 SHOE, 2.375	Min ID 1.995 in 1.995 in 1.995 in 1.970 in 1.995 in 1.780 in 2.041 in	Top. 11.0 ft 12.0 ft 3,481.9 ft 3,482.9 ft 3,487.9 ft			Perfin	erval / SPE / Pi	asing