

DISTRICT I
1625 French Drive Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-01450

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

B-2148

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

1 Type of Well:

OIL

GAS

WELL ☐

WELL ☐

OTHER WIW

2. Name of Operator

The Wiser Oil Company

8. Well No.

30

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line

Section 17 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4211' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Surface Casing: 10-3/4" set @ 250'

Production Casing: 7" set @ 4502' 11.60#

Perforations: 4238'-4460' CIBP @ 4112'

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

1. MIRU unit. Spot 50' plug on CIBP @ 4112'

2. Tag cmt. plug.

3. Circulate abandonment mud.

4. Spot 50' cmt. plug @ 2620'.

5. Tag cmt. plug.

6. Spot 50' cmt. plug @ 1620'

7. Tag cmt. plug.


8. Perforate csg. @ 260' and circulate cmt. to surface. Leave a 50' cement plug @ 260' to 210'.

9. Tag cement.

10. Spot 50' cmt. plug to surface.

11. Install dry hole marker.

12. Clean location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TYPE OR PRINT NAME Mike Jones

TITLE Prod. Supt.

DATE April 1, 2003

TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

OC FIELD REPRESENTATIVE II/STAFF MANAGER

TITLE

DATE

APR 04 2003