Submit 3 Copies to Appropriate District Office

.,

State of New Mexico Energy Minerals and Natural Resources Department

_

District Office	Energy, Minerals and Natural Resources Department		Form C-103 Boursed Marsh 25, 1000		
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 OIL CONSERVATION DIVISION DISTRICT II 811 South First, Artesia NM 88210 P.O. Box 2088			Revised March 25, 1999 WELL API NO. 30-025-23695		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe. New Mexico		5. Indicate Type of Lease		
DISTRICT IV 2040 South Pacheco, Sante Fe, NM 875			STATE FEE 6. State Oil & Gas Lease No.		
2040 South Facheco, Same Fe, NW 87.	000		8055		
(DO NOT USE THIS FORM FO	NOTICES AND REPORTS ON V R PROPOSALS TO DRILL OR TO DEEP	ELLS			
DIFFERENT R	ESERVOIR. USE "APPLICATION FOR	PERMIT"	7. Lease Name or Unit Agreement Name		
	ORM C-101) FOR SUCH PROPOSALS)		North Vacuum Abo Unit		
1. Type of Well: Oil	Gas				
Well 2. Name of Operator	Well Other Injecto		8. Well No.		
-	oil Corporation		155		
3. Address of Operator P.O. Box			9. Pool name or Wildcat		
Housto	n TX 772	210-4358	Vacuum;Abo, North		
4. Well Location Unit Letter D	560 Feet From The North	Line and 560	Feet From The West Line		
Section 23					
Section 23	Township 17-S	Range 34-E er DR, RKB, RT, GR, etc.)	NMPH Lea County		
	GR 4034	<i></i>			
11 Checl	k Appropriate Box to Indicate	Nature of Notico D	Conort or Other Data		
	INTENTION TO:	-	EQUENT REPORT OF:		
PERFORM REMEDIAL WORK		REMEDIAL WORK			
		COMMENCE DRILLIN	NG OPNS. DPLUG & BANDOWENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND C	EMENT JOB		
OTHER:		OTHER: Return wel	I to injection 👩 🗜 🐂 🙀		
12. Describe proposed or completed op work) SEE RULE 1103. (For Mu	perations. (Clearly state all pertinent details,	and give pertinent dates, inclu-	ding estimated date distarting any proposed		
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Return well to injection 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date desarting and proposed completion) Image: Set Rule 1103. (For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion) 4/21/03 Drive Crew & WSU to location. Spot rig & wait on rig mats. RU WSU. SDFN 4/22/03 Drive crew to location. Hold safety meeting, inspect rig, check H2S monitor. Unflange wellhead. NU BOP & test of well wait on FL, racked 2-3/8" Tbg on rack. Started in hole w/ Ret head, PU 94 Jts tbg & tagged @ 3020'. Install Tbg stripper. Wash out sand, work on unsetting RTBP for 1-1/2 hrs. RTBP came loose, remove tbg stripper. POOH w/ 9 Jts. Tubing elevators broke. Close well in. SDFN 4/23/03 Drive crew to location. Hold safety meeting, inspect rig, check H2S monitor. Open well & POOH w/ Tbg, Ret head & RTBP. Close well in. SDFN 4/24/03 Drive crew to location. Hold safety meeting, inspect rig, check H2S monitor. Open well & POOH w/ Tbg, Ret head & RTBP. Close well in. SDFN 4/24/03 Drive crew to location. Hold safety meeting, inspect rig, check H2S monitor. Open well & POOH w/ Tbg, Ret head & RTBP. Close well in. SDFN Wind blowing too hard.					
4/22/03 Drive crew to location	. Hold safety meeting, inspect rig	, check H2S monitor. I	Inflange wellhead, NUROP & test OK		
Wait on FL, racked 2-3/8" Tbg on rack. Started in hole w/ Ret head, PU 94 Jts tbg & tagged @ 3020'. Install Tbg stripper.					
Wash out sand, work on unsetting RTBP for 1-1/2 hrs. RTBP came loose, remove tbg stripper. POOH w/ 9 Jts. Tubing elevators broke. Close well in. SDFN					
4/23/03 Drive crew to location. Hold safety mosting inspect via shark H2C marity of the Boow (The Property of the Book (The Property of the Book (The Property of the Book (The Property of the Boow (The Property of the Book (The Book (The Property of the Book (The Book (Th					
RTBP. Close well in. SDFN Wind blowing too hard.					
4/24/03 Drive crew to location. Open well, no pressure. POOH w/ kill string. RIH w/ Ret tool & Tbg, continue PU Tbg from rack. PU Total 246 Jts. Latch onto RTBP, open bypass. Well had 1000 # PSI below RTBP. Flow well to vac truck. FB					
100 BBLS in 1 Hr. Unset RTBP, RD vac truck. Close well in. SDFN					
SEE ATTACHMENT FOR ADDITIONAL REMARKS					
I hereby certify that the information above is true and					
SIGNATURE Jiffany Ste	bbus	Staff Office Assistant	DATE 05/13/2003		
TYPE OR PRINT NAME Tiffany A. Ste	ebbins		TELEPHONE NO. (713) 431-1207		

(This space for State Use)	
APPROVED BY Hauge W. Winks	TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGERAY 1 9 2003
CONDITIONS OF APPROVAL IF ANY	л.

Submit 3 Copies to Appropriate District Office DISTRICT I	ATTACHMENT State of New Mexico Energy, Minerals and Natural Resources Department	Form C-103 Revised March 25, 1999				
1625 N. French Dr., Hobbs, NM 88240 <u>DISTRICT II</u> 811 South First, Artesia NM 88210 <u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410 <u>DISTRICT IV</u> 2040 South Pacheco, Sante Fe, NM 87505	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088	WELL API NO. 30-025-23695 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 8055				
CONT USE THIS FORM FOR DIFFERENT RES (FOR 1. Type of Well: Oil Well	7. Lease Name or Unit Agreement Name North Vacuum Abo Unit					
2. Name of Operator	Well Other Injector	8. Well No.				
Exxon Mobil	-	155				
3. Address of Operator P.O. Box 43	58	9. Pool name or Wildcat				
Houston	TX 77210-4358	Vacuum;Abo, North				
4. Well Location Unit Letter : 56	0 Feet From The North Line and 560	Feet From The Line				
Section 23	Township 17-S Range 34-E	NMPH Lea County				
	10. Elevation (Show whether DR, RKB, RT, GR, etc.) GR 4034					
Additional Remarks						

4/25/03 Drive crew to location. Hold safety meeting, inspect rig & check H2S monitor. 1000 # PSI on Tbg & Csg. RU pump truck, pumped 200 BBLS down Tbg & out Csg into a vac truck. Started to TOH w/ 246 jts Tbg & RTBP. TIH W-458 "A-3" Lok-Set Ret, Csg, Pkr W/"FL" 4.5" X 1.5" X 2-3/8", On & Off Tool & 43 stands. Find out Csg on Btm 1s 17# Csg. TOH W-Pkr. RIH with kill string. Close well in. SDFWE

4/28/03 Drive crew to location. Hold safety meeting, inspect rig, check H2S monitor. Check pressure, well had 300# PSI. Bled well down to vac truck. POOH with kill string. RIH W-5-1/2" Lok-Set Pkr, FL Tool, & 260 Jts of 2-3/8 Tbg. RU pump truck to pump brine down Csg to kill well. Tag Btm @ 8452'. PU two next collars & set Pkr @ 8436'. Test Csg to 600# PSI for 30 min. Rel FL Tool & circ 190 BBLS of Brine water & Pkr Fluid. Latch on to Profile. Close well in. SDFN

4/29/03 Drive crew to location. Hold safety meeting, inspect rig, check H2S monitor. Bleed well down to vac truck. ND BOP, install tree. Pump truck pressured up on Csg, held Ok. RD pump truck. RD WSU & clean location. MO WSU. SDFN

5/13/03 Ran MIT chart, witnessed by NM OCD representative Johnny Robinson. Original chart with Johnny Robinson. Returned well to injection.

Time	Tubing	Production Casing	Surface Casing
Initial	660	340	0
15 Min.	660	355	0
30 Min.	660	360	0

