Submit 3 Copies To Appropriate District Office State of Nev		Form C-103
District Energy, Minerals and 1625 N. French Dr., Hobbs, NM 87240	Natural Resources	WELL API NO.
District II	TON DRIVEN	30-025-20327
811 South First, Artesia, NM 87210 OIL CONSERVAT  District III 2040 South	,	5. Indicate Type of Lease
1000 RIO BIAZOS Rd., Aziec, NM 87410		STATE X FEE
District IV Santa Fe, NI 2040 South Pacheco, Santa Fe, NM 87505	WI 8/303	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WI	CLIC	E-8160
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-1 PROPOSALS.)	R PI LIG BACK TO A	7. Lease Name or Unit Agreement Name:
1. Type of Well: Oil Well Gas Well Other Water In	jection	Mesa Queen
2. Name of Operator Xeric Oil & Gas Corpora	ation	8. Well No.
3. Address of Operator P. O. Box 352		9. Pool name or Wildcat
4. Well Location Midland, TX 79702		Mesa Queen Associated
11-34 -w H 2210 a a . N1		
ine and 330 reet from the Last line		
Section 17 Township 16S	Range 32E	NMPM Lea County
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4359 DF		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:	SUBS	EQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	COMMENCE DRILL	
PULL OR ALTER CASING   MULTIPLE	CASING TEST AND	ABANDONMENT   O
COMPLETION	CEMENT JOB	
OTHER:  12. Describe proposed or completed operations. (Clearly state all	OTHER:	e pertinent dates, including estimated date
COMPLETION	OTHER:	e pertinent dates, including estimated date wellbore diagram of proposed completion
OTHER:  12. Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.	OTHER:	wellbore diagram of proposed completion
OTHER:  12. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit.	OTHER:	e pertinent dates, including estimated date wellbore diagram of proposed completion
OTHER:  Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag.	OTHER:	wellbore diagram of proposed completion
OTHER:  12. Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag.	OTHER: Il pertinent details, and give ple Completions: Attach	wellbore diagram of proposed completion
OTHER:  Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down.	OTHER: Il pertinent details, and give ple Completions: Attach	wellbore diagram of proposed completion
OTHER:  Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag.	OTHER: Il pertinent details, and give ple Completions: Attach	wellbore diagram of proposed completion
OTHER:  12. Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface.	OTHER: Il pertinent details, and give ple Completions: Attach	wellbore diagram of proposed completion
OTHER:  Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.	OTHER: Il pertinent details, and give ple Completions: Attach	wellbore diagram of proposed completion
OTHER:  Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multior recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.  THE COMMISSION HOURS PRIOR TO	OTHER: Il pertinent details, and give ple Completions: Attach	wellbore diagram of proposed completion
OTHER:  Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.  THE COMMISSION HOURS PRIOR TO PLUGGING OPERA	OTHER: Il pertinent details, and give ple Completions: Attach of the Completions of the Completions of the BEGINNING CATIONS FOR THE C-10	wellbore diagram of proposed completion
OTHER:  Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.  THE COMMISSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.	OTHER: Il pertinent details, and give ple Completions: Attach of the Completions of the Completions of the Beginning of the Beginning of the Beginning of the C-10	wellbore diagram of proposed completion
OTHER:  Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.  THE COMMISSION HOURS PRIOR TO PLUGGING OPERA	OTHER: Il pertinent details, and give ple Completions: Attach of the Completions of the Completions of the Beginning of the Beginning of the Beginning of the C-10	wellbore diagram of proposed completion
OTHER:  12. Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.  THE COMMISSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.  I hereby certify that the information above is true and complete to SIGNATURE	OTHER: Il pertinent details, and give ple Completions: Attach of the Completions of the Details of the BEGINNING CATIONS FOR THE C-10 the best of my knowledge	wellbore diagram of proposed completion  A 2 3 4 5 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
OTHER:  12. Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.  THE COMMISSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.  I hereby certify that the information above is true and complete to SIGNATURE	OTHER: Il pertinent details, and give ple Completions: Attach of the Completions of the Completions of the BEGINNING OF THE BEGINNING OF THE C-10 of the best of my knowledge	and belief.  DATE  5/27/03  915-683-3171
OTHER:  12. Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.  THE COMMISSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.  I hereby certify that the information above is true and complete to SIGNATURE	OTHER: Il pertinent details, and give ple Completions: Attach of the Completions of the Completions of the BEGINNING OF THE BEGINNING OF THE C-10 of the best of my knowledge	and belief.  DATE 5/27/03
OTHER:  12. Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.  THE COMMISSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.  I hereby certify that the information above is true and complete to SIGNATURE  Angle Crowford  Type or print name  (This space for State use)	OTHER: Il pertinent details, and give ple Completions: Attach of the Completions of the BEGINNING ON THE BEGINNING ON THE C-10 the best of my knowledge.  E Production An	and belief.  DATE  915-683-3171  Telephone No.
OTHER:  12. Describe proposed or completed operations. (Clearly state al of starting any proposed work). SEE RULE 1103. For Multi or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.  THE COMMISSION HOURS PRIOR TO PLUGGING OPERATO BE APPROVED.  I hereby certify that the information above is true and complete to SIGNATURE  Angle Crowford  Type or print name  (This space for State use)	OTHER: Il pertinent details, and give ple Completions: Attach of the Completions of the Completions of the BEGINNING OF THE BEGINNING OF THE C-10 of the best of my knowledge	and belief.  DATE  915-683-3171  Telephone No.

## XERIC OIL & GAS CORP. WELLBORE DIAGRAM

WELL: Mesa Queen Unit #5
COUNTY: Lea
STATE: NM

HOLE SIZE: 11"

CASING: 85/8"@368'

CEMENTED WITH: 2005X

CEMENT TOP: Surt.

TUBING: \_\_\_\_

PUMP : \_\_\_\_

PACKER:

HOLE SIZE: 77/8"

CASING: 5/2" @ 34/08

CEMENTED WITH: 1255X

CEMENT TOP: 2746

PERFS:

3404 - 10'

PBTD: 3454'

TD: 3474'