Office	State of New Mexico			Form C-103 Revised March 25, 1999
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 87240		WELL API NO.	· · · · · · · · · · · · · · · · · · ·	
District II 811 South First, Artesia, NM 87210	OIL CONSERVATION D	IVISION	5 Indiana Thurse C	30-025-30295
District III	2040 South Pacheco		5. Indicate Type of STATE X	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8750	5	6. State Oil & Gas	
2040 South Pacheco, Santa Fe, NM 87505			B-9613	
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)  1. Type of Well: Oil Well Gas Well			Jnit Agreement Name HIDE QUEEN UNIT 84910	
2. Name of Operator SAGA PET	OtherWIW CROLEUM LLC		8. Well No. 135	
3. Address of Operator 415 W W			9. Pool name or Warn Dollarhide Queen	ildcat
4. Well Location				
Unit Letter F : 2100 feet from the NORTH line and 1630 feet from the WEST line				
Section 32	Township24S Ra	inge 38E	NMPM	CountyLEA
	10. Elevation (Show whether DR, 3167			
	Appropriate Box to Indicate Na	ture of Notice, I	Report or Other D SEQUENT REP	ata
PERFORM REMEDIAL WORK	NTENTION TO:  PLUG AND ABANDON	REMEDIAL WOR		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	ILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AI CEMENT JOBS	ND	
OTHER:		OTHER:MIT		X
12. Describe proposed or complet of starting and proposed wor or recompletion.  OCD press test failure - HIT reparations.	ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple Cuired as follows its dwn. POOH w/18 ft of the 21st i	tinent details, and g Completions: Attach	a diagram of proposed	ncluding estimated date
12. Describe proposed or complete of starting and proposed wor or recompletion.  OCD press test failure - HIT reparts to the failure of the f	k). SEE RULE 1103. For Multiple (	tinent details, and good completions: Attach t - PU 5-1/2" WP wog, POOH w/remain its. Replaced w/ ne ran chart 500#, 8 m	n diagram of proposed y/OS w/extension 16' nder of tbg & LD pkr. w. RD Tbg Testers. in. Good chart & a 3	ncluding estimated date di completion bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH.
12. Describe proposed or complet of starting and proposed wor or recompletion.  OCD press test failure - HIT reparts to 5-27-03 thru 6-2-03 Tbg part 20 jts tbg, RIH w/OS collar, catch fix well dn. RU Basin Testers, test it Test csg to 500# 15 min. Unset prepare to 500# & in 9 mins hold. POOH w/pkr, replace w/reno hold. PUH & look for csg leak	k). SEE RULE 1103. For Multiple of the day of the 21st just dwn, POOH w/18 ft of the 21st just, POOH w/tbg & FT, LD parted the polymer of the polymer of the 200 ft of the 21st just of the 21st just, POOH w/tbg & FT, LD parted the polymer of the 200 ft of the 21st just of the 21	tinent details, and good completions: Attach t - PU 5-1/2" WP wog, POOH w/remain its. Replaced w/ ne ran chart 500#, 8 m phole w/ same resulpsi chart-held ok. R	diagram of proposed of the control o	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. 1g to 500 psi-will not 1t pkr, press to 500 psi- 1525', set pkr, NUWH,
12. Describe proposed or completed of starting and proposed work or recompletion.  OCD press test failure - HIT reparts to 5-27-03 thru 6-2-03 Tbg part 20 jts tbg, RIH w/OS collar, catch fix well dn. RU Basin Testers, test it Test csg to 500# 15 min. Unset jt Repressure to 500# & in 9 mins it hold. POOH w/pkr, replace w/reno hold. PUH & look for csg leak dump 20-10 lb cans of diamond starting and starting	k). SEE RULE 1103. For Multiple of the day of the 21st just dwn, POOH w/18 ft of the 21st just, POOH w/tbg & FT, LD parted the polymer of the polymer of the 200 ft of the 21st just of the 21st just, POOH w/tbg & FT, LD parted the polymer of the 200 ft of the 21st just of the 21	tinent details, and good to a public to a	diagram of proposed of the control o	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. 1g to 500 psi-will not 1t pkr, press to 500 psi- 1525', set pkr, NUWH,
12. Describe proposed or completed of starting and proposed work or recompletion.  OCD press test failure - HIT reparts to 5-27-03 thru 6-2-03 Tbg part 20 jts tbg, RIH w/OS collar, catch fix well dn. RU Basin Testers, test it Test csg to 500# 15 min. Unset jt Repressure to 500# & in 9 mins it hold. POOH w/pkr, replace w/reno hold. PUH & look for csg leak dump 20-10 lb cans of diamond starting and starting	k). SEE RULE 1103. For Multiple of the day of the 21st j is dwn, POOH w/18 ft of the 21st j ish, POOH w/tbg & FT, LD parted the nhole 7000# below slips busted 17 jokr circ pkr fluid 120 bbls. Set pkr is lost from 500# to 400#. Move pkr u dressed pkr. RIH w/5 stds, run 500 k, HIC @ 575' from surface. RIH w/5 seal.	tinent details, and good to a public to a	diagram of proposed of OS w/extension 16' oder of tbg & LD pkr. w. RD Tbg Testers. in. Good chart & a 3 lts. Attempt to test cs. IH w/5 more stds, setging. RU swab FL to 2000 of the control of the cont	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. 1g to 500 psi-will not 1t pkr, press to 500 psi- 1525', set pkr, NUWH,
12. Describe proposed or completed of starting and proposed work or recompletion.  OCD press test failure - HIT reparts to 5-27-03 thru 6-2-03 Tbg part 20 jts tbg, RIH w/OS collar, catch fix well dn. RU Basin Testers, test it Test csg to 500# 15 min. Unset jt Repressure to 500# & in 9 mins it hold. POOH w/pkr, replace w/reno hold. PUH & look for csg leak dump 20-10 lb cans of diamond starting and starting	k). SEE RULE 1103. For Multiple of the day of the 21st j is dwn, POOH w/18 ft of the 21st j ish, POOH w/tbg & FT, LD parted the nhole 7000# below slips busted 17 jokr circ pkr fluid 120 bbls. Set pkr is lost from 500# to 400#. Move pkr u dressed pkr. RIH w/5 stds, run 500 k, HIC @ 575' from surface. RIH w/5 seal.	tinent details, and good to a public to a	diagram of proposed of OS w/extension 16' oder of tbg & LD pkr. w. RD Tbg Testers. in. Good chart & a 3 lts. Attempt to test cs. IH w/5 more stds, setging. RU swab FL to 2000 of the control of the cont	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. 1g to 500 psi-will not 1t pkr, press to 500 psi- 1525', set pkr, NUWH,
12. Describe proposed or completed of starting and proposed work or recompletion.  OCD press test failure - HIT reparts to 5-27-03 thru 6-2-03 Tbg part 20 jts tbg, RIH w/OS collar, catch fix well dn. RU Basin Testers, test it Test csg to 500# 15 min. Unset jt Repressure to 500# & in 9 mins it hold. POOH w/pkr, replace w/reno hold. PUH & look for csg leak dump 20-10 lb cans of diamond starting and starting	k). SEE RULE 1103. For Multiple of the day of the 21st j is dwn, POOH w/18 ft of the 21st j ish, POOH w/tbg & FT, LD parted the nhole 7000# below slips busted 17 jokr circ pkr fluid 120 bbls. Set pkr is lost from 500# to 400#. Move pkr u dressed pkr. RIH w/5 stds, run 500 k, HIC @ 575' from surface. RIH w/5 seal.	tinent details, and good to a public to a	a diagram of proposed of OS w/extension 16' older of tbg & LD pkr. w. RD Tbg Testers. in. Good chart & a 3 lts. Attempt to test cs. IH w/5 more stds, set ging. RU swab FL to 19 of the control of the co	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 5# drop in an instant. g to 500 psi-will not t pkr, press to 500 psi- 525', set pkr. NUWH.
of starting and proposed wor or recompletion.  OCD press test failure - HIT repa 5-27-03 thru 6-2-03 Tbg part 20 jts tbg, RIH w/OS collar, catch fi well dn. RU Basin Testers, test it Test csg to 500# 15 min. Unset prepare to 500# & in 9 mins hold. POOH w/pkr, replace w/reno hold. PUH & look for csg lead dump 20-10 lb cans of diamond 6-4-03 Press to 580 psi - held for	k). SEE RULE 1103. For Multiple of the day of the 21st j is dwn, POOH w/18 ft of the 21st j ish, POOH w/tbg & FT, LD parted the nhole 7000# below slips busted 17 jokr circ pkr fluid 120 bbls. Set pkr is lost from 500# to 400#. Move pkr u dressed pkr. RIH w/5 stds, run 500 k, HIC @ 575' from surface. RIH w/5 seal.	tinent details, and gottenent details, and gottenent details, and gottenent details, and gottenent details. Attach whose, POOH w/remain the sent that the sent the sent that the sent the sent that the sent that the sent the sent that the sent the sent that the sent the se	a diagram of proposed of OS w/extension 16' older of tbg & LD pkr. w. RD Tbg Testers. in. Good chart & a 3 lts. Attempt to test cs. IH w/5 more stds, set ging. RU swab FL to 3 lts. Attempt to stds, set ging. RU swab FL to 3 lts.	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. 1g to 500 psi-will not 1t pkr, press to 500 psi- 1525', set pkr, NUWH,
of starting and proposed wor or recompletion.  OCD press test failure - HIT repa 5-27-03 thru 6-2-03 Tbg part 20 jts tbg, RIH w/OS collar, catch fi well dn. RU Basin Testers, test it Test csg to 500# 15 min. Unset prepare to 500# & in 9 mins hold. POOH w/pkr, replace w/reno hold. PUH & look for csg lead dump 20-10 lb cans of diamond 6-4-03 Press to 580 psi - held for	k). SEE RULE 1103. For Multiple of aired as follows jts dwn, POOH w/18 ft of the 21st j sh, POOH w/tbg & FT, LD parted the nhole 7000# below slips busted 17 okr circ pkr fluid 120 bbls. Set pkr is dost from 500# to 400#. Move pkr underssed pkr. RIH w/5 stds, run 500 k, HIC @ 575' from surface. RIH w/s seal.  30 mins - good test - chart attached ion above is true and complete to the surface.	tinent details, and gottenent details, and gottenent details, and gottenent details, and gottenent details. Attach whose, POOH w/remain the sent that the sent the sent that the sent the sent that the sent that the sent the sent that the sent the sent that the sent the se	diagram of proposed of OS w/extension 16' of the LD pkr. w. RD Tbg Testers. in. Good chart & a 3 lts. Attempt to test cs. IH w/5 more stds, set ging. RU swab FL to stdge and belief.	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. g to 500 psi-will not t pkr, press to 500 psi- 525', set pkr, NUWH,
of starting and proposed wor or recompletion.  OCD press test failure - HIT reparts to 5-27-03 thru 6-2-03 Tbg part 20 jts tbg, RIH w/OS collar, catch fix well dn. RU Basin Testers, test in Test csg to 500# 15 min. Unset pressure to 500# & in 9 mins hold. POOH w/pkr, replace w/reno hold. PUH & look for csg lead dump 20-10 lb cans of diamond 6-4-03 Press to 580 psi - held for	k). SEE RULE 1103. For Multiple of aired as follows jts dwn, POOH w/18 ft of the 21st j sh, POOH w/tbg & FT, LD parted the hole 7000# below slips busted 17 j okr circ pkr fluid 120 bbls. Set pkr if cost from 500# to 400#. Move pkr underessed pkr. RIH w/5 stds, run 500 kr, HIC @ 575' from surface. RIH w/6 seal.  30 mins - good test - chart attached ion above is true and complete to the surface.  TITLE	tinent details, and good completions: Attach to the PU 5-1/2" WP word, POOH w/remain its. Replaced w/ ne ran chart 500#, 8 m phole w/ same resulpsi chart-held ok. Rebg, leave pkr swing the pkr swing	diagram of proposed of OS w/extension 16' of the der of the & LD pkr. w. RD The Testers. in. Good chart & a 3 lts. Attempt to test cs. IH w/5 more stds, set ging. RU swab FL to stdge and belief.	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. If to 500 psi-will not the pkr, press to 500 psi-525', set pkr, NUWH, 12 13 74 75 6  DATE 06/09/2003  DATE 06/09/2003  COD  DATE 06/09/2003  COD  DATE 06/09/2003
12. Describe proposed or complete of starting and proposed wor or recompletion.  OCD press test failure - HIT repassed starting and proposed wor or recompletion.  OCD press test failure - HIT repassed starting and proposed work of the starting and proposed work of the starting and pressure to 500 part 20 jts tbg, RIH w/OS collar, catch fix well dn. RU Basin Testers, test it Test csg to 500# 15 min. Unset pressure to 500# & in 9 mins in hold. POOH w/pkr, replace w/reno hold. PUH & look for csg lead dump 20-10 lb cans of diamond starting and press to 580 psi - held for I hereby certify that the information of the starting and proposed work of the	k). SEE RULE 1103. For Multiple of aired as follows jts dwn, POOH w/18 ft of the 21st j sh, POOH w/tbg & FT, LD parted the short of the 7000# below slips busted 17 j okr circ pkr fluid 120 bbls. Set pkr is clost from 500# to 400#. Move pkr underssed pkr. RIH w/5 stds, run 500 kr, HIC @ 575' from surface. RIH w/6 seal.  30 mins - good test - chart attached ion above is true and complete to the SBAND  CC FIELD	tinent details, and good completions: Attach to the PU 5-1/2" WP word, POOH w/remain its. Replaced w/ ne ran chart 500#, 8 m phole w/ same resulpsi chart-held ok. Rebg, leave pkr swing the pkr swing	diagram of proposed of OS w/extension 16' oder of tbg & LD pkr. w. RD Tbg Testers. in. Good chart & a 3 lts. Attempt to test cs. IH w/5 more stds, setging. RU swab FL to stage and belief.	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. g to 500 psi-will not t pkr, press to 500 psi- 525', set pkr, NUWH, 12137475 DATE 06/09/2003 CO  DATE 06/09/2003 CO  DATE 06/09/2003 CO  DATE 06/09/2003
12. Describe proposed or complete of starting and proposed work or recompletion.  OCD press test failure - HIT reparts 1-27-03 thru 6-2-03 Tbg part 20 jts tbg, RIH w/OS collar, catch fix well dn. RU Basin Testers, test its 1-25 to	k). SEE RULE 1103. For Multiple of aired as follows jts dwn, POOH w/18 ft of the 21st j sh, POOH w/tbg & FT, LD parted the short of the 7000# below slips busted 17 j okr circ pkr fluid 120 bbls. Set pkr is clost from 500# to 400#. Move pkr underssed pkr. RIH w/5 stds, run 500 kr, HIC @ 575' from surface. RIH w/6 seal.  30 mins - good test - chart attached ion above is true and complete to the SBAND  CC FIELD	tinent details, and good completions: Attach to the PU 5-1/2" WP word, POOH w/remain its. Replaced w/ ne ran chart 500#, 8 m phole w/ same resulpsi chart-held ok. Rebg, leave pkr swing the pkr swing	diagram of proposed of OS w/extension 16' of the der of the & LD pkr. w. RD The Testers. in. Good chart & a 3 lts. Attempt to test cs. IH w/5 more stds, set ging. RU swab FL to stdge and belief.	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. If to 500 psi-will not the pkr, press to 500 psi-525', set pkr, NUWH, 12 13 74 75 6  DATE 06/09/2003  DATE 06/09/2003  COD  DATE 06/09/2003  COD  DATE 06/09/2003
12. Describe proposed or complete of starting and proposed wor or recompletion.  OCD press test failure - HIT repassed starting and proposed wor or recompletion.  OCD press test failure - HIT repassed starting and proposed work of the starting and proposed work of the starting and pressure to 500 part 20 jts tbg, RIH w/OS collar, catch fix well dn. RU Basin Testers, test it Test csg to 500# 15 min. Unset pressure to 500# & in 9 mins in hold. POOH w/pkr, replace w/reno hold. PUH & look for csg lead dump 20-10 lb cans of diamond starting and press to 580 psi - held for I hereby certify that the information of the starting and proposed work of the	k). SEE RULE 1103. For Multiple of aired as follows jts dwn, POOH w/18 ft of the 21st j sh, POOH w/tbg & FT, LD parted the short of the 7000# below slips busted 17 j okr circ pkr fluid 120 bbls. Set pkr is clost from 500# to 400#. Move pkr underssed pkr. RIH w/5 stds, run 500 kr, HIC @ 575' from surface. RIH w/6 seal.  30 mins - good test - chart attached ion above is true and complete to the SBAND  CC FIELD	tinent details, and good completions: Attach to the PU 5-1/2" WP word, POOH w/remain its. Replaced w/ ne ran chart 500#, 8 m phole w/ same resulpsi chart-held ok. Rebg, leave pkr swing the pkr swing	diagram of proposed of OS w/extension 16' of the der of the & LD pkr. w. RD The Testers. in. Good chart & a 3 lts. Attempt to test cs. IH w/5 more stds, set ging. RU swab FL to stdge and belief.	bumper sub, xo & 24 RU Vac Trk- bleed Set pkr. NUWH. 15# drop in an instant. If to 500 psi-will not to pkr, press to 500 psi- 525', set pkr, NUWH, 1213747550  DATE 06/09/2003  CLEST OCO  DATE 06/09/2003  CREST OCO  DATE 06/09/2003  CREST OCO  DATE 06/09/2003  CREST OCO  DATE 06/09/2003

