| • Submit 3'Copies To Appropriate District   |   |  |  |
|---|---|--|--|
| Office France Minamla and Natural I   |   |  |  |
| 1625 N. French Dr., Hobbs, NM 88240   | WELL API NO.  |  |  |
| District II<br>1301 W. Grand Ave., Artesia, NM 88210<br>District III<br>1220 South St. From size  | VISION 5. Indicate Type of Lease                          |  |  |
| 1000 Rio Brazos Rd., Aztec, NM 87410 3 2013   | Dr. STATE FEE   |  |  |
| District IV<br>1220 S. St. Francis Dr., Santa Fe, NM<br>87505   | 6. State Oil & Gas Lease No.<br>18164                     |  |  |
| SUNDRY RECEIVES AND REPORTS ON WELLS  | 7. Lease Name or Unit Agreement Name                      |  |  |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B.<br>DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SU   |   |  |  |
| PROPOSALS.)   1. Type of Well: Oil Well   Gas Well   Other  | 8. Well Number 14   |  |  |
| 2. Name of Operator   | 9. OGRID Number   |  |  |
| Fasken Oil and Ranch, Ltd.  | 151416<br>10. Pool name or Wildcat                        |  |  |
| <ul><li>3. Address of Operator</li><li>303 W. Wall, Suite 1800, Midland, TX 79701</li></ul>   | Denton; Wolfcamp  |  |  |
| 4. Well Location  |   |  |  |
|   | ine and <u>2137</u> , feet from the <u>West</u> line      |  |  |
| Section 11 Township 15S Range   |   |  |  |
| 11. Elevation (Show whether DR, RK)<br>3811' GR   | 3, K1, GR, etc.)  |  |  |
| Pit or Below-grade Tank Application or Closure   Pit type Depth to Groundwater Distance from nearest fresh water  | well Distance from nearest surface water                  |  |  |
| Pit Liner Thickness: mil Below-Grade Tank: Volume   | bbls; Construction Material                               |  |  |
| 12. Check Appropriate Box to Indicate Natur   | e of Notice. Report or Other Data                         |  |  |
| NOTICE OF INTENTION TO:   |   |  |  |
|   |   |  |  |
| TEMPORARILY ABANDON CHANGE PLANS  | MMENCE DRILLING OPNS. P AND A                             |  |  |
| PULL OR ALTER CASING DULTIPLE COMPL   | SING/CEMENT JOB   |  |  |
| OTHER:  | HER:  |  |  |
| 13. Describe proposed or completed operations. (Clearly state all pertino f starting any proposed work). SEE RULE 1103. For Multiple Co   |   |  |  |
| or recompletion.  | · · · · · · · · · · · · · · · · · · ·                     |  |  |
|   |   |  |  |
| Fasken Oil and Ranch, Ltd. proposes to plug and abandon the Denton No. 14   | I. Please see attached procedure and current and proposed |  |  |
| plug and abandon wellbore diagrams.   |   |  |  |
|   |   |  |  |
|   | · · · · · · · · · · · · · · · · · · ·                     |  |  |
|   | · · · · · ·   |  |  |
| The Oil Co  | nservation Division Must be notified                      |  |  |
| 24 hours p  | prior to the beginning of plugging operations.            |  |  |
|   |   |  |  |
| Therefore a first the second |   |  |  |
| I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines $\Box$ , a g  |   |  |  |
| SIGNATURE lan 2000 TITLE Regu   | latory Analyst DATE12-28-2012                             |  |  |
| Type or print name Kim Tyson E-mail address: kimt@:   | forl.com Telephone No. (432) 687-1777                     |  |  |
| $\frac{\text{For State Use Only}}{2} \wedge A + \wedge H \neq A$  |   |  |  |
| APPROVED BY: Maley & Drown TITLE Compliance are 1/4/2013  |   |  |  |
| Conditions of Approval (if any):  |   |  |  |
|   | M. M.   |  |  |
| · · · · · · · · · · · · · · · · · · ·   | JAN 0 8 2013 UN   |  |  |

| JAN | Ĩ0 | 8 | 2013 |
|-----|----|---|------|
|-----|----|---|------|

Recommended Plug & Abandon Procedure Denton No. 14 Fasken Oil and Ranch, Ltd. 660' FNL and 2137' FEL Sec. 11, T15S, R37E Lea County, New Mexico

| OBJECTIVE:   | P&A   |
|--|---|
| WELL DATA: Elevation:  | 3810.5' KB  |
| TD:  | 9550'   |
| PBTD:<br>Casing:   | 8985'(CIBP @ 9020' w/ 35' cmt 5-6-93)<br>13 3/8", 48#, H-40 @ 350' w/ 350 sxs to surface                |
|  | 8 5/8", 24 &32# @ 4647' W/ 2000 sxs to surface  |
| a series and the series of the | 5 ½", 15.5 & 17#, J-55, N-80 LT&C @ 9545 <u>'</u> cmt w/<br>625sxs, DV tool @ 7497'.TOC @ 3,250' by TS. |
| Perfs:   | Wolfcamp9032'-9535'   |

- 1. Notify NMOCD of intent to plug and abandon. Confirm with Kim Tyson that pit permits have been obtained.
- 2. Make sure mast anchors have been tested and tagged in the last 24 months.
- 3. Receive +/- 9000' of 2-3/8" EUE 8rd N-80 tubing and tubing subs, 2 sets of pipe racks, catwalk, and 3K manual BOP with 2-3/8" pipe rams and blind rams.
- 4. Set matting boards, pipe racks and catwalk. RUPU.
- 5. NDWH and NU 3K manual BOP with 2-3/8" pipe rams.
- 6. RIW with 2-3/8" EUE 8rd N-80 tubing open-ended and tag cement of 5-1/2" CIBP @ PBTD 8,985'. Notify Midland Office of the results. SPDT 2.5 5X5 CMT @ Tag
- 7. Pick up +/- 5' and pump enough mud laden brine to bring top of mud to 7600'.
- 8. POW and LD tubing with EOT @ 7600'.
- Pump enough mud laden brine water to bring top of mud to 4750', followed by a 5 bbl fresh water spacer ahead of cement. Mix and spot 25 sx Class "H" cement (15.6 ppg, 1.18 ft<sup>3</sup>/sx yield) at7600'. TOC should be @ +/- 7382'. Stand back 3000' of tubing and WOC for 4 hours. RIW with tubing, tag cement, and notify Midland office and NMOCD of results. If TOC is below 7447', mix and spot additional cement to achieve noted TOC.

- 10. POW and LD tubing with EOT @ 4750'.
- 11. Pump enough mud laden brine water to bring top of mud to 3250', followed by a 5 bbl fresh water spacer ahead of cement. Mix and spot 35 sx Class "C" cement (14.8 ppg, 1.32 ft<sup>3</sup>/sx yield) with 2% CaCl<sub>2</sub>at4750'. TOC should be @ 4408'. Stand back 2000' of tubing and WOC for 4 hours. RIW with tubing, tag cement, and notify Midland office and NMOCD of results. If TOC is below 4597', mix and spot additional cement to achieve noted TOC.
- 12. POW and LD all but 2900' of tubing. Stand remainder of tubing in derrick.
- 13. RU wireline crew and 3k psi lubricator. RIW and perforate 5-1/2" casing @ 3200',(4h, 1 jspf). POW with guns and confirm all guns fired.
- 14. Set5-1/2" tension packer @ 2900'.
- 15. Establish injection rate into squeeze holes and report results to Midland office.
- 16. Mix and circulate 70 sx Class "C" with 2% CaCl<sub>2</sub>cement through perforations displacing cement inside tubing to 2950'.
- 17. Unseat packer and displace casing with mud laden brine water to surface. LD all but 2 joints of tubing.
- 18. RU wireline crew and RIW and perforate 5-1/2" casing @ 400' (4h, 1 jspf). POW and confirm all guns fired.
- 19. RIW with 2 joints of tubing and 5-1/2" tension packerat 60'. Establish injection rate into perforations.
- 20. Mix and circulate 125sx Class "C" with 2% CaCl<sub>2</sub> cement through perforations to surface on backside.Unseat packer and fill remainder of casing with cement to surface.


- 21. Dig out wellheads and cut off below "A" section wellhead. Weld cap and dry hole marker on top of 13-3/8" casing stub. Install 1" 2000 psi ball valve on top of dry hole marker plate, pack valve in grease, close valve, and remove handle.
- 22. Send 2-3/8" tubing and wellheads to Midland for inspection.

3

23. RDPU and release all rental equipment. Dig out mast anchors. Clean location. Rip caliche on location and install access barrier as per BLM stipulations.

## Denton No. 14

## Current



cwb 4-24-06 Denton 14 wb diagram.xls



## Denton No. 14

## Proposed

