Submit I Copy To Appropriate District State of New Mexico	Form C-103
Office District I – (575) 393-6161 IG25 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1383	es Revised August 1, 2011
$\frac{District 1}{2} = (373) + ($	WELL API NO. 30-005-00926 /
District III - (505) 334-6178 APR 17 2019 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM RECEIVED	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Drickey Queen Sand Unit
1 Type of Well: Oil Well Cos Well Costber Liesting	8. Well Number 5
2. Name of Operator Celero Energy II, LP	9. OGRID Number
3. Address of Operator <sub>400</sub> W. Illinois, Ste. 1601 Midland, TX 79701	10. Pool name or Wildcat
4. Well Location	Caprock; Queen
Unit Letter H : 1980 feet from the N line and 660 feet from the E line	
Section 35         Township I3S         Range 31E         NMPM         County Chaves           11. Elevation (Show whether DR, RKB, RT, GR, etc.)         11. Elevation (Show whether DR, RKB, RT, GR, etc.)         11. Elevation (Show whether DR, RKB, RT, GR, etc.)         11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK I PLUG AND ABANDON I REMEDIAL	
TEMPORARILY ABANDON 🗍 CHANGE PLANS 🗍 COPPEN	derground Intection Contropprogram Manual
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE MULTIPLE COMPL 11.6 C Packer shall be set within or less than 100	
OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
<ol> <li>Blow well down, release pkr, circ w/ produced wtr &amp; POOH w/ inj string. PU 2-3/8" workstring &amp; make a bit run to TD. Run a CIL from 3030' to surface.</li> </ol>	
2. Coordinate with plugging company. RIH w/O-E workstring & spot 50 sx Class C.w/2% CaCl2 at TD. POOH to 2000' & reverse	
clean. WOC a min of 4 hrs & tag TOC. Spot again as necessary-required TOC will be determined from CIL. 3. RIH w/ bit & dress off TOC. POOH & RBIH w/ treating pkr & test csg. Locate & EIR into leak(s) using produced wtr.	
Depending on the number of leaks & injection rate, the decision will be made to squeeze them w/ cmt or pump gel then return a later date & squeeze. Final stage will be a cmt squeeze.	
4. After squeezing leak(s), TOOH w/ pkr, PU bit & DC's & drill out to TD of 3075'.	
<ol> <li>PU a min of 500'4", 11#, L-80, UFJ pipe on Duplex shoe. Bottom 300' of pipe should have Bond Coat. Have Bond Coat repair kit(s) on location. Use Seal Lube on the connections.</li> </ol>	
6. Cmt liner w/ a min of 100 sx Class C leaving 5' of cmt on Duplex shoe. POOH w/ out reversing TOL. WOC a min of 4 hrs, RIH w/bit & DC's & & tag TOC. Pressure test to 500 psi. Run pkr & squeeze TOL, if necessary.	
7. Clean out liner to within 2' of Duplex shoe. POOH. *Continued on attached sheet	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
/	
SIGNATURE Lisa Hunt TITLE Regulatory Analyst	DATE_04/15/2013
Type or print name Lisa Hunt E-mail address: <u>lhunt@cel</u>	eroenergy.com PHONE: (432)686-1883
APPROVED BY TITLE DIST MAR DATE 723-2013	
Conditions of Approval: The Operator shall give the OCD	
District office 24 hours notice before work begins	

....

......

...<u></u>

------

e - 11 feldest de see 10-

APR Office 24 hours prior to running MIT Test & Chart.

1

## Drickey Queen Sand Unit #5 - C103 continued

8. RU WL & run a GR/CCL tie-in log from TD to 100' above TOL. Correlate to Apollo GR/CCL/CNL dated 3/24/08. Perfs will be picked from log. Have a 15' gun on location loaded at 4SPF, 0-degree phasing.

9. RIH w/treating pkr on workstring & acidize w/ 1500 gals inhibited 7-1/2% NEFE HCL at max rate w/ out exceeding 3500 psi. Displace w/ FW & overflush w/ a min of 35 bbls FW.

10. Run inj pkr & inj tbg. Space out, land tbg, ND BOPE & NU WH. Run MIT & place well on injection.