Francis M	ate of New Mexico	/ Form C-103	
Office District I ~ (575) 393-6161 HOBBS OCD Energy, Minerals and Natural Resources WELL API NO			
District II = (575) 748-1283			
	South St. Francis Dr.	5. Indicate Type of Lease STATE ☐ FEE ✓	
1000 Rio Brazos Rd., Aztec, NM 8/410	anta Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NMRECFIVE			
SUNDRY NOTICES AND REPO		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI		Bertha Barber	
PROPOSALS.) 1. Type of Well: Oil Well, ✓ Gas Well ☐ O	ther	8. Well Number ₀₁₆	
2. Name of Operator Apache Corporation		9. OGRID Number 873	
3. Address of Operator		10. Pool name or Wildcat	
303 Veterans Airpark Lane, Suite 3000 Midland, TX	79705	Monu Bli-46990/M.Tubb-47090/M.Abo-46970	
4. Well Location			
7	om the South line and 165		
	ship 20S Range 37E Show whether DR, RKB, RT, GR, etc.)	NMPM County Lea	
3554' GL	show whether DR, RRD, R1, GR, etc.,		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO	o: SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND AB			
TEMPORARILY ABANDON			
PULL OR ALTER CASING ☐ MULTIPLE COI DOWNHOLE COMMINGLE ☐	MPL CASING/CEMENT		
_	□ OTHER RC		
OTHER:	D OTTICE.		
13 Describe proposed or completed operations.	13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez	19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & A	npletions: Attach wellbore diagram of	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish c 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2	19.15.7.14 NMAC. For Multiple Cor ze the Blinebry & acidize the Tubb & A irc, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx	npletions: Attach wellbore diagram of	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish c 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552	19.15.7.14 NMAC. For Multiple Cor ze the Blinebry & acidize the Tubb & A irc, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean.	npletions: Attach wellbore diagram of	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish c 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2	19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & Airc, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean.	npletions: Attach wellbore diagram of	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt (1/24/2013 Pump 43 sx Class C; press up & squeeze	19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & Airc, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/di	npletions: Attach wellbore diagram of abo: to pit - circ hole clean.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish c 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt (19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & Airc, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/di	npletions: Attach wellbore diagram of abo: to pit - circ hole clean.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt of 1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3	19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & A circ, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/di c; drill hard cmt from 5316'-5614'; circ h BP @ 5880'. 31/2013 DO CIBP @ 5900'.	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. rill collars & bit. nole clean.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt of 1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB	19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & A circ, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/di c; drill hard cmt from 5316'-5614'; circ h BP @ 5880'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid.	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. till collars & bit. nole clean.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt (1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3/2/2013 Acidize Abo w/1500 gal 20% NEFE acid	19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & A circ, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/di c; drill hard cmt from 5316'-5614'; circ h BP @ 5880'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid.	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. till collars & bit. nole clean.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552 1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt (1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3 2/01/2013 Acidize Abo w/1500 gal 20% NEFE acid 2/06/2013 RIH w/prod equip - 2-3/8" tbg - SN @ 726	19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & Airc, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/dright hard cmt from 5316'-5614'; circ here is 2580'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid. 68'; ETD @ 7268'. 2/07/2013 RIH w/dright w/dright hard cmt from 5316'-5614'; circ here is 31/2013 RIH w/dright hard cmt from 5316'.	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. till collars & bit. nole clean.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt (1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3/2/2013 Acidize Abo w/1500 gal 20% NEFE acid	19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & A circ, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/di c; drill hard cmt from 5316'-5614'; circ h BP @ 5880'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid.	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. till collars & bit. nole clean.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552 1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt (1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3 2/01/2013 Acidize Abo w/1500 gal 20% NEFE acid 2/06/2013 RIH w/prod equip - 2-3/8" tbg - SN @ 726	19.15.7.14 NMAC. For Multiple Corze the Blinebry & acidize the Tubb & Airc, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/dright hard cmt from 5316'-5614'; circ here is 2580'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid. 68'; ETD @ 7268'. 2/07/2013 RIH w/dright w/dright hard cmt from 5316'-5614'; circ here is 31/2013 RIH w/dright hard cmt from 5316'.	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. till collars & bit. nole clean. 2/04-05/2013 Swab pump & rods. Leave well pumping.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552 1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt (1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3 2/01/2013 Acidize Abo w/1500 gal 20% NEFE acid 2/06/2013 RIH w/prod equip - 2-3/8" tbg - SN @ 726	2e the Blinebry & acidize the Tubb & A circ, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/di c; drill hard cmt from 5316'-5614'; circ hole 9 5880'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid. 68'; ETD @ 7268'. 2/07/2013 RIH w/di company.	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. rill collars & bit. nole clean. 2/04-05/2013 Swab pump & rods. Leave well pumping.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt of 1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3/2/01/2013 Acidize Abo w/1500 gal 20% NEFE acid 2/06/2013 RIH w/prod equip - 2-3/8" tbg - SN @ 726/2014 Date: Spud Date: 5/12/1997	ze the Blinebry & acidize the Tubb & A circ, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/dis; drill hard cmt from 5316'-5614'; circ hap @ 5880'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid. 68'; ETD @ 7268'. 2/07/2013 RIH w/dispersion of the complete to the best of my knowledge.	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. rill collars & bit. nole clean. 2/04-05/2013 Swab pump & rods. Leave well pumping.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt of 1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3/2/01/2013 Acidize Abo w/1500 gal 20% NEFE acid 2/06/2013 RIH w/prod equip - 2-3/8" tbg - SN @ 726/2014 Date: Spud Date: 5/12/1997	2e the Blinebry & acidize the Tubb & A circ, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/di c; drill hard cmt from 5316'-5614'; circ hole 9 5880'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid. 68'; ETD @ 7268'. 2/07/2013 RIH w/di company.	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. rill collars & bit. nole clean. 2/04-05/2013 Swab pump & rods. Leave well pumping.	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552 1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt of 1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3 2/01/2013 Acidize Abo w/1500 gal 20% NEFE acid 2/06/2013 RIH w/prod equip - 2-3/8" tbg - SN @ 726 Spud Date: Spud Date: 5/12/1997	ze the Blinebry & acidize the Tubb & A circ, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/dis; drill hard cmt from 5316'-5614'; circ hap @ 5880'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid. 68'; ETD @ 7268'. 2/07/2013 RIH w/dispersion of the complete to the best of my knowledge. TITLE Sr. Staff Reg Tech	npletions: Attach wellbore diagram of abo: to pit - circ hole clean. iill collars & bit. hole clean. 2/04-05/2013 Swab pump & rods. Leave well pumping. 506 e and belief. DATE 6/11/2013	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt of 1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3/2/01/2013 Acidize Abo w/1500 gal 20% NEFE acid 2/06/2013 RIH w/prod equip - 2-3/8" tbg - SN @ 726/2014 Date: Spud Date: 5/12/1997	ze the Blinebry & acidize the Tubb & A irc, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/di ;; drill hard cmt from 5316'-5614'; circ hard from 5316	Inpletions: Attach wellbore diagram of shoo: Ito pit - circ hole clean. It collars & bit. Inole clean. It collars & bit. Inole clean. In collars & bit. Inol	
of starting any proposed work). SEE RULE proposed completion or recompletion. Apache performed the following to DO plugs, squeez 1/16/2013 MIRUSU Tag CIBP @ 5663'; establish of 1/17/2013 RIH & set cmt ret & tbg @ 5540'. 1/18/2 1/21/2013 DO cmt ret @ 5540'. DO cement to 5552/1/22/2013 DO cmt from 5552'-5704'; circ hole clean 1/23/2013 DO cmt from 5704'-5809'; fell out of cmt of 1/24/2013 Pump 43 sx Class C; press up & squeeze 1/28/2013 RIH w/tbg & tag cmt @ 5316'. Estab circ 1/29/2013 DO cmt from 5614'-5874'. RIH & tag CIB 1/30/2013 DO cmt from 5874'-5900'; circ clean. 1/3/2/01/2013 Acidize Abo w/1500 gal 20% NEFE acid 2/06/2013 RIH w/prod equip - 2-3/8" tbg - SN @ 726/2014 Date: Spud Date: 5/12/1997 I hereby certify that the information above is true and SIGNATURE About About About Type or print name Reesa Holland Fisher	ze the Blinebry & acidize the Tubb & A circ, DO CIBP & circ hole clean. 013 Pump 470 sx Class C; circ 32 sx 2'; circ hole clean. @ 5809'. RIH to 5872'; circ clean. e leak @ 1500#. 1/25/2013 RIH w/dis; drill hard cmt from 5316'-5614'; circ hap @ 5880'. 31/2013 DO CIBP @ 5900'. & Tubb w/2000 gal 20% NEFE acid. 68'; ETD @ 7268'. 2/07/2013 RIH w/dispersion of the complete to the best of my knowledge. TITLE Sr. Staff Reg Tech	Inpletions: Attach wellbore diagram of shoo: Ito pit - circ hole clean. It collars & bit. Inole clean. It collars & bit. Inole clean. In collars & bit. Inol	

Apache Corporation – Bertha Barber #16 GL=3554' KB=3570° Wellbore Diagram – Current Date: 7/11/2012 Spud:5/12/97 API: 30-025-33919 R. Taylor **Surface Location** 2140' FNL & 1650' FWL, Lot K Sec 5, T20S, R37E, Lea County, NM **Surface Casing** 13-3/8" 48# K-55 @ 490' w/ 545 sxs to surface Hole Size =17-1/2" **Intermediate Casing** 8-5/8" 24# &28# @ 2429' w/ 980 sxs to surface 9/99: Sqz'd csg leak @ 3,758'-3,788' w/1600 sxs 800 sx foamed, 100 sx thix, 700 sx class "C" w/ adds; multiple attempts failed Hole Size =11" 9/99: Ran 7" csg patch @ 3,753'-3793'. 9/99: Ran 108 its 4-1/2" tie-back string to surf, pmpd 450 sx class "C" neat, then stung into liner top. 6/97: 4-1/2"x 7" Liner Hanger @ 4812' TAC @ 6297' Hole Size =7-7/8" Intermediate Casing II 7" 23# K-55 @ 5122' w/ 150 sxs 1/09: POOH w/ tbg & set CIBP @ 5,563'. Well TA'd, expires 1/27/14. 5/07: Perf Blinebry @ 5,604'-30',5684'-5730',5,744'-52', 56'-60', 70'-72', 80'-87', 98'-5,802'. (218 holes) Acidized w/ 8000 gal 15% HCl. 1/13: SQZ Blinebry w/ 470 sxs cement 7/07: Set CIBP @ 5,737'. Isolated fr/ 5,744'-5,802'. 3/08: DO CIBP & push down to 5,880'. 5/07: Set CIBP @ 5,900' w/10'cmt. 1/13: DO CIBP. 10/99; Perf Tubb @ 6418-6422, 6437-6439, 6442-6452, 6464-6481 w/ 1 jspf. (66 holes). Acidized w/ 3000 gal 15%. Frac'd w/ 33k gal Delta frac w/ 32.5k# 20/40 snd. 2/13: Acidized w/ 2000 gallons 20% NEFE 6/97: Perf Abo @ 7,204 - 7,230' w/ 2 jspf (54 holes). Acidize w/2,000 gals 15% Ferchek 2/13: Acidized w/ 1500 gallons 20% NEFE Hole Size 2/05: Tight spot in csg @ 7,447'. =6-1/8" **Production Liner** PBTD = 5.563'4-1/2" 11.6# K-55 @ 7796' w/ 235 sxs to 4812 MD = 7.800Liner Hanger @ 4812'