Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II HOBBS OCD CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210	30-025-06784 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87440 2 3 2013 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Sarkeys A
1. Type of Well: Oil Well Gas Well Other	8. Well Number 1
2. Name of Operator	9. OGRID Number 012024
John H. Hendrix Corporation	10 P I WELL & DUCKEL
3. Address of Operator P. O. Box 3040, Midland, TX 79702-3040	10. Pool name or Wildcat DHC Blinebry Tubb and Drinkard
4. Well Location	
Unit Letter G:1980 feet from theNorth line and	1980feet from theEastline
Section 26 Township 21S Range 37E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, et	c.)
3383' GR	
12. Check Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION TO	
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	_
TEMPORARILY ABANDON	RILLING OPNS. P AND A
DOWNHOLE COMMINGLE	NT JOB
DOWN IOLE COMMINGEL	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details,	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions:	
13. Describe proposed or completed operations. (Clearly state all pertinent details,	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.	
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.	Attach wellbore diagram of proposed completion [H. Set frac pkr @ 5400', test csg above pkr. OK]
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400', test to 1000#. PU	Attach wellbore diagram of proposed completion H. Set frac pkr @ 5400', test csg above pkr. OK Brons). Formations pressured-up so frac was cut
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died.	Attach wellbore diagram of proposed completion H. Set frac pkr @ 5400', test csg above pkr. OK Stons). Formations pressured-up so frac was cut 5 min 1172#; 10 min 1136#; 15 min 1097#.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400', test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK stons). Formations pressured-up so frac was cut imin 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg,	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK stons). Formations pressured-up so frac was cut imin 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400', test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK stons). Formations pressured-up so frac was cut imin 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg,	Attach wellbore diagram of proposed completion H. Set frac pkr @ 5400', test csg above pkr. OK Stons). Formations pressured-up so frac was cut min 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf.	Attach wellbore diagram of proposed completion H. Set frac pkr @ 5400', test csg above pkr. OK Stons). Formations pressured-up so frac was cut min 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400', test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20	Attach wellbore diagram of proposed completion H. Set frac pkr @ 5400', test csg above pkr. OK Stons). Formations pressured-up so frac was cut min 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf.	Attach wellbore diagram of proposed completion H. Set frac pkr @ 5400', test csg above pkr. OK Stons). Formations pressured-up so frac was cut min 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400', test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20	Attach wellbore diagram of proposed completion H. Set frac pkr @ 5400', test csg above pkr. OK Stons). Formations pressured-up so frac was cut min 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20 Spud Date:	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK (Btons). Formations pressured-up so frac was cut imin 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production. %) under Order No. DHC-HOB -0501.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400', test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK (Btons). Formations pressured-up so frac was cut imin 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production. %) under Order No. DHC-HOB -0501.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400°, test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20 Spud Date: Rig Release Date:	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK stons). Formations pressured-up so frac was cut min 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production. %) under Order No. DHC-HOB -0501.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400', test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; 5 SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20 Spud Date: Rig Release Date:	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK (Btons). Formations pressured-up so frac was cut imin 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production. %) under Order No. DHC-HOB -0501.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20 Spud Date: Rig Release Date: Rig Release Date:	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK Btons). Formations pressured-up so frac was cut imin 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production. %) under Order No. DHC-HOB -0501. dge and belief. DATE 07/19/13
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; \$ \$124 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20 Spud Date: Rig Release Date: Rig Release Date: Type or print name Carolyn Doran Haynes E-mail address: cdoranhayr	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK Stons). Formations pressured-up so frac was cut min 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production. %) under Order No. DHC-HOB -0501. dge and belief. DATE 07/19/13
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; S SI 24 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20 Spud Date: Rig Release Date: Rig Release Date: Type or print name Carolyn Doran Haynes E-mail address: cdoranhaynes	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK Stons). Formations pressured-up so frac was cut min 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production. %) under Order No. DHC-HOB -0501. dge and belief. DATE 07/19/13 nes@jhhc.org PHONE: 432-684-6631
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 06/10/13 MIRU. POOH w/ all equipment. 06/11-12/13 GIH w/frac pkr and RBP on 3 ½" WS, set RBP @ 6400", test to 1000#. PU 06/14-17/13 Frac Blinebry and Tubb zones w/48975# sand in 65 Quality CO2 foam (348 short. Flushed all away. AIR 21; PMax 4500#; PAvg 3215#; ISIP 1333#; \$ \$124 hrs. Flow back 9 bbls water. Well died. 06/18-19/13 Rls pkr, POOH, GIH and CO sand, etc. latch onto RBP and POOH. GIH w 06/20-25/13 GIH w/pump and rods. Pump stuck, paraffin problems, strip out; Clean tbg, 07/13/13 Test well – 5 oil, 10 water, 182 mcf. The subject well is DHC Blinebry (40%), Tubb (40%) and Drinkard (20 Spud Date: Rig Release Date: Rig Release Date: Type or print name Carolyn Doran Haynes E-mail address: cdoranhayr	Attach wellbore diagram of proposed completion (H. Set frac pkr @ 5400', test csg above pkr. OK Btons). Formations pressured-up so frac was cut imin 1172#; 10 min 1136#; 15 min 1097#. / prod tbg, TFF @ 6566'. Swab to clean. GIH w/prod equip. Return well to production. %) under Order No. DHC-HOB -0501. dge and belief. DATE 07/19/13