

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87400  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

**HOBBS OGD CONSERVATION DIVISION**  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 16 2013

<b>SUNDRY NOTES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-01477
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <u>Injection</u>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator LINN OPERATING, INC.		6. State Oil & Gas Lease No.
3. Address of Operator 600 TRAVIS, SUITE 5100, HOUSTON, TEXAS 77002		7. Lease Name or Unit Agreement Name CAPROCK MALJAMAR UNIT
4. Well Location Unit Letter <u>H</u> ; 1980 feet from the <u>N</u> line and <u>660</u> feet from the <u>E</u> line Section <u>19</u> Township <u>17S</u> Range <u>33E</u> NMPM <u>LEA</u> County		8. Well Number: 053
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4,156' GR		9. OGRID Number 269324
		10. Pool name or Wildcat MALJAMAR; GRAYBURG-SAN ANDRES

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: RETURN TO INJECTION ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

Per Underground Injection Control Program Manual  
OTHER: 11.6 C Packer shall be set within or less than 100

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Description of Work: Pull tubing and packer. Cleanout and acidize. Run tubing and packer back in the hole and RTI.

Please see attached proposed procedures.

**Condition of Approval: notify  
OCD Hobbs office 24 hours  
prior of running MIT Test & Chart**

\* Use Closed Loop System

Spud Date:                       
CONDITION OF APPROVAL: Operator shall give the OCD  
District Office 24 hour notice before running the MIT test and chart.

Rig Release Date:                     

**The Oil Conservation Division**

I certify that the information above is true and complete to the best of my knowledge and belief.

**Prior to the beginning of operations**

SIGNATURE T. Callahan TITLE: REG COMPLIANCE SPECIALIST III DATE SEPTEMBER 13, 2013

Type or print name TERRY B. CALLAHAN  
For State Use Only

E-mail address: tcallahan@linenergy.com PHONE: 281-840-4272

APPROVED BY: [Signature] TITLE: Dist. MGR DATE 9-17-2013  
Conditions of Approval (if any):

SEP 17 2013

## CMU #53

LEA COUNTY, NM

30-025-01477

09/12/2013

---

**Project Scope:** POH w/ Tbg and Pkr, clean out fill, acidize and RTI.

---

**Well Procedure:**

1. Test anchors to at least 2200# prior to rigging up
2. MIRU WO Rig and record casing and tubing pressure.
3. Bleed pressure off of well. If well is flowing, flow back to frac tank or vac truck. Contact engineer if pressure does not die and well needs to be killed.
4. ND WH, screw on flange w/ O-ring seal or long thread connection w/ no seal. Tubing hanger either bowl w/ slips or flange. Make note in daily report.
5. NU 5000# BOP.
6. Unset 2 3/8" x 5 1/2" AD-1 tension packer and TOO H with 2 3/8" tubing and AD-1 packer.
7. RU Reverse Unit package with pump, frac tank, 6-3 1/2" drill collars and power swivel.
8. RIH with 4 3/4" bit, 6-3 1/2" DCs and 2 7/8" workstring and tag. Previous tag @ 3,958'.
9. Cleanout wellbore. PBT D @ 4595'. Perf interval is 4080' – 4346'. Circulate clean.
10. RD swivel and Reverse Unit. POOH w/ tubing, DCs and bit. LD DCs and bit.
11. RIH with 2 7/8" workstring and 2 7/8" x 5 1/2" treating packer to 4400'.
12. Spot 140 gals of 15% NEFe HCl acid. Let spend for atleast 30 minutes.
13. PU to 4030'. Reverse out 10 bbls water. Set packer @ 4030'.
14. Pump 5,320 gals of 15% NEFe HCl and ~3000# rock salt for diversion. Let spend for one hour.
15. Let flow back or prep to swab back load until water cleans up.
16. RU 2 cup swab equipment w/ 7260# lubricator and hydraulic oil saver. Keep replacement cups on site.
17. Unset packer, POOH and LD 2 7/8" workstring and packer.
18. PU 2-3/8" IPC injection tubing, and TIH with new 2 3/8" x 5 1/2" Arrow-set type packer with on/off tool landed at 4,000' (unset).
19. ND BOP.
20. Circulate packer fluid.
21. Set packer at 4,000'.
22. NU WH.
23. Conduct mock MIT to 500 PSI.
24. Notify foreman that the well is ready for a witnessed MIT.
25. RDMO.
26. RTI.

**Contact Information:**

Matt Lake – Asset Engineer  
Cell – 713-263-4933  
Office – 281-840-4088

Jess Hayes - Foreman  
Cell – 575-602-3283

