| | Submit 1 Copy To Appropriate District Office | | New Mexico | | | Form C-103 Revised July 18, 2013 |
|------------------------------------|---|---|------------------------|----------------------------|-------------------------------------|-------------------------------------|
| 1 | <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 | Energy, Minerals a | ing Natural K | esources | WELL API NO. | Revised July 16, 201. |
| | <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 | OIL CONSERV | | | 30-025-11297 5. Indicate Type of | Lease |
| | <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 | 0 | St. Francis I | Dr. | STATE | FEE |
| <u>[</u> 1 | <u>District IV</u> – (505) 476-3460 I220 S. St. Francis Dr., Santa Fe, NM 87505 | Santa Fe, | , NM 87505 | | 6. State Oil & Gas | Lease No. |
| | SUNDRY NO | OTICES AND REPORTS ON OPOSALS TO DRILL OR TO DEEP | EN OR PLUG BA | ÇK TO A | | Jnit Agreement Name |
| | DIFFERENT RESERVOIR. USE "AP PROPOSALS.) | PLICATION FOR PERMIT" (FORM | 1 C-101) FOR SUC | INDERS OCD | LANGLIL JAL | |
| | 1. Type of Well: Oil Well | Gas Well 🗌 Other IN. | JECTOR | | 8. Well Number | - |
| 2 | 2. Name of Operator LEGACY | RESERVES OPERATING L | | PR 1 1 2014 | J. OOICID IValliou | 240974 |
| 3 | 3. Address of Operator PO BOX 1 | 10848, MIDLAND, TX 79702 | 2 | RECEIVED | 10. Pool name or W LANGLIE MATTI | |
| 4 | 4. Well Location | <u> </u> | | | | |
| | Unit Letter P | <u>: 660</u> feet from the | | line and <u>66</u> | 0 feet from the | <u>EAST</u> line |
| | Section <u>31</u> | Township | | ange 37E | NMPM | County LEA |
| | | 11. Elevation <i>(Show whe</i> 3242' DF | ether DR, RKB | , <i>RT</i> , GR, etc.) | | |
| | | Appropriate Box to Ind | licate Nature | | Report or Other D | |
| F | | INTENTION TO: PLUG AND ABANDON | | SUD: IEDIAL WORI | | |
| | TEMPORARILY ABANDON | CHANGE PLANS | | | | AND A |
| F | PULL OR ALTER CASING | MULTIPLE COMPL | | SING/CEMENT | ЈОВ 🔲 | |
| | | | | | | |
| | CLOSED-LOOP SYSTEM | \boxtimes | П ОТН | IFB [,] | | П |
| _ | | ompleted operations. (Clearly work). SEE RULE 19.15.7.1 recompletion. | | | | |
| | ~ | r | | | | |
| | | | | | | |
| | SEE ATTACHED P&A | A PROCEDURE ALONG WI | TH CURRENT | & PROPOSE | D WELLBORE DIA | GRAMS |
| | Х | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| G | | | 1 | | |] |
| Sp | oud Date: | Rig R | elease Date: | | | |
| Sp | oud Date: | Rig R | elease Date: | | | |
| | bud Date: | | Į | my knowledge | e and belief. |] |
| I h | | | to the best of | my knowledge JLATORY TF | | 5 <u>04/10/2014</u> |
| I h SI Ty | IGNATURE | ion above is true and complete | e to the best of EREGU | | CHDATH | |
| I h SI Ty <u>Fo</u> Al | IGNATURE | ion above is true and complete | e to the best of EREGU | JLATORY TH | CHDATH | |

.

PROCEDURE TO PLUG AND ABANDON Langlie Jal Unit #27 Langlie Mattix (7-Rivers, & Queen) Field Lea County, New Mexico 4/4/14 AFE# 614028

GENERAL WELL DATA

- 9-5/8" – 36# surface csg @ 1,182', cmt'd w/300 sxs. TOC @ surface by circ.

- 7" – 20# prod. csg @ 3,410', cmt'd w/200 sx. TOC @ 2,191' calc @ 75%

- TD @ 3,540'
- PBTD @ 3,540'
- 7-Rivers perfs: 3,156'-3,515'
- Queen perfs: 3,515'-3,540'

OBJECTIVE: Plug and Abandon Well.

PROCEDURE

- 1. Hold Safety Meeting. High concentrations of H2S may be present. MIRU plugging equipment.
- 2. Kill well if necessary and ND WH, remove any tubing joints, and NU BOP.
- 3. PU work string and RIH to set CIBP @ 3110'.
- 4. Circulate well with mud.
- 5. Spot 25 sxs of cement on top of CIBP, 3110' 2,970'.
- 6. POOH with work string. TO 2600', SPOT 255X5 CMT
- 7. MIRU WL. Piek-up-perf-gun and perf-7" esg @ 1,400'.
- 8. POOH wireline and RIH-with tubing and packer-
- 9. Pump & squeeze-29 sxs of cement into perfs at 1,400' and flush to 1,300'.
- 10. POOH-with-work-string and WOC.
- 11. Tag top of plug @ 1,300².
- 12. Pick up perf gun and perf 7" csg @ 1,232'.
- 13. POOH wireline and RIH with tubing and packer.
- 14. Pump & squeeze 75 sxs of cement into perfs at 1,232' and flush to 1032'.
- 15. POOH with work string and WOC.

- 16. Tag top of plug @ 1032'.
- 17. Pick up perf gun and perf 7" csg @ 400'.
- 18. POOH wireline.
- 19. Pump & squeeze 134 sxs of cement down casing into perfs at 400' and circulate cement to surface. Cement should be on backside of 7" casing.
- 20. RDMO plugging equipment.
- 21. ND BOP.
- 22. Cut off well head and weld on marker.

| PREPARED BY: | _Martin Staelens | DATE:_4/9/14 | | |
|--------------|------------------|--------------|---------|--|
| | | | | |
| APPROVED BY: | Shawn Young | DATE: | 4/10/14 | |



