Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Submit I Copy To Appropriate District State of New Mexico Office District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM88240 District II – (575) 748-1283	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM88240 District II – (575) 748-1283	WELL API NO. 30-025-33967
811 S. First St., Artesia, NM 88210 A 4 20101L CONSERVATION DIVISION	5. Indicate Type of Lease
District III – (505) 334-6178 MAI 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505	STATE FEE
1220 S. St. Francis Dr., Santa Fe, NM RECEIVED	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Hansen State (306601)
1. Type of Well: Oil Well 🗸 Gas Well 🗌 Other	8. Well Number 007
2. Name of Operator Apache Corporation	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705	Monument; Abo, Southeast (96764)
4. Well Location	650 feat from the East line
Section 16 Township 20S Range 37E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3341' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🖸 PLUG AND ABANDON 🗌 REMEDIAL WORK 🗌 ALTERING CASING 🗌	
PULL OR ALTER CASING	
CLOSED-LOOP SYSTEM	
OTHER: OTHER: OTHER:	and give portinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
Apache would like to clean out any fill then perforate and acidize the Abo per the attached procedure.	
Spud Date: 06/30/1997 Rig Release Date: 07/18/1997	7
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE	DATE_05/12/2014
Type or print name Fatima Vasquez E-mail address: Fatima.Vasquez@apachecorp.com PHONE: (432) 818-1015	
For State Use Only	
APPROVED BY: Maley Show TITLE Dist. Supervisor Date 5/14/2014	
Conditions of Approval (if any):	
	MAY 1 4 2014
)

Hansen State #7 API # 30-025-33967 Sec 16, T20S, R37E Elevation: 3570' KB, 3554' GL TD: 7,600' PBTD: 7,424' Casing Record: 8-5/8" 24# J-55 @ 1,166' w/ 590 sxs 5-1/2" 15.5# & 17# K-55 @ 7,600' w/ 665 sxs

Perfs: Abo: 7034-52, 7125-34; 7174-79; 7201-44 w/ 2 jspf (150 holes)

Objective: Clean out any fill and acidize the Abo down tubing, RTP. AFE: 11-14-1829

- 1. MIRU unit. Kill well as necessary. Unseat pump. POOH w/ rods and pump.
- 2. ND WH. NU BOP. Release TAC. POOH w/ tubing.
- 3. PU and TIH w/ bit, bit sub, casing scrapper, and drill collars on 2-7/8" J-55 production tubing to PBTD @ 7,424'. Clean out any fill if above perforations. POOH w/ WS.
- MIRU WL. NU lubricator. PU and RIH with perforator and perforate the Abo from 7289-98; 7305-13; 7370-82; 7393-7402; 7411-17 w/ 2 jspf 120° phasing (88 holes). POOH with perf guns and rig down WL. Correlate to Schlumberger Platform Express Compensated Neutron Three Detector Density/NGT log dated 7/16/1997.
- 5. PU and RIH w/ SN and PKR. Set PKR above new perforations at \pm 7,260'. Monitor backside. *Open perforations above PKR*.
- 6. MIRU acid services. Acidize the Abo (7289-7417) down the tubing with 4,000 gallons 15% NEFE w/ additives dropping 160 ball sealers to divert evenly spaced throughout the job as a max rate but do not exceed **6,000 psi** surface treating pressure. Displace to bottom perf with 46 bbls of flush. Release PKR, TIH and knock balls off. TOOH and set PKR at 7,260'.
- 7. RU swab equipment and recover load and swab test for fluid entry and oil cut. Report results to Midland. RD swab equipment.
- 8. Kill well if necessary. Unset PKR and POOH w/ PKR and 2-7/8" tubing.
- 9. TIH w/ SN and RBP-PKR straddle assembly w/ ball catcher. Set RBP w/ ball catcher at ± 7,270'. TOH and set PKR at 7,250 and test RBP to 1000 psi. Release PKR and TOOH and set PKR above perfs at ± 6,980'. Test backside to 1000 psi.
- 10. MIRU acid services. Acidize down 2-7/8" J-55 tubing w/ 5,600 gals of 15% NEFE HCL w/ additives using 300 ball sealers to divert evenly spaced through the job as max rate but do not exceed 6,000 psi surface treating pressure. Displace to bottom perf with 46 BBLS of flush. RDMO acidizing services.
- 11. Unseat PKR and TIH to knock balls off. TOOH and set PKR at \pm 6,980'.
- 12. RU swab equipment and recover load and swab test perfs for fluid entry and oil cut. Report results to Midland. RD swab equipment.
- 13. Kill well if necessary. TIH to RBP and ball catcher. Latch and release RBP. TOOH w/ PKR-RBP.
- 14. PU and RIH w/ production tbg and rods w/ new pump as per the Monument office specification
- 15. RDMOPU. Return well to production and place into test for 10 days.



