Form 3160-5 August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WE Do not use this form for proposals to drill or to re- abandoned well. Use form 3160-3 (APD) for such pu				OMM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 15: Lease Serial No. NMNM114985		
SUBMIT IN 1	ctions on reverse side		٩	reement, Name and/or No.		
1. Type of Well				8. Well Name and N LIMESTONE 11	o. 23 33 FEDERAL 1H	
2. Name of Operator CHEVRON USA INC	Contact:	CINDY H MURILLO RAMURILLO@CHEVRON				
3a. Address 15 SMITH RD MIDLAND, TX 79705	3b. Phone No. (include area code) Ph: 575-263-0431 Fx: 575-263-0445		10. Field and Pool, or Exploratory BRININSTOOL; BONE SPRING			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, and State		
Sec 11 T23S R33E Mer NMP 150FNL 650FWL				LEA COUNTY, NM		
12. CHECK A	PPROPRIATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE, R	EPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION				
	Acidize	🗖 Deepen	Produc	tion (Start/Resume)	□ Water Shut-Off	
□ Notice of Intent	Alter Casing	Fracture Treat	🗖 Reclam	nation	Well Integrity	
🛛 Subsequent Report	Casing Repair	New Construct	tion 🔲 Recom	plete	🛛 Other	
Final Abandonment Notice	Change Plans	Plug and Aban	don 🗖 Tempo	arily Abandon		
Attach the Bond under which the following completion of the invo testing has been completed. Fina determined that the site is ready f CHEVRON HAS COMPLE 12/23/13 MIRU Halliburton water tanks. Install Restrai tanks for water supply. Fin pumping down backside @ Shut back side pumps dow BHA, N/U to Frac tank. Blo 12/28/13 MIRU Halliburton grease unit. R/U Boots and valve. NU night cap, Rig up crane SISD.	TED THE ABOVE WELL AS Blender and 3 Frac Pumps nt lines on all pressured Iror sh rigging up Halliburton Fra (25 BPM @ 5500 PSOI. Wo n and TOOH with coil tubin w down coil with N2. RDMC wireline unit an crane truck I Coots 200 ton Crane ND 7 o Choke manifold to casing own in 5 mins. Clean out co	the Bond No. on file with B sults in a multiple completio led only after all requirement S FOLLOWS: tied into casing outlets. The Lobo water line in a Pumps, blender and or rk coil tubing out of hole g. N/D BOP's and lubric coil unit and related ec Rig up Halliburton 5 K 1/16 x 10K crown valve valves to bleed casing of	LM/BIA. Required su n or recompletion in a s, including reclamatic Tie blender into fr to fresh water command center. S e from 14,663 to 10 ator , lay down Ok upment. lubricator and e, flow cross and H off if necessary. RE	ibsequent reports shall t new interval, a Form 3 on, have been completed resh Start D, 600. d School tyde D	be filed within 30 days 160-4 shall be filed once	
	Electronic Submission #	243684 verified by the B EVRON USA INC, sent to	LM Well Informatio o the Hobbs	n System		
Name (Printed/Typed) CINDY H MURILLO		Title F	Title PERMITTING SPECIALIST			
Signature (Electro	nic Submission)	Date (04/28/2014			
	THIS SPACE F	OR FEDERAL OR S		ISE	<u></u>	
Approved By		Title	Petroleum Ei	ngineer	Date	
Conditions of approval, if any, are atta certify that the applicant holds legal of which would entitle the applicant to co	equitable title to those rights in th			K2		
Title 18 U.S.C. Section 1001 and Title States any false, fictitious or fraudul				nake to any department	or agency of the United	
** OPEF	ATOR-SUBMITTED ** (PERATOR-SUBMIT	TED ** OPERA	tor-submitte JUN 1		

Additional data for EC transaction #243684 that would not fit on the form

32. Additional remarks, continued

Fesco Accumulator, valves and hose reels. Move in GE well Head Tech, Install flow bushing with BPV with 2 3/8 threads. ND lower master valve and install night cap, rig down choke lines and hyd choke manifold. Load out equipment and move out.

01/03/14 TEC MI spot pipe racks. United Vision deliver and off load 338 joints 2 7/8 L80 6 5#, EUE

L80 tubing and pump joints 2, 4,6, 8, 10 01/06/14 Finish moving in and off loading rig equipment (pump, tank, BOP's, etc) modify rig deck to allow for guide wires to be attached to base beam. R/U TEC 17 with new guide wires to base beam. Raise derrick.

01/08/14 Rig up pump and line. Check for pressure 0 PSI WHP, Open well and continue R/U N/U BOP. After removing night cap discover well has 2 3/8 dummy hanger with BPV installed continue N/U BOP. R/U rig floor and drillers stand.

01/09/14 Pull dimmy hanger 2 3/8 w/BPV out of hole and replace with 2 7/8 dummy hanger with Two-way check. Run in hold down pins. Test BOP 250 PSI low 5000 high on all rams. Hold each test 5 minutes, Lower inside wing valve on BOP, leaking and must be repaired. Hydraulic quick on annular preventer leaking. Replace and test annular preventer to 250 PSI low and 3500 high. Hold each test 5 minutes. Test TIW valves and rig lines to the manifold 250 low and 4000 high PSI. One of the two TIW valves would not test and will be replaced. Hold each test 5 minutes. Test lower wing valve 250 PSI low and 5000 PSI high after being repaired. RU to run production tubing. Move pipe racks and measure row of tubing.

01/10/14 Bring tongs to rig floor and raise hydraulic cat walk side. Have to repair tongs. Rig up slick line. Test lubricator to 2000 PSI. Break circulation down production tubing. Break circulation to insure that tubing is full. Pump at 15 BPM 500 PSI when circulation is gained. RIH with GS pulling tool latch plug in tubing at 10412' WLM and release pump thru plug. POOH with pump thru plug and RD Fesco slick line.

and release On/Off tool and space out. Determine 19.26 pumps needed 20.4. Install hanger and landing pumps and prepare to circulate inhibited packer fluid. Back off landing joints. Install BPV. ND BOP stack. N/U Tree and test, void to 5000 PSI with casing valve open, remove 2 way check from tree and pressure up down tubing to 3400 PSI to blow out pump out plug. Well pressure settles at 2375' PSI. Close casing valve and close upper master wing valve already closed and close crown

valve. Bleed off test pump line and R/D same. SWFD. 01/14/14 Rig down pump and lines. Flush and clean out enviro mat and rig pit , lower derrick and inventory completion equipment. Bring completion equipment to connex for future use. 01/15/14 Move equipment off location and wait on truck to move remaing equipment.