Form 3160-5	UNITED STATES			1		ORM APPROVED	
	PARTMENT OF THE IN				Exp	4B No. 1004-0137 bires: July 31, 2010	
	GEMENT	tions	5. Lea	ase Serial No.	FEE FOO		
Do not use this abandoned well.	NOTICES AND REPOR form for proposals to Use Form 3160-3 (API	drill or to re-e D) for such pr	enter an roposals	6. If I	ndian, Allottee or		
SUBM	IT IN TRIPLICATE – Other in	structions on page	2.	7. If U		nent, Name and/or No. NMNM82050X	
1. Type of Well Oil Well Gas Well Other SEP				8. Well Name and No. CATO SAN ANDRES UNIT NO. 14			
2. Name of Operator Cano Petro of New Mexico, Inc.					9. API Well No. 30-005-20066		
3a. Address 3b. Phone N PO Box 4470, Tulsa, OK 74159-0470 3b. Phone N			ECEIVE de area code) 582-0088	10. Fi	10. Field and Pool or Exploratory Area CATO (SAN ANDRES)		
4. Location of Well (Footage, Sec., T.,R.M. or Survey Description) Unnit Ltr C: 660' FNL & 1980' FWL of Sec 09 - T08S - R 30E			11. Country or Par CH			tate S COUNTY, NEW MEXICO	
12. CHE	CK THE APPROPRIATE BOX(ES) TO INDICATE	NATURE OF	NOTICE, RE	PORT OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent	Acidize	Deepen Fracture Trea	at	Production (Reclamation	Start/Resume)	Water Shut-Off	
	Casing Repair	New Constru		Recomplete		Other	
Subsequent Report	Change Plans	Plug and Ab	andon	Temporarily			
Final Abandonment Notice	Convert to Injection	Plug Back		Water Dispo	sal	<u> </u>	
To return well to production as part 1. MIRU Well Service Unit & circula 2. POOH w/ rods, tbg & Pkr. Test th testing. 3. RIH w/notched collar on 2-3/8" V 4. RIH w/AD-1 style Pkr on WS to 3 5. If well fails pre-test then POOH v 6. Clean-out hole after squeeze cer 7. After passing MIT unseat Pkr. RI 8. Set Pkr, close casing valves & sc begin recovering load. 9. After recovering nost of load, PC 10. RIH w/1 it 2-3/8" tbg bull-plugged 11. RIH w/2' gas separator on botto 12. Long stroke pump with rig to as 13. Hook up flow lines and electrici 14. I hereby certify that the foregoing is	ating tank. Fill with treated lease og on way out of hole to 5000 VS to clean out to PBTD of 33 3150' +/- (No higher than 3122 w/ WS & Pkr. in 100' intervals t menting and re-test csg integr H w/WS & Pkr to 3290'. Spot t queeze acid into existing perfs DOH w/ WS & Pkr. ed for a MA, then 1-4' perfed s om of 1.5" RHTC pump & strai ssure proper pump action. Har ty and POP.	se water. psig and replace a 15'. Circulate botto 2'). Perform pre-te: to locate bad pipe ity. When well pas 2500 gal 15% NEI s. Record bleed off sub of 2-3/8", a 2" ght 3/4" rod string ng well on Pumpin	oms up for 2 hi st of casing to 2 . After discussi ises pre-test sc FE acid to EOT f pressures for SN, & tested 2 to seat pump i g Unit and RDI SUBJECT	rs, then POC 500 psig. Tr on with Tuls chedule with 7. POOH w/ 2 hrs. After 2.3/8" tbg. Pu an SN. MO Well Sei TO	DH w/ same. y to hold steady of a Engineers squ essed MIT w/BL WS & Pkr to 200 that unseat Pkr & at EOT @ 3150'- rvice Unit & circu	for 1/2 hr. eeze bad interval. M - Roswell & NMOCD in Hobbs. 0'. & RIH w/WS & Pkr to 3150' & +/	
 I hereby certify that the foregoing is Name (Printed/Typed) David P. Spencer 		Title	Senior C) Dil and Gas I	Engineer		
Signature		Date	August 12, 2	2014			
	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE	USE		
Approved by /S	/ Angel Mayes		ags And #		•	B-78-14	
Conditions of approval, if any, are attached nat the applicant holds legal or equitable ntitle the applicant to conduct operations	title to those rights in the subject le	t warrant or certify	Office		Da well Field Office	V A	
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repr		••	owingly and will	Ifully to make	to any department of	or agency of the United States any false,	
(Instructions on page 2)							

SEP 1 0 2014 ML





Not to Scale

Macintosh HD:Users:davesp:Desktop:CSAU #14 Proposals and AFE:Present - CSAU #14 Wellbore Diagram.xlsSchematic (1)

BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.