

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-11471
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name LANGLIE JAL UNIT
8. Well Number 68
9. OGRID Number 240974
10. Pool name or Wildcat LANGLIE MATTIX;7RVRS-Q-G

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
LEGACY RESERVES OPERATING LP

3. Address of Operator
PO BOX 10848, MIDLAND, TX 79702

4. Well Location
Unit Letter O : 660 feet from the SOUTH line and 1980 feet from the EAST line
Section 6 Township 25S Range 37E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3219' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☒
OTHER: ☐

E-PERMITTING

RI P&A NR P&A R
CI INT TO P&A COMP
C: CSNG CHG Loc
TA RBDMS CHART
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

---SEE ATTACHED P&A PROCEDURE ALONG WITH CURRENT AND PROPOSED WELLBORE DIAGRAMS---

**The Oil Conservation Division
MUST BE NOTIFIED 24 Hours
Prior to the beginning of operations**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Laura Pina TITLE REGULATORY TECH DATE 01/06/2015

Type or print name LAURA PINA E-mail address: lpina@legacylp.com PHONE: 432-689-5200

For State Use Only

APPROVED BY: Mary Brown TITLE Dist. Supervisor DATE 1/8/2015

Conditions of Approval (if any):

JAN 13 2015

AM

PROCEDURE TO PLUG AND ABANDON
Langlie Jal Unit #68
Langlie Mattix (7-Rivers, & Queen) Field
Lea County, New Mexico
12/17/14
AFE# 615009

GENERAL WELL DATA

- 9-5/8" – 36# surface csg @ 298', cmt'd w/250 sxs. TOC @ surface by circ.
- 7" – 23# prod. csg @ 3,586', cmt'd w/350 sxs. TOC @ 2191' by Calc, DV tool @ 1109'
Cmt'd w/100 sxs, TOC of stage II @ 551' by calc.
- TD @ 3,600'
- PBTD @ 3,585'
- 7-Rivers perfs: 3,194'-3,336'
- Queen perfs: 3,382'-3,494'

OBJECTIVE: *Plug and Abandon Well.*

PROCEDURE

1. Hold Safety Meeting. High concentrations of H2S may be present. MIRU plugging equipment.
2. Kill well if necessary and ND WH and NU BOP.
3. POOH with any tbg in the well.
4. PU work string and TIH and tag CIBP at 3145'. ✓
5. Circulate well with mud.
6. Spot 40 sxs of cement on CIBP from 3145' to 2906'. ✓
7. PUH to 1160'. Spot 25 sxs cement from 1160' to 1010'. ✓ WOC & TAG
8. POOH with work string and WOC.
9. Tag top of plug @ 1010'.
10. Pick up perf gun and perf 7" csg @ 350'. ✓
11. POOH wireline.
12. Pump & squeeze 75 sxs of cement down casing into perfs at 350' and circulate cement to surface.
Cement should be on backside of 7" casing.
13. RDMO plugging equipment.
14. ND BOP.

15. Cut off well head and weld on marker.

APPROVED BY: Shawn Young DATE: 12/17/14

PREPARED BY:

Dominico Carrizales

IMPROVED

02-Apr-12

