Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave. Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-10373
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd Aztec NM 87410	STATE X FEE
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	B-934
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	New Mexico "M" State
1. Type of Well: Oil Well Gas Well Other	8. Well Number 13
2. Name of Operator	9. OGRID Number 008359
GP II Energy	9. OGRID Number 008339
3. Address of Operator	10. Pool name or Wildcat
P. O. Box 50682 Midland, TX 79710	10. 1001 mills of Wildow
4. Well Location	
Unit Letter K: 1980 feet from the S line and 1980 feet from the	
Wline	
Section 20 Township 22S Range 37E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3377'GR	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A DEPARTMENT OF THE PROPERTY	
	_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB
OTHER: OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
See enclosed proposed procedure and well bore diagram.	
* • • • • • • • • • • • • • • • • • • •	1000 3000
	10 10 10 10 10 10 10 10 10 10 10 10 10 1
THE OIL CONSERVATION DIVISION MUST	2
BE NOTIFIED 24 HOURS PRIOR TO THE	1 /
BEGINNING OF PLUGGING OPERATIONS.	
	Mar - 18 D
I hereby certify that the information above is true and complete to the least of th	11.11.0
I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or cipsed according to NMOCD guidelines [], a general permit []	and belief. I further certify that any pit or below-
	or an (actached) afternative OCD-approved plan [
SIGNATURE DATE 11/08/05	
Type or print name Joe Compton E-mail address: joe@gp2energy.com Telephone No. 432-684-4748 Alexander	
Type or print dame Joe Compton E-mail address: joe@gp2energy.com Telep	ohone No. 432-684-4748 NOV 1 8 2005
APPROVED BY: WALL OC FIELD REPRESENTATIVE IL/STAFF MANIADATE	
V The state of the	

GP II ENERGY, INC. NEW MEXICO "M" STATE #13 1980' FSL & 1980' FWL SEC 20, T22S, R37E LEA COUNTY, NEW MEXICO


T.D. 3668' PBTD: 3510'

STATE LEASE #: B-934

SPUD DATE:

COMP. DATE: DEC. 20, 1957

GL ELEVATION: 3377' DF ELEVATION: 3386'



Squeeze and Plugging Procedures for the New Mexico "M" State #13

- 1. RUPU.
- 2. Install and test BOP.
- 3. Pressure up backside to 500# for 15' to check tubing casing integrity. Casing leaks are common in this area from 300' to 700'. If there are casing leaks, determine where they are. If there are no casing leaks, TOH with Packer.
- 4. GIH with wire line CIBP and set at approximately 3430'. GIH with bailer and dump 35' cement on CIBP. GIH with tbg open ended and tag plug set above CIBP. PU and circulate hole with plugging mud.
- 5. Perforate and squeeze 25 sack cement plug at 1650'. WOC and tag plug. Perforate casing at top of salt @ 1100'. Pump 25 sack cement plug. WOC and tag plug. If there are holes in the casing and they are close to top of salt pump plug sufficient to cover both. WOC.
- 6. PU and pump 100'+ cement plug across 8 5/8" shoe, sufficient to bring plug 50'+ above top of shoe and 50'+ below 8 5/8" casing shoe. PU and WOC.
- 7. Tag plug set across 8 5/8" shoe. PU and set surface plug.
- 8. Cut off casing and set dry hole marker.
- 9. Clean and remeditate location.

Note: The NMOCD will be notified at least 24 hours before starting work on well.