
| Submit 3 Copies To Appropriate District | State of New Me | | | Form C-103 |
|---|--|--|--|--------------------|
| Office District I | Energy, Minerals and Natur | al Resources | | May 27, 2004 |
| 1625 N. French Dr., Hobbs, NM 87240 | | | WELL API NO. | 25 |
| District II 1301 W. Grand Ave., Artesia, NM 88210 | OIL CONSERVATION DIVISION | | 30 - 025 - 24635 5. Indicate Type of Lease | |
| District III | 1220 South St. Francis Dr. | | I | 1 |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV | Santa Fe, NM 87 | 7505 | STATE X | FEE |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | | 6. State Oil & Gas Leas | se No. |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | | | 7. Lease Name or Unit Agreement Name: ARES STATE | |
| PROPOSALS.) 1. Type of Well: | | | 8. Well Number | |
| Oil Well Gas Well X Other | | | 1 | |
| 2. Name of Operator MISSION RESOURCES CORPORATION | | | 9. OGRID Number 148381 | |
| 3. Address of Operator | | | 10. Pool name or Wild | cat |
| 1100 LOUISIANA, STE. 1455 HOUSTON, TX 77002 | | | JALMAT; TAN, YATES, 7-RVRS (GAS) 79240 | |
| 4. Well Location | | | | |
| Unit Letter A: | 660 feet from the NOR | TH line and | 660 feet from the | EAST line |
| Section 16 | Township 23S | Range 36E | NMPM C | ounty LEA |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3454'DF | | | | |
| Pit or Below-grade Tank Application or Closure | | | | |
| Pit type N/A Depth to Groundwater 149 Distance from nearest fresh water well 1000+ Distance from nearest surface water 1000+ | | | | |
| Pit Liner Thickness: N/A mil | Below-Grade Tank: Volume_ | bbls; Construction | on Material | |
| 12. Check A NOTICE OF INTERPRETARY ABANDON | Appropriate Box to Indicate ENTION TO: PLUG AND ABANDON X CHANGE PLANS | | SEQUENT REPOR | |
| PULL OR ALTER CASING | MULTIPLE COMPLETION | CASING TEST AND CEMENT JOB | _ | |
| OTHER: | | OTHER: | | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | | | | |
| See attached for revised Procedure and Wellbore Schematic to Plug and Abandon Well. THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE | | | | |
| TI- | E OIL CONSERVATION | i division mus | $\int_{\mathcal{E}} \mathcal{E}_{\mathcal{E}} $ | 20 20 22 |
| P | E NOTIFIED 24 HOURS | PRIOR TO THE | 6016 | 32 |
| , Di | GINNING OF PLUGGIN | IG OPERATION | | 10 A |
| Di | Editabling of Fedgen | O OI E | 100 | |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative QCD-approved plan | | | | |
| SIGNATURE SIGNATURE | TIT | | Coordinator DA | 10/00/05 |
| Type or print name Valorie J. Ga | E-r | nail address: | | e No. 832-369-2125 |
| For State Use Only a | . 1 | | F | |
| APPROVED BY Lay W. | Wink | NJE 3 is eigen hat fra fra fra fra | TAGE ALABEA CEADAT | PEC 0 6 2005 |
| Conditions of Approval, if thy: | | State State State V & State St | TOTAL TOTAL STREET | |



Mission Resources Corp. Ares State #1 Jalmat Field Lea County, NM November 29, 2005

Plugging and Abandonment Procedure

- 1. MIRU work over rig. Kill well. Install BPV. ND tree. NU BOP's.
- 2. POOH with rods & tubing.
- 3. RU EL. Run GR/junk basket to 3315'±. Set CIBP @ 3300'±. Dump bail cement on top of CIBP. Test casing to 500 psi..
- 4. TIH with workstring. Load hole with gelled 10# brine.
- 5. Mix and spot 200' cement plug from 2880-3080' (base of salt @ 2980').
- 6. Mix and spot 200' cement plug from 1270-1470' (top of salt @ 1370').
- 7. Perforate 5-1/2" casing at 450'.
- 8. Squeeze perfs @ 345' and circulate to surface with 150 sxs cement.
- 9. Cut off wellhead weld on P&A marker.
- 10. Clean off location for OCD inspection.

VEITHER PERF & CIR, TO SURFACE OR PERF & SQZ. F/ 1420-1320'0