Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources	May 27, 2004
7625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-025-29622
1301 W. Grand' Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd Aztec NM 87410	STATE x FEE
District IV Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	23000
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Eunice Monument South Unit
PROPOSALS.)	8. Well Number 462
1. Type of Well: Oil Well Gas Well X Other Convert to Producer 2. Name of Operator	9. OGRID Number 5380
XTO ENERGY INC.	9. OGRID Number 3360
3. Address of Operator 200 LORAINE STE 800 MIDLAND, TX 79701	10. Pool name or Wildcat
200 LORAINE STE 800 MIDLAND, TX 79701 4. Well Location	Eunice Monument; Grayburg-San Andres
Unit Letter L: 2590 feet from the 5 line and	50 feet from the W line
Section 9 Township S21 Range 36E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR,	
Pit or Below-grade Tank Application □ or Closure □	
Pit typeDepth to GroundwaterDistance from nearest fresh water well	Distance from manual surface weeks
	Distance from nearest surface water Construction Material
12. Check Appropriate Box to Indicate Nature of Not	ce, Report of Other Data
	UBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL V	<u> </u>
<u></u>	DRILLING OPNS. P AND A
PULL OR ALTER CASING	MENT JOB
	-
OTHER: X CONVERT TO PRODUCER OTHER:	
OTHER: X CONVERT TO PRODUCER OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details	, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions	
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion.	
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER	
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR	
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND 10 CS	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND 1 D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INJ RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50' ABOVE LEAK, CIRC THRU CICR, SQZ LEAK	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND 1 D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INJ RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50' ABOVE LEAK, CIRC THRU CICR, SQZ LEAK RIH W/ BIT AND DO CICR AND CMT TO 4240', TST SQZ TO 500 PSI, POH	Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND 10 D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INJ RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50' ABOVE LEAK, CIRC THRU CICR, SQZ LEAK RIH W/ BIT AND DO CICR AND CMT TO 4240', TST SQZ TO 500 PSI, POH CONTINUE W/PERF & ACD FROM ABOVE PROCEDURE	Attach wellbore diagram of proposed completion /EVERY 10 BBLS .NR, CMT LNR, POH, WOC
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INJ RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50' ABOVE LEAK, CIRC THRU CICR, SQZ LEAK RIH W/ BIT AND DO CICR AND CMT TO 4240', TST SQZ TO 500 PSI, POH CONTINUE W/PERF & ACD FROM ABOVE PROCEDURE I hereby certify that the information above is true and complete to the best of my know	Attach wellbore diagram of proposed completion /EVERY 10 BBLS LNR, CMT LNR, POH, WOC
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275′, DUMP 35′ ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½″ FLOAT SHOE, 1 JT 5 ½″ CSG, LND COLLAR 1000′ 5 ½″ CSG AND D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH CO/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INJ RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50′ ABOVE LEAK, CIRC THRU CICR, SQZ LEAK RIH W/ BIT AND DO CICR AND CMT TO 4240′, TST SQZ TO 500 PSI, POH CONTINUE W/PERF & ACD FROM ABOVE PROCEDURE I hereby certify that the information above is true and complete to the best of my know grade tank has been/will be constructed or/closed according to NMOCD guidelines □, a general perm	Attach wellbore diagram of proposed completion /EVERY 10 BBLS LNR, CMT LNR, POH, WOC ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INJ RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50' ABOVE LEAK, CIRC THRU CICR, SQZ LEAK RIH W/ BIT AND DO CICR AND CMT TO 4240', TST SQZ TO 500 PSI, POH CONTINUE W/PERF & ACD FROM ABOVE PROCEDURE I hereby certify that the information above is true and complete to the best of my know	Attach wellbore diagram of proposed completion /EVERY 10 BBLS LNR, CMT LNR, POH, WOC ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan .
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275′, DUMP 35′ ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½″ FLOAT SHOE, 1 JT 5 ½″ CSG, LND COLLAR 1000′ 5 ½″ CSG AND D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH CO/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INJ RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50′ ABOVE LEAK, CIRC THRU CICR, SQZ LEAK RIH W/ BIT AND DO CICR AND CMT TO 4240′, TST SQZ TO 500 PSI, POH CONTINUE W/PERF & ACD FROM ABOVE PROCEDURE I hereby certify that the information above is true and complete to the best of my know grade tank has been/will be constructed or/closed according to NMOCD guidelines □, a general perm	Attach wellbore diagram of proposed completion /EVERY 10 BBLS INR, CMT LNR, POH, WOC ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan YSTDATE11/18/2005
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND 10/0 CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INI RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50' ABOVE LEAK, CIRC THRU CICR, SQZ LEAK RIH W/ BIT AND DO CICR AND CMT TO 4240', TST SQZ TO 500 PSI, POH CONTINUE W/PERF & ACD FROM ABOVE PROCEDURE I hereby certify that the information above is true and complete to the best of my know grade tank has been will be constructed or closed according to NMOCD guidelines TITLE REGULATORY ANAL	Attach wellbore diagram of proposed completion /EVERY 10 BBLS INR, CMT LNR, POH, WOC ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan YSTDATE11/18/2005
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERR UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INJ RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50' ABOVE LEAK, CIRC THRU CICR, SQZ LEAK RIH W/ BIT AND DO CICR AND CMT TO 4240', TST SQZ TO 500 PSI, POH CONTINUE W/PERF & ACD FROM ABOVE PROCEDURE I hereby certify that the information above is true and complete to the best of my know grade tank has been/will be constructed or/closed according to NMOCD guidelines □, a general pern SIGNATURE M. LYN MARR E-mail address: Lyn Marr@xtoen For State Use Only	Attach wellbore diagram of proposed completion /EVERY 10 BBLS LNR, CMT LNR, POH, WOC ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan YSTDATE11/18/2005 ergy.comTelephone No432-620-6714
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSI, POH C/O LNR, TST TO 500 PSI, POH PERF/ACD AS ABOVE SUPPLEMENTAL PROCEDURE FOR SQUEEZING LEAK ISOLATE LEAK, TST INJ RATE/PSI, POH W/PKR AND RBP RIH W/CICR TO 50' ABOVE LEAK, CIRC THRU CICR, SQZ LEAK RIH W/ BIT AND DO CICR AND CMT TO 4240', TST SQZ TO 500 PSI, POH CONTINUE W/PERF & ACD FROM ABOVE PROCEDURE I hereby certify that the information above is true and complete to the best of my know grade tank has been/will be constructed or closed according to NMOCD guidelines TITLE REGULATORY ANAL Type or print name M. LYN MARR E-mail address: Lyn Marr@xtoen	Attach wellbore diagram of proposed completion /EVERY 10 BBLS LNR, CMT LNR, POH, WOC ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan YSTDATE11/18/2005 ergy.comTelephone No432-620-6714