

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-07168
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name M. M. Harris
8. Well Number 2
9. OGRID Number 227103
10. Pool name or Wildcat SWD; Devonian (96101)


<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> SWD	
2. Name of Operator Platinum Exploration Inc	
3. Address of Operator 550 W. Texas, Suite 500 Midland, TX 79701 432-687-1664	
4. Well Location Unit Letter <u>D</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>8</u> Township <u>12S</u> Range <u>38E</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3869' GR	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input checked="" type="checkbox"/>
--	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached: 11/14/05 - 12/6/05



SWD-991

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Debbie Freeman TITLE Agent DATE 12/7/05

Type or print name Debbie Freeman

E-mail address: debbief@t3wireless.com

Telephone No. 432-687-1664

For State Use Only

APPROVED BY: Hayward W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE \_\_\_\_\_

Conditions of Approval (if any):

DEC 13 2005

**Platinum Exploration Inc**  
**MM Harris #2 SWD**  
**Lea County, NM API#3002507168**  
**UL D Sec 8 TS 12S R 38E**

**11/14/05**

MI RU PU. POOH w/ tbg, Tag @ 6673', drill out wire, perforating debris and cmt from 6673-6690', Wash down to 7607' RIH circ out heavy mud every 1000', tag @ 11725'. Attempt to drill – unable to make new hole, drilling on steel. Displace hole w/ 550 bbls FW. RIH tag 7 7/8" open hole @ 4497' Tag 5 1/2 csg @ 4868'. Milled down to 4870'. RIH w/ mill, DC, SN and tbg. Tag top of 5 1/2 csg @ 4870', work shoe over top of csg & EO shoe @ 4879' and tag top of 5 1/2 w/ mill @ 4870'. Dress off top of 5 1/2 csg from 4870'- 4875', circ clean & POOH, RIH Work to latch onto 5 1/2 csg @ 4875', release spear & POOH. RIH Attempt to latch onto 5 1/2 csg @ 4875' w/ no success. RIH w/ mill, XO, 4 – 4" DC, SN and 146 jts 2 7/8 EUE 8 rd L80 tbg. Tag top of 5 1/2 csg @ 4875' w/ shoe, mill to 4877' w/ shoe & fall over top of 5 1/2 csg. RIH tag top of 5 1/2 w/ concave mill. Dress off top of 5 1/2 csg from 4875-4880' & circ clean. POOH and LD skirted mill, Latch onto 5 1/2" csg at 4,880', Attempt to pressure up on 5 1/2" csg. Pump 2.5 bpm at 300 PSI, and circ out 9 5/8" csg. Release OS, and POOH. RIH w/ 5 1/2" RBP, Ret tool, SN, and 215 jts 2 7/8 " EUE 8rd L80 tbg. Set plug at 7,000'. Dump 2 SX sand on plug, and POOH w/ 143 jts 2 7/8" EUE 8rd L80 tbg. PU & RIH w/ 5 1/2 lead seal csg patch, 5 1/2 circ sub, 5 1/2 float collar, 14 jts 5 1/2 17# K55 csg (556'), 5 1/2 releasing sleeve w/ 8 3/8 liner entry guide, XO, 131 jts 2 7/8 EUE 8 rd L80 tbg and 18' x 2 7/8 EUE 8 rd L80 tbg subs. Latch onto 5 1/2 csg @ 4880'. Pump 12 bbls FW to catch circ @ 3 BPM @ 250 psi. Pump 325 sx 14.6# class C, 50/50 poz cmt (72 bbls) @ 2.9 BPM @ 200 psi. ,pump 25 bbls FW. Latch tbg wipe into csg wiper and prs to 1800 psi to shear csg wiper. Cont to displace w/ FW @ 2 BPM w/ prs increasing to 500 psi. Pump total of 38.25 bbls to latch casing wiper into FC. Prs to 1500 psi – bleed off and POOH w/ tbg subs & 8 jts 2 7/8 EUE 8 rd L80 tbg. Reverse out w/ 80 bbls FW (circ out 20 bbls cmt). Tag cmt @ 4045', test 9 5/8" csg to 1000 psi for 5 min – no leak. Drill out hard cmt from 4045 to top of 5 1/2 csg @ 4300'. Circ clean and test liner top to 1000 psi for 5 min – OK. RIH Tag cmt at liner top (4300'). Drill out med hard cmt from 4300' to 4313'. Fall out, and circ clean. RIH tag cmt at 4860'. Drill out cmt to wiper plug at 4876'. Drill out both wiper plugs and float collar. Drill cmt from float collar at 4878' to 4912'. Fall out at 4912' and circ clean. Test csg to 1000 psi for 5 min. Test good. No leak. POOH and LD bit. RIH w/, Work mill through top of 5 1/2" liner from 4300' to 4312'. RIH work liner thru float collar at 4877'. RIH w/ 108 jts 2 7/8" EUE 8rd L80 tbg. Tag sand at 6992'. Wash out sand to RBP at 7000'. Tag liner top at 4300', Dress off liner top. RIH Tag at 11,726'. Test csg to 1000 psi for 5 min. Test good. No leak. Mill metal, cmt, and wire from 11,725' to top of model D at 11,993' and test csg to 1000 psi for 5 min. Test good, no leak. Mill on model D from 11,995' to 11,996'.