Form 3160-5 (September 2001)		proposals to drill	NT <b>1</b> ON WELLS	625 N. Obbs, f <sup>er an</sup>	Cons. I French NM 882	FOI Division DM Expire 5. Lease Serial 40 40 40 40 40 40 40 40 40 40 40 40 40	RM APPROVED B NO. 1004-0135 ss January 31, 2004 No.
	SUBMIT IN TRIPLICATE -					7. If Unit or C/	A/Agreement, Name and/or No
1. Type of Well     Gas Well       X     Oil Well     Gas Well       2. Name of Operator     Gas Well						8. Well Name and No. LEA CHAPPARRAL FED #1	
P.O. BOX 140907, IRVING, TX 75014-0907           4. Location of Well (Footage, Sec., T. R., M., or Survey Description)				0. ( <i>include arc</i> <b>401.0752</b>	ea code)	<ul> <li>9. API Well No.</li> <li>30-025-30413</li> <li>10. Field and Pool, or Exploratory Area</li> <li>QUAIL RIDGE</li> </ul>	
UNIT LETHER K 1980' FSL & 1980' FWL K SEC. 33, T-19-S, R-34-E						11. County or <b>IEA</b>	NM
12.	CHECK APPROPRIATE	BOX(ES) TO IN	DICATE NA	TURE OF N	IOTICE, REI	PORT, OR OTH	IER DATA
TYPE	TYPE OF SUBMISSION					N	
Sut     S	tice of Intent exequent Report at Abandonment Notice sed or Completed Operation (clear is to deepen directionally or recomplet d under which the work will be pe- oletion of the involved operations. n completed. Final Abandonment the final site is ready for final inspe- <b>DIEUM MANAGEMENT CO. REX</b> <b>TIONS AS PER THE ATTACHE</b> <b>TIACT DAVID EYLER AT 432</b>	plete horizontally, give s rformed or provide the If the operation results in Notices shall be filed or etion.) <b>DESTS APPROVAL</b> <b>D PLUGGING PROC</b>	New	ure Treat Construction and Abandon Back stimated startin tions and meas file with BLM/ mpletion or re uirements, inc	Reclamat Recomp Tempora Water D Water D ured and true v BIA. Required completion in a luding reclamat	lete arily Abandon isposal proposed work and certical depths of al i subsequent report a new interval, a Fe tion, have been co	I pertinent markers and zones. s shall be filed within 30 days orm 3160-4 shall be filed once mpleted, and the operator has
	CONCINCICO CONCINCICO		34535 /// //// /////////////////////////	1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.		JUL - 7 GARY GOU	2003 RLEY
	hat the foregoing is true and correct ( <i>pped</i> )		Title				
	A. EYLER	7	Date	AGENT 06/28/03	3		
		S SPACE FOR FEI					
Approved by		<u></u>	Ti	tle		D	ate

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

i.

Gruy Petroleum Management Company Lea Chaparral Fed. #1 A.P.I. #: 30-025-30413 Lease Serial #: NM-60789 Field: Quail Ridge Location: NE/4, SW/4 Sec. 33, Twp. 19S, Rge. 34E Lea County, New Mexico

 Completion Date: 07/19/88

 Total Depth:
 13,690° P.B.T.D.: 9410° (05/98)

 Casing Data:
 13-3/8° 54.5# @ 515° w/ 660 sxs. – Cement circulated to surface.

 9-5/8° 40# N-80 @ 5300° w/ 2750 sxs. – TOC = 25° (TS) DV Tool @ 3304°

 5-1/2° 20# & 17# N-80 & L-80 @ 13680° w/ 1400 sxs. – TOC = 8100° (TS)

 Tubing Data:
 2-7/8° J-55 @ 9300° (Estimated – No tubing detail available)

 Rod Data:
 (370 – Estimated – No rod detail available)

 Open Perfs:
 7046°-56° (Brushy Canyon) and 8672°-9012° (Bone Springs)

 Remarks:
 Squeeze holes @ 6846° w/ 140 sxs. and 7300° w/ 130 sxs.

## PXA PROCEDURE

P

- 1) MIRU work rig & PXA equipment.
- 2) POOH laying down rods. ND tree & NU BOP's; Release TAC & POOH standing back 2-7/8" tbg.; Remove TAC & RIH w/ tubing OE to 8650'. Mix & pump a 25 sx. class "C" cmt. plug @ 8450'-8650'; POOH w/ tbg. & WOC; RIH w/ tbg. & tag cmt. plug; POOH laying down tbg. to 7000'; Mix & pump a 25 sx. class "C" cmt. plug @ 6800'-7000'; POOH w/ tbg. & WOC; RIH w/ tbg. & tag top of cmt. plug; POOH w/ tbg. standing back 5400' & laying down the balance.
- 3) ND BOP's & NU casing jacks & equip.; Work stretch on 5-1/2" csg.; RUWL & csg. cutter & RIH & cut 5-1/2" casing; POOH & RDWL; POOH laying down 5-1/2" casing; ND csg. equip. & NU BOP's.
- 4) RIH w/ tbg. OE to 5400'; Mix & pump a 90 sx. class "C" cmt. plug @ 5200'-5400'; POOH w/ tbg. & WOC; RIH w/ tbg. & tag top of cmt. plug.
- 5) POOH laying down tbg. to 2000'; Mix & pump a 50 sx. class "C" cmt. plug @ 1900'-2000'; POOH w/ laying down tbg. to 565'; Mix & pump a 50 sx. class "C" cmt. plug @ 465'-565'.
- 6) POOH w/ laying down tubing to 63' & mix & pump a 25 sx. cmt. surf. plug @ 3'-63'. FOOH w/ tubing.
- 7) Dig out and cut off well head 3' B.G.L.; Weld steel plate on top of casings & set dry hole marker.
- 8) RDMO rig and PXA equipment. Clean location.

