				FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				LC 029405A 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. 8920003410		
1. Type of Well Gas Well Other Inject				8. Well Name and No.		
2. Name of Operator ConocoPhillips Company				MCA Unit #020 9. API Well No.		
3a Address 4001 Penbrook, Odessa, Texas	3b. Phone No. (include area code) 432-368-1244		30-025-08029 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., 2			Maljamar GB/SA			
660' FNL & 1,980' FEL, Unit 1	₹-32-Е		11. County or Parish, State Lea			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat	Production (St Reclamation Recomplete	Start/Resume) Water Shut-Off		
Subsequent Report	Change Plans	Plug and Abandon	Temporarily A			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposa	any proposed work and approximate duration thereof.		
APPROVED FOR MONTH PERIOD				in a new interval, a Form 3160-4 shall be filed once		
			L			
 I hereby certify that the fore Name (Printed/Typed) James F. Newman 		Title E	ngineer, Triple N S	ervices, Inc. 432.687.1994		
Signature	K	Date		01/11/2006		
	THIS SPACE FOR	FEDERAL OR S	TATE OFFICI	E USE		
Approved by <u>Hauy</u> Conditions of approval, if any, are certify that the applicant holds easy which would entitle the applicant t	d or equitable title to those rights	does not warrant or	Title	Date		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						
(Instructions on page 2) GWW						

.



ConocoPhillips

Proposed Plugging Procedure

MCA Unit #20W Maljamar (Grayburg-San Andres) Field Lea County, New Mexico

Casings: 8⁵/₄" 28# casing @ 694', cmt'd w/ 50 sx 7" 20# casing @ 3,585' w/ 150 sx, TOC 1,640' calculated

- TA'd w/ Otis Interlock packer & tbg plug @ 3,533' (set 04/10/95)
- Notify BLM & NMOCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- 1. Set steel pit and flow down well as needed.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 5,000# hydraulic BOP.
- **3.** RIH w/ 2³/₈" EUE workstring to packer @ 3,533'. RU cementer and circulate hole w/ mud, pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 145' in 7" 20# casing) 3,533 3,389'. *Grayburg-San Andres plug*
- 4. POOH w/ tubing to 1,930'. RU cementer and load hole w/ mud, pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 145' in 7" 20# casing) 1,930 1,785'. Base of salt plug
- 5. RU lubricator and RIH w/ 1-11/16" link-jet perforating charges on wireline, and perforate four squeeze holes @ 830'. POOH w/ wireline.
- 6. RIH w/ AD-1 packer to 400'. Load hole w/ mud and set packer. Establish rate into perforations, maximum pressure 1,000 psi. Squeeze 75 sx C cmt w/ 2% CaCl₂ (1.32 ft³/sk yield, 99.0 ft³ slurry volume, calculated fill 277' in 8⁵/₈" casing) 830 553'. WOC and tag this plug no deeper than 654'. POOH w/ packer. **Top of Salt & surface casing shoe plug**
- **7.** RIH w/ 1-11/16" link-jet perforating charges on wireline, and perforate four squeeze holes @ 400'. POOH w/ wireline.
- RIH w/ AD-1 packer to 30'. Set packer and establish circulation to surface in 7 x 8⁵/₈" annulus. POOH w/ packer and ND BOP, NU wellhead. Circulate 115 sx C cement (1.32 ft³/sk yield, 152 ft³ slurry volume, calculated fill 423' in 8⁵/₈" casing) 400' to surface. *freshwater & surface plug*
- **9.** RDMO location. Clean steel pit & haul fluids to disposal. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit

Date: July 22, 2005



PROPOSED PLUGGED WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit

Date: January 11, 2006

