Form 3160-5 (April 2004) UNITED STATES OCD-HOBBS DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.				5. Lease S	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No. LC 029405A 6. If Indian, Allottee or Tribe Name	
				6. If Ind		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					t or CA/Agreement, Name and/or No. 003410	
1. Type of Well Gas Well I Other					Name and No.	
2. Name of Operator ConocoPhillips Company					MCA Unit #054 9. API Well No.	
3a. Address 4001 Penbrook, Odessa, Texas	3b. Phone No. (include area code) 432-368-1244		30-0	30-025-08039 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.,			Maljamar GB/SA			
1980' FNL & 1980' FWL, Unit Letter F, Section 19, T-17-S, R-32-E				11. County or Parish, State		
				Lea	Lea	
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NAT	URE OF NOTICE,	REPORT, O	OR OTHER DATA	
TYPE OF SUBMISSION		Т	YPE OF ACTION			
Notice of Intent	Acidize	Deepen Fracture Treat	Production (Start/Resume)	Water Shut-Off	
Subsequent Report	Casing Repair	New Constructio			Other	
Final Abandonment Notice	Change Plans	Plug and Abando	n Temporarily			
determined that the site is ready for final inspection.) See attached current & proposed wellbore diagrams & procedure.				F	APPROVED	
					JAM 2 6 2006	
APPROVED FOR MONTH PERIOD				L	GARY GOURLEY	
ENDING 8-26-06				F	PETROLEUM ENGINEER	
14. I hereby certify that the fore						
Name (Printed/Typed) James F. Newma		Title	Engineer, Triple N S	Services. Inc.	432.687.1994	
Signature	AL-	Date		01/11/2006		
	THIS SPACE FOR F			FIISE	······································	
M	1, 1 0					
Approved by Lawy L). Wink		Title		Date	
Conditions of approval, if any, are a certify that the applicant hold regal which would entitle the applicant to	l or equitable title to those rights in	the subject lease	Office		·	
	43 USC Section 1212 make it a	crime for any person is to any matter within	knowingly and willfull its jurisdiction.	y to make to a	ny department or agency of the United	
(Instructions on page 2)						
GWW						

į



ConocoPhillips

Proposed Plugging Procedure

MCA Unit #54W Maljamar (Grayburg-San Andres) Field Lea County, New Mexico

Casings: 8⁵/₈" 28# casing @ 745', cmt'd w/ 50 sx 7" 20# casing @ 3,453' w/ 150 sx, TOC 1,340' calculated 4¹/₂" 9.5# liner surface to 3,550', cmt'd w/ 185 sx, TOC 1,385' calculated 5¹/₂" liner 3,743 – 3,808'

- TA'd w/ cement retainer set @ 3,453' (02/06/95)
- Notify BLM & NMOCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- 1. Set steel pit and flow down well as needed.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 5,000# hydraulic BOP. Flow down/kill well as needed, POOH laying down injection tubing & packer as present.
- **3.** RIH w/ 2³/₆" EUE workstring, tag CICR @ 3,453'. RU cementer and circulate hole w/ mud, pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 362 in 4½" 9.5# casing) 3,453 3,099'. *Grayburg-San Andres plug*
- POOH w/ tubing to 1,915'. RU cementer and load hole w/ mud, pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 362' in 4½" 9.5# casing) 1,915 1,553'.
 Base of salt plug
- POOH w/ tubing to 1,400'. RU cementer and load hole w/ mud, pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 362' in 4½" 9.5# casing) 1,400 1,038'.
- 6. RU lubricator and RIH w/ four 2½" strip-jet perforating charges on wireline, and perforate four squeeze holes @ 815'. POOH w/ wireline.
- 7. RIH w/ AD-1 packer to 400'. Load hole and set packer. Establish rate into perforations, maximum pressure 1,000 psi. Squeeze 50 sx C cmt w/ 2% CaCl₂ (1.32 ft³/sk yield, 66 ft³ slurry volume, calculated fill 188' in 85%" 28#casing) 815 695'. WOC and tag this plug no deeper than 695'. POOH w/ packer. Top of Salt & surface casing shoe plug
- 8. RIH w/ four 2½" strip-jet perforating charges on wireline, and perforate four squeeze holes
 @ 400'. POOH w/ wireline.
- 9. RIH w/ AD-1 packer to 30'. Set packer and establish circulation to surface in 7 x 8%" annulus. POOH w/ packer and ND BOP, NU wellhead. Circulate 75 sx C cement (1.32 ft³/sk yield, 99 ft³ slurry volume) 400' to surface. *freshwater & surface plug*

CURRENT WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit



١

PROPOSED PLUGGED WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date: January 11, 2006

