Submit 3 Copies To Appropriate District Office	State of New Me	xico	56Form C-103
District I	Energy, Minerals and Natur		HLAPINO V May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		20	LL API NO. FEA 2008
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION	Indicate Type of trease Received
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran	cis Dr.	STATE NO FEE MAN
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	0. 1	State Oil & Gas Lease No. OCD
87505		B78	
SUNDRY NOTICES DO NOT USE THIS FORM FOR PROPOSALS	S AND REPORTS ON WELLS		Lease Name or Unit Agree Store
DIFFERENT RESERVOIR. USE "APPLICATI	ION FOR PERMIT" (FORM C-101) FO	D CUCU	rington Paddock Unit
PROPOSALS.) 1. Type of Well: Oil Well 🔲 Gas	s Well 🔲 Other: Injection		Well Number: 39
2 Name of Operator			OGRID Number
Chevron USA-Inc Pure	Resources LS)	
3. Address of Operator			Pool name or Wildcat
P.O. Box 7139, Midland, Texas 79708	}	Lov	rington (Paddock)
4. Well Location			/
		<u>h</u> line and <u>660</u>	feet from the <u></u> line
Section 36			MPM County Lea
	1. Elevation (Show whether DR, 830' DF	RKB, RT, GR, etc.)	
it or Below-grade Tank Application D or Cl		· · · · · · · · · · · · · · · · · · ·	
it type_STEELDepth to Groundwate	r_60Distance from nearest fresh	water well_over 1000 Distan	ce from nearest surface water
it Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construc	tion Material
12. Check Apr	propriate Box to Indicate Na	ature of Notice Rep	ort or Other Data
	-		
NOTICE OF INTE			QUENT REPORT OF:
		REMEDIAL WORK	
—	HANGE PLANS	COMMENCE DRILLING	
		CASING/CEMENT JOL	
		OTHER:	_
13. Describe proposed or complete	d operations. (Clearly state all p	ertinent details, and give	e pertinent dates, including estimated date
13. Describe proposed or complete of starting any proposed work).	d operations. (Clearly state all p SEE RULE 1103. For Multipl	ertinent details, and give	e pertinent dates, including estimated date wellbore diagram of proposed completion
 Describe proposed or complete of starting any proposed work). or recompletion. 	SEE RULE 1103. For Multipl	ertinent details, and give	e pertinent dates, including estimated date wellbore diagram of proposed completion
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h 	SEE RULE 1103. For Multiplars. prior to MI&RU.	ertinent details, and give e Completions: Attach	wellbore diagram of proposed completion
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme 	SEE RULE 1103. For Multiplurs. prior to MI&RU. ent under packer at 5,948' (ertinent details, and give e Completions: Attach (Paddock,open hole)	wellbore diagram of proposed completion
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme 3. Displaced hole w/MLF 	SEE RULE 1103. For Multiplurs. prior to MI&RU. ent under packer at 5,948' (7, 9.5 ppg brine w/12.5 gel j	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl.	WOC Tagged @ 5,975'.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme 3. Displaced hole w/MLF 4. Spotted 25sx plug from 	SEE RULE 1103. For Multiplurs. prior to MI&RU. ent under packer at 5,948' (7, 9.5 ppg brine w/12.5 gel j	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme 3. Displaced hole w/MLF 4. Spotted 25sx plug from 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p 1 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme 3. Displaced hole w/MLF Spotted 25sx plug from 5. Perf'd and squeezed 45 Unable to pull casing, p Squeezed 80sx plug from 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p a 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme 3. Displaced hole w/MLF Spotted 25sx plug from 5. Perf'd and squeezed 45 Unable to pull casing, p Squeezed 80sx plug from 8. Perf'd @ 400' and sque 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. ged @ 280'.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme 3. Displaced hole w/MLF Spotted 25sx plug from 5. Perf'd and squeezed 45 Unable to pull casing, 1 Squeezed 80sx plug from 8. Perf'd @ 400' and sque 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p a 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. ged @ 280'.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme 3. Displaced hole w/MLF Spotted 25sx plug from 5. Perf'd and squeezed 45 Unable to pull casing, p Squeezed 80sx plug from 8. Perf'd @ 400' and sque 	SEE RULE 1103. For Multiple rrs. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 40sx plug to surface	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. agged @ 280'. gged @ surface.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme Displaced hole w/MLF Spotted 25sx plug from Perf'd and squeezed 45 Unable to pull casing, p Squeezed 80sx plug from Perf'd @ 400' and sque Perf'd @ 100' and sque 	SEE RULE 1103. For Multiple rrs. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 40sx plug to surface	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. agged @ 280'. gged @ surface. wed as to plugging of the Well Bore.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme Displaced hole w/MLF Spotted 25sx plug from Perf'd and squeezed 45 Unable to pull casing, p Squeezed 80sx plug from Perf'd @ 400' and sque Perf'd @ 100' and sque Installed dry hole mark 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 40sx plug to surface ter on 2/3/2006	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag Appro Liabilit surface	Wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. agged @ 1,938'. agged @ surface. ved as to plugging of the Well Bore. ry under bond is retained until a restoration is completed.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme Displaced hole w/MLF Spotted 25sx plug from Perf'd and squeezed 45 Unable to pull casing, j Squeezed 80sx plug from Perf'd @ 400' and sque Perf'd @ 100' and sque 10.Installed dry hole mark 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 40sx plug to surface ter on 2/3/2006	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag (surface). WOC Tag surface and the surface	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. agged @ 1,938'. gged @ 280'. gged @ surface. wed as to plugging of the Well Bore. y under bond is retained until <u>e restoration is completed.</u> belief. I further certify that any pit or below-
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme Displaced hole w/MLF Spotted 25sx plug from Perf'd and squeezed 45 Unable to pull casing, j Squeezed 80sx plug from Perf'd @ 400' and sque Perf'd @ 100' and sque 10.Installed dry hole mark 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 40sx plug to surface ter on 2/3/2006	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag (surface). WOC Tag surface and the surface	Wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. agged @ 1,938'. agged @ surface. ved as to plugging of the Well Bore. ry under bond is retained until a restoration is completed.
 Describe proposed or complete of starting any proposed work). or recompletion. Notified NMOCD 24 h Squeezed 50sx of ceme 3. Displaced hole w/MLF Spotted 25sx plug from 5. Perf'd and squeezed 45 Unable to pull casing, p Squeezed 80sx plug from 8. Perf'd @ 400' and sque Perf'd @ 100' and sque Perf'd @ 100' and sque Installed dry hole mark 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 40sx plug to surface ter on 2/3/2006	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag (surface). WOC Tag st of my knowledge and], a general permit or an	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. agged @ 1,938'. agged @ surface. wed as to plugging of the Well Bore. ty under bond is retained until <u>e restoration is completed.</u> belief. I further certify that any pit or below- (attached) alternative OCD-approved plan [].
of starting any proposed work), or recompletion. 1. Notified NMOCD 24 h 2. Squeezed 50sx of ceme 3. Displaced hole w/MLF 4. Spotted 25sx plug from 5. Perf'd and squeezed 45 6. Unable to pull casing, p 7. Squeezed 80sx plug from 8. Perf'd @ 400' and sque 9. Perf'd @ 100' and sque 10.Installed dry hole mark hereby certify that the information abo rade tank has been/will be constructed or close IGNATURE	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (7, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5x plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 40sx plug to surface ter on 2/3/2006	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag (surface). WOC Tag st of my knowledge and], a general permit □ or an anager	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. 'agged @ 1,938'. 'agged @ 1,938'. 'gged @ 280'. 'gged @ surface. ved as to plugging of the Well Bore. 'y under bond is retained until 'e restoration is completed. belief. I further certify that any pit or below-(attached) alternative OCD-approved plan □.
 13. Describe proposed or complete of starting any proposed work). or recompletion. 1. Notified NMOCD 24 h 2. Squeezed 50sx of cemed 3. Displaced hole w/MLF 4. Spotted 25sx plug from 5. Perf'd and squeezed 45 6. Unable to pull casing, j 7. Squeezed 80sx plug from 8. Perf'd @ 400' and sque 9. Perf'd @ 100' and sque 10.Installed dry hole mark 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 100sx plug (fresh wa eezed 40sx plug to surface ter on 2/3/2006	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag (surface). WOC Tag st of my knowledge and], a general permit \Box or an anager	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. gged @ 280'. gged @ surface. ved as to plugging of the Well Bore. y under bond is retained until <u>e restoration is completed.</u> belief. I further certify that any pit or below-(attached) alternative OCD-approved plan □. DATE_2/3/2006 ephone No. (432) 561-8600
 13. Describe proposed or complete of starting any proposed work). or recompletion. 1. Notified NMOCD 24 h 2. Squeezed 50sx of cemed 3. Displaced hole w/MLF 4. Spotted 25sx plug from 5. Perf'd and squeezed 45 6. Unable to pull casing, j 7. Squeezed 80sx plug from 8. Perf'd @ 400' and sque 9. Perf'd @ 100' and sque 10.Installed dry hole mark 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 100sx plug (fresh wa eezed 40sx plug to surface ter on 2/3/2006	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag (surface). WOC Tag st of my knowledge and], a general permit \Box or an anager	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. gged @ 280'. gged @ surface. ved as to plugging of the Well Bore. y under bond is retained until <u>e restoration is completed.</u> belief. I further certify that any pit or below-(attached) alternative OCD-approved plan □. DATE_2/3/2006 ephone No. (432) 561-8600
 13. Describe proposed or complete of starting any proposed work). or recompletion. 1. Notified NMOCD 24 h 2. Squeezed 50sx of cemed 3. Displaced hole w/MLF 4. Spotted 25sx plug from 5. Perf'd and squeezed 45 6. Unable to pull casing, p 7. Squeezed 80sx plug from 8. Perf'd @ 400' and sque 9. Perf'd @ 100' and sque 10.Installed dry hole mark 	SEE RULE 1103. For Multiple ars. prior to MI&RU. ent under packer at 5,948' (5, 9.5 ppg brine w/12.5 gel p n 4,650'-4,475' (existing sq 5sx plug from 3,000'-2,800 perf'd @ 2,232'. om 2,232''-1,940' (T. salt,8 eezed 100sx plug (fresh wa eezed 100sx plug (fresh wa eezed 40sx plug to surface ter on 2/3/2006	ertinent details, and give e Completions: Attach (Paddock,open hole) p/bbl. jueeze perfs, San An ' (B.salt) WOC Tag 3-5/8" shoe) WOC T ater plug). WOC Tag (surface). WOC Tag (surface). WOC Tag st of my knowledge and], a general permit □ or an anager	wellbore diagram of proposed completion . WOC Tagged @ 5,975'. dres). WOC Tagged @ 4,425'. ged @ 2,803'. agged @ 1,938'. gged @ 280'. gged @ surface. ved as to plugging of the Well Bore. y under bond is retained until <u>e restoration is completed.</u> belief. I further certify that any pit or below-(attached) alternative OCD-approved plan □. DATE_2/3/2006 ephone No. (432) 561-8600

DA)